

DAIMLER

# REACH Information

Daimler Truck AG  
Mercedes-Benz Special Trucks  
eEconic

Candidate List Version: 21.01.2025

04/2025

Уважаеми клиенти,

Влезният в сила на 1 юни 2007 г. във връзка с Регламента на ЕС относно химикалите (ЕО) No 1907/2006, (REACH - регистрация, оценка, разрешаване и ограничаване на химикали), има за цел да осигури защита на човешкото здраве и околната среда от възможните рискове при употребата на химикали.

Daimler Truck AG подкрепя целите на Регламента REACH. Член 33 от Регламента изисква да Ви предоставяме информация относно веществата, пораждащи особено безпокойство (SVHC), които са вложени в нашите продукти. Това изискване има за цел да гарантира безопасната работа с посочените вещества в продължение на целия жизнен цикъл на продукта.

Въз основа на законовите изисквания и вземайки предвид данните от доставчиците на Daimler Truck AG бяха идентифицирани следните вещества, които могат да се съдържат в над 0,1 тегловни процента от отделни изделия на този автомобил. При употребата на автомобила по предназначение не съществува опасност за хората и околната среда. Допълнителна информация относно безопасната употреба на Вашия автомобил ще откриете в ръководството за експлоатация.

Моля, обърнете внимание, че допълнително веществото олово (CAS-No 7439-92-1) се съдържа в стартерната акумулаторна батерия, в сплави, наслявания, стъклени/керамични/ еластомерни компоненти, както и различни електронни компоненти (преди всичко лотове).

| Група продукти                                          | наименование на веществото                   | CAS NO.    |
|---------------------------------------------------------|----------------------------------------------|------------|
| Акумулаторна<br>Батерия За Бордова<br>Мрежа             | Lead-monoxide                                | 1317-36-8  |
|                                                         | Diboron-trioxide                             | 1303-86-2  |
|                                                         | Lead(II,IV)-oxide                            | 1314-41-6  |
|                                                         |                                              |            |
| Антенна За Контрол<br>На Налягането В<br>Гумите         | Lead titanium zirconium oxide                | 12626-81-2 |
| Антенен Усилвател                                       | Lead-monoxide                                | 1317-36-8  |
|                                                         | Diboron-trioxide                             | 1303-86-2  |
| Блок Управление<br>Датчик За Ъгъл На<br>Завъртане Волан | Lead-monoxide                                | 1317-36-8  |
|                                                         | Diboron-trioxide                             | 1303-86-2  |
|                                                         |                                              |            |
|                                                         |                                              |            |
| Бутон                                                   | Octamethylcyclotetrasiloxane                 | 556-67-2   |
|                                                         | Decamethylcyclopentasiloxane                 | 541-02-6   |
|                                                         | Lead-monoxide                                | 1317-36-8  |
|                                                         | Dodecamethylcyclohexasiloxane                | 540-97-6   |
| Бутонен<br>Превключвател                                | Lead-monoxide                                | 1317-36-8  |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3    |
| Вентилатор                                              | TBBA                                         | 79-94-7    |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3    |
| Винт С Шестостенна<br>Глава                             | Diboron-trioxide                             | 1303-86-2  |
| Волан                                                   | Lead-monoxide                                | 1317-36-8  |
| Врата                                                   | Triphenyl-phosphate                          | 115-86-6   |
| Въздушна<br>Възглавница На<br>Окачването                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol | 119-47-1   |

|                                                    |                                                             |             |
|----------------------------------------------------|-------------------------------------------------------------|-------------|
| Габаритна Светлина                                 | TBBA                                                        | 79-94-7     |
|                                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| Глуха Пробка                                       | Bumetrizole                                                 | 3896-11-5   |
| Датчик За Налягане                                 | Lead titanium zirconium oxide                               | 12626-81-2  |
|                                                    | Lead-monoxide                                               | 1317-36-8   |
|                                                    | 1,2-Dimethoxyethane                                         | 110-71-4    |
|                                                    | 1,3-Propanesultone                                          | 1120-71-4   |
| Датчик За Температура                              | TBBA                                                        | 79-94-7     |
| Датчик За Ускорение                                | Diboron-trioxide                                            | 1303-86-2   |
| Двупозиционен Превключвател                        | Lead-monoxide                                               | 1317-36-8   |
|                                                    | TBBA                                                        | 79-94-7     |
| Диод                                               | TBBA                                                        | 79-94-7     |
| Дисков Обтуратор                                   | Imidazolidine-2-thione                                      | 96-45-7     |
| Екран                                              | 2-Methylimidazole                                           | 693-98-1    |
|                                                    | Lead-monoxide                                               | 1317-36-8   |
|                                                    | Diboron-trioxide                                            | 1303-86-2   |
| Ел. Блок Edrive Common Powertrain Controller       | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                    | Lead-monoxide                                               | 1317-36-8   |
|                                                    | Diboron-trioxide                                            | 1303-86-2   |
|                                                    | TBBA                                                        | 79-94-7     |
|                                                    | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone          | 119313-12-1 |
| Ел. Блок Система За Следене На Налягането В Гумите | Lead-monoxide                                               | 1317-36-8   |
| Електр.Блок Модул За Улав. и Актив. Сигнал Кабина  | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                    | Lead-monoxide                                               | 1317-36-8   |
|                                                    | Diboron-trioxide                                            | 1303-86-2   |
| Електрически Кабелен Сноп                          | Melamine                                                    | 108-78-1    |
|                                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Електродвигател На Стъклочистачките                | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol             | 25973-55-1  |
| Електромагнитен Клапан                             | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
| Електронен Блок Air-Processing Unit                | Lead titanium zirconium oxide                               | 12626-81-2  |
|                                                    | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                    | Lead-monoxide                                               | 1317-36-8   |
|                                                    | Diboron-trioxide                                            | 1303-86-2   |
| Електронен Блок Dc/Dc-Преобразувател Нисковолтов 1 | N,N-Dimethylacetamide                                       | 127-19-5    |
|                                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |

|                                                      |                                                          |            |
|------------------------------------------------------|----------------------------------------------------------|------------|
| Dc/Dc-                                               | Lead-monoxide                                            | 1317-36-8  |
|                                                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                      | Dodecamethylcyclotetrasiloxane                           | 540-97-6   |
|                                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Video Radar Decision<br>Unit      | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>ХМС                               | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Автоматична<br>Климатична Система | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Въздушна<br>Възглавница           | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | TBBA                                                     | 79-94-7    |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Датчик За Дистанция               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | TBBA                                                     | 79-94-7    |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Датчик За Дъжд И<br>Светлина      | Lead-monoxide                                            | 1317-36-8  |
|                                                      |                                                          |            |
| Електронен Блок<br>Дисплей                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                      | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | 1-Propanol, 2,3-dibromo-                                 | 96-13-9    |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Електронна<br>Контактна Ключалка  | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Комбиинструмент                   | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | TBBA                                                     | 79-94-7    |
| <hr/>                                                |                                                          |            |
| Електронен Блок<br>Късообхватен Радар                | Lead-monoxide                                            | 1317-36-8  |

|                                                                       |                                                          |            |
|-----------------------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Електронен Блок<br/>Модул На Врата<br/>Водач</b>                   | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Електронен Блок<br/>Модул На Вратата<br/>Спътник</b>               | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Електронен Блок<br/>Мулти-<br/>функционална<br/>Камера</b>         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                                       | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <b>Електронен Блок<br/>Преобразувател</b>                             | 2-Methylimidazole                                        | 693-98-1   |
|                                                                       | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                                       | TBBA                                                     | 79-94-7    |
| <b>Електронен Блок<br/>Регулиране На<br/>Нивото</b>                   | Lead-monoxide                                            | 1317-36-8  |
| <b>Електронен Блок С-<br/>Ма За Управление На<br/>Акум.Батерия</b>    | Lead-monoxide                                            | 1317-36-8  |
| <b>Електронен Блок<br/>Тахограф</b>                                   | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                                       | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                                       | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                                                                       | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Електронен Блок<br/>Телематична<br/>Платформа</b>                  | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                                       | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                                       | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Електронен Блок<br/>Управление На<br/>Заряда</b>                   | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                                       | TBBA                                                     | 79-94-7    |
| <b>Електронен Блок<br/>Управление На<br/>Предавателната<br/>Кутия</b> | Lead-monoxide                                            | 1317-36-8  |
|                                                                       | Diboron-trioxide                                         | 1303-86-2  |

|                            |                                                                                                   |             |
|----------------------------|---------------------------------------------------------------------------------------------------|-------------|
| <b>Електронен Блок</b>     |                                                                                                   |             |
| <b>Управляем</b>           |                                                                                                   |             |
| <b>Допълнителен Мост</b>   | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1    |
|                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3     |
| <b>Електронен Блок</b>     |                                                                                                   |             |
| <b>Централен Гейтуей</b>   | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | Diboron-trioxide                                                                                  | 1303-86-2   |
| <b>Електронен Главен</b>   |                                                                                                   |             |
| <b>Спирачен Кран</b>       | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | Diboron-trioxide                                                                                  | 1303-86-2   |
| <b>Етернет-</b>            |                                                                                                   |             |
| <b>Преобразувател</b>      | Lead-titanium-trioxide                                                                            | 12060-00-3  |
|                            | Lead-monoxide                                                                                     | 1317-36-8   |
| <b>Задвижващ Мост</b>      | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9  |
|                            | N,N-Dimethylacetamide                                                                             | 127-19-5    |
|                            | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                            | 2-Methylimidazole                                                                                 | 693-98-1    |
|                            | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                            | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | Diboron-trioxide                                                                                  | 1303-86-2   |
|                            | 4-Nonylphenol, branched                                                                           | 84852-15-3  |
|                            | Nonylphenol                                                                                       | 25154-52-3  |
|                            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1    |
|                            | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6    |
|                            | TBBA                                                                                              | 79-94-7     |
|                            | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-                      |             |
|                            | [3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters                                  | 255881-94-8 |
|                            | Phenol, methylstyrenated                                                                          | 68512-30-1  |
|                            | Triphenyl-phosphate                                                                               | 115-86-6    |
| <b>Задна Габаритна</b>     |                                                                                                   |             |
| <b>Светлина</b>            | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | TBBA                                                                                              | 79-94-7     |
|                            | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                       | 3147-75-9   |
| <b>Изпарител</b>           | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | Diboron-trioxide                                                                                  | 1303-86-2   |
| <b>Калници</b>             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                       | 3147-75-9   |
| <b>Камера</b>              | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                            | 2-Methylimidazole                                                                                 | 693-98-1    |
|                            | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                            | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5  |
|                            | Lead-monoxide                                                                                     | 1317-36-8   |
|                            | Diboron-trioxide                                                                                  | 1303-86-2   |
|                            | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6    |
|                            | Refractory ceramic fibres                                                                         | 142844-00-6 |
|                            | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                   | 75980-60-8  |
| <b>Капак</b>               | C,C'-azodi(formamide)                                                                             | 123-77-3    |
| <b>Капак На Щекерна</b>    |                                                                                                   |             |
| <b>Букса</b>               | Bumetrizole                                                                                       | 3896-11-5   |
| <b>Капачка За Радиатор</b> | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3     |

|                    |                                                                            |            |
|--------------------|----------------------------------------------------------------------------|------------|
| Климатична Система | Lead-monoxide                                                              | 1317-36-8  |
| Ключалка На        |                                                                            |            |
| Вратата            | Triphenyl-phosphate                                                        | 115-86-6   |
| Комплект Ключове   | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| Компресор На       |                                                                            |            |
| Климатика          | 4,4'-Isopropylidenediphenol                                                | 80-05-7    |
|                    | 2-Methylimidazole                                                          | 693-98-1   |
|                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5 |
|                    | Lead-monoxide                                                              | 1317-36-8  |
|                    | Diboron-trioxide                                                           | 1303-86-2  |
|                    | Tris(nonylphenyl)phosphite                                                 | 26523-78-4 |
| Контролна Лампа    | TBBA                                                                       | 79-94-7    |
|                    | Melamine                                                                   | 108-78-1   |
| Крушка             | Diboron-trioxide                                                           | 1303-86-2  |
| Кръгъл Шестостенен |                                                                            |            |
| Винт               | Diboron-trioxide                                                           | 1303-86-2  |
| Лампа За Вътрешно  |                                                                            |            |
| Осветление         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Лост За Управление | Lead-monoxide                                                              | 1317-36-8  |
|                    | Diboron-trioxide                                                           | 1303-86-2  |
| Модул За           |                                                                            |            |
| Управление         | Lead-monoxide                                                              | 1317-36-8  |
|                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Модул На           |                                                                            |            |
| Високоволтовата    |                                                                            |            |
| Акумулаторна       |                                                                            |            |
| Батерия            | Lead-monoxide                                                              | 1317-36-8  |
|                    |                                                                            |            |
|                    | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| Мост               | Boric acid                                                                 | 10043-35-3 |
|                    | Imidazolidine-2-thione                                                     | 96-45-7    |
|                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                    | 2-Methylimidazole                                                          | 693-98-1   |
|                    | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                    | Lead-monoxide                                                              | 1317-36-8  |
|                    | Diboron-trioxide                                                           | 1303-86-2  |
|                    | Tris(nonylphenyl)phosphite                                                 | 26523-78-4 |
|                    | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione           | 2451-62-9  |
|                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
|                    | Chromium-trioxide                                                          | 1333-82-0  |
|                    | Hexahydromethylphthalic-anhydride                                          | 25550-51-0 |
|                    | Paraffin oils, chloro                                                      | 85422-92-0 |
|                    | TBBA                                                                       | 79-94-7    |
|                    | Phenol, methylstyrenated                                                   | 68512-30-1 |
|                    | Triphenyl-phosphate                                                        | 115-86-6   |
|                    | O,O,O-Triphenyl phosphorothioate                                           | 597-82-0   |
| Мостов Модулятор   | Lead-monoxide                                                              | 1317-36-8  |
| Мрежа За Багаж     | N,N-Dimethylacetamide                                                      | 127-19-5   |
| Мултимедиен        |                                                                            |            |
| Присъединителен    |                                                                            |            |
| Елемент            | Lead-monoxide                                                              | 1317-36-8  |

|                     |                                              |            |
|---------------------|----------------------------------------------|------------|
| Присъединителен     | Diboron-trioxide                             | 1303-86-2  |
| Огледало            | 2-Methylimidazole                            | 693-98-1   |
|                     | Lead-monoxide                                | 1317-36-8  |
|                     | Diboron-trioxide                             | 1303-86-2  |
| Огледало Външно     | TBBA                                         | 79-94-7    |
|                     | Triphenyl-phosphate                          | 115-86-6   |
| О-Пръстен           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol | 119-47-1   |
| Отопление           | Lead-titanium-trioxide                       | 12060-00-3 |
|                     | Lead-monoxide                                | 1317-36-8  |
|                     | Diboron-trioxide                             | 1303-86-2  |
| Панел За Управление | Lead-monoxide                                | 1317-36-8  |
|                     | TBBA                                         | 79-94-7    |
| Педал На Газта      | Lead-monoxide                                | 1317-36-8  |
|                     | TBBA                                         | 79-94-7    |
| Плафон На Тавана    | Triphenyl-phosphate                          | 115-86-6   |
| Пневматична         |                                              |            |
| Седалка             | Triphenyl-phosphate                          | 115-86-6   |
| Помпа За            |                                              |            |
| Охладителна         |                                              |            |
| Течност             | Lead-monoxide                                | 1317-36-8  |
|                     | Diboron-trioxide                             | 1303-86-2  |
|                     | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3    |
| Превключвател На    |                                              |            |
| Кормилната Колона   | Lead-monoxide                                | 1317-36-8  |
|                     | TBBA                                         | 79-94-7    |
| Превключвател На    |                                              |            |
| Светлините          | Lead-monoxide                                | 1317-36-8  |
| Профилно            |                                              |            |
| Уплътнение          | C,C'-azodi(formamide)                        | 123-77-3   |
| Проходна Втулка     | Imidazolidine-2-thione                       | 96-45-7    |
| Работен Цилиндър    | Imidazolidine-2-thione                       | 96-45-7    |
|                     | Lead-monoxide                                | 1317-36-8  |
| Разпределител На    |                                              |            |
| Напрежение          | Octamethylcyclotetrasiloxane                 | 556-67-2   |
|                     | Decamethylcyclopentasiloxane                 | 541-02-6   |
|                     | Dodecamethylcyclohexasiloxane                | 540-97-6   |
| Седалка До Водача   | C,C'-azodi(formamide)                        | 123-77-3   |
|                     | Melamine                                     | 108-78-1   |
|                     | Triphenyl-phosphate                          | 115-86-6   |
| Седалка На Водача   | 4,4'-Isopropylidenediphenol                  | 80-05-7    |
|                     | Triphenyl-phosphate                          | 115-86-6   |
| Сигнална Жилетка    | Diboron-trioxide                             | 1303-86-2  |
| Спирачен Маркуч     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol | 119-47-1   |
|                     | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3    |
| Странична Врата     | Triphenyl-phosphate                          | 115-86-6   |
| Странично Стъкло    | Diboron-trioxide                             | 1303-86-2  |
| Трансформатор На    |                                              |            |
| Напрежение          | Melamine                                     | 108-78-1   |
| Уплътнение          | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3    |
| Фар                 | Lead-monoxide                                | 1317-36-8  |
| Филцова Лента       | Disodium-octaborate                          | 12008-41-2 |



Poštovani kupče,

Cilj zakona koji je stupio na snagu 1. lipnja 2007. na temelju Uredbe (EZ) br. 1907/2006 (REACH - registracija, evaluacija, autorizacija i ograničavanje kemikalija) je zaštita ljudskog zdravlja i okoliša od mogućih opasnosti od kemikalija.

Tvrtka Daimler Truck AG podržava ciljeve Uredbe REACH. Članak 33. Zakona predviđa obvezu informiranja naših kupaca o posebno zabrinjavajućim tvarima (SVHC) u našim proizvodima. Cilj ove specifikacije je osigurati sigurno rukovanje definiranim tvarima tijekom cijelog životnog ciklusa proizvoda.

Na temelju zakonskih zahtjeva i uzimajući u obzir podatke dobavljača tvrtke Daimler Truck AG utvrđene su sljedeće tvari koje se u pojedinačnim proizvodima u ovom vozilu mogu nalaziti u koncentraciji većoj od 0,1 % masenog udjela. Pri namjenskoj uporabi vozila nema opasnosti za ljude i okoliš. Daljnje informacije o sigurnoj uporabi vozila možete pronaći u uputama za rad.

Molimo, vodite računa o tome da se olovo (CAS br. 7439-92-1) nalazi i u startnom akumulatoru, u legurama, premazima, staklenim/keramičkim/elastomernim komponentama te različitim elektroničkim komponentama (prije svega u lemovima).

| Product group           | Substance name                                                   | CAS no.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Brake Value Sensor      | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Automatic Climate Control</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Central Gateway</b>            | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Electronic Ignition Lock</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Instrument Cluster</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit Rain-Light Sensor</b>          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Video Radar Decision Unit</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Air-Processing Unit</b>       | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclotetrasiloxane                           | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                              |             |
|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                         | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | TBBA                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                                         | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                         | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                         | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                         | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                         | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                         | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                         | TBBA                                                                                                                                         | 79-94-7     |
|                                                         | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                         | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | Melamine                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                  |                                                 |            |
|------------------|-------------------------------------------------|------------|
| Wiper Motor      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol | 25973-55-1 |
| Working Cylinder | Imidazolidine-2-thione                          | 96-45-7    |
|                  | Lead-monoxide                                   | 1317-36-8  |

Vážení zákazníci,

zákon, který vstoupil v platnost dne 1. června 2007 o nařízení EU o chemických látkách (ES) č. 1907/2006, (REACH - o registraci, hodnocení, povolování a omezování chemických látek), si klade za cíl zajistit ochranu lidského zdraví a životního prostředí před možnými riziky způsobenými chemickými látkami.

Společnost Daimler Truck AG podporuje cíle nařízení REACH. Článek 33 právních předpisů stanoví, že zákazník musí být informován o látkách vzbuzujících velmi velké obavy (SVHC) v našich produktech. Cílem tohoto ustanovení je zajistit bezpečné zacházení s definovanými látkami v průběhu celého životního cyklu výrobku.

Na základě právních předpisů a s přihlédnutím k informacím poskytnutým dodavateli společnosti Daimler Truck AG byly identifikovány následující látky, které se mohou v jednotlivých předmětech tohoto vozidla nacházet v koncentraci vyšší než 0,1 % hmotnostních. Při použití vozidla v souladu s určením nehrozí žádné nebezpečí lidem ani životnímu prostředí. Další informace k bezpečnému používání vašeho vozidla naleznete v návodu k použití.

Nezapomeňte prosím, že olovo (č. CAS 7439-92-1) je také obsaženo ve startovacím akumulátoru, slitinách, povrstveních, skleněných/keramických/elastomerových a také různých elektronických součástech (zejména pájkách).

| Produktová skupina            | Název látky                                                                                       | č. CAS.    |
|-------------------------------|---------------------------------------------------------------------------------------------------|------------|
| <b>Akumulátor Palubní</b>     |                                                                                                   |            |
| <b>Sítě</b>                   | Lead-monoxide                                                                                     | 1317-36-8  |
|                               | Diboron-trioxide                                                                                  | 1303-86-2  |
|                               | Lead(II,IV)-oxide                                                                                 | 1314-41-6  |
| <b>Anténa Tlaku Vzduchu V</b> |                                                                                                   |            |
| <b>Pneumatice</b>             | Lead titanium zirconium oxide                                                                     | 12626-81-2 |
| <b>Anténní Zesilovač</b>      | Lead-monoxide                                                                                     | 1317-36-8  |
|                               | Diboron-trioxide                                                                                  | 1303-86-2  |
| <b>Blatník</b>                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                       | 3147-75-9  |
| <b>Boční Dveře</b>            | Triphenyl-phosphate                                                                               | 115-86-6   |
| <b>Boční Okno</b>             | Diboron-trioxide                                                                                  | 1303-86-2  |
| <b>Brzdová Hadice</b>         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1   |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3    |
| <b>Čerpadlo Chladicí</b>      |                                                                                                   |            |
| <b>Kapaliny</b>               | Lead-monoxide                                                                                     | 1317-36-8  |
|                               | Diboron-trioxide                                                                                  | 1303-86-2  |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3    |
| <b>Dioda</b>                  | TBBA                                                                                              | 79-94-7    |
| <b>Dveře</b>                  | Triphenyl-phosphate                                                                               | 115-86-6   |
| <b>Elektrický Kabelový</b>    |                                                                                                   |            |
| <b>Svazek</b>                 | Melamine                                                                                          | 108-78-1   |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3    |
| <b>Ethernetový Měnič</b>      | Lead-titanium-trioxide                                                                            | 12060-00-3 |
|                               | Lead-monoxide                                                                                     | 1317-36-8  |
| <b>Hnací Náprava</b>          | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9 |
|                               | N,N-Dimethylacetamide                                                                             | 127-19-5   |
|                               | Octamethylcyclotetrasiloxane                                                                      | 556-67-2   |
|                               | 2-Methylimidazole                                                                                 | 693-98-1   |
|                               | Decamethylcyclopentasiloxane                                                                      | 541-02-6   |
|                               | Lead-monoxide                                                                                     | 1317-36-8  |
|                               | Diboron-trioxide                                                                                  | 1303-86-2  |
|                               | 4-Nonylphenol, branched                                                                           | 84852-15-3 |

|                                    |                                                                                                                                              |             |
|------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Hnací Náprava                      | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                    | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
|                                    | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
| Jednotka Obslužná                  | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Kamery                             | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                    | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                    | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                    | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                    | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                    | Refractory ceramic fibres                                                                                                                    | 142844-00-6 |
|                                    | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                                                              | 75980-60-8  |
| Klimatizace                        | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Kolébkový Spínač                   | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
| Kombinovaný Přepínač               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
| Koncové Světlo                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
|                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Kondenzátor Chladiva               | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                    | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                    | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                    | Tris(nonylphenyl)phosphite                                                                                                                   | 26523-78-4  |
| Kontrolka                          | TBBA                                                                                                                                         | 79-94-7     |
|                                    | Melamine                                                                                                                                     | 108-78-1    |
| Kryt Zásuvky                       | Bumetrizole                                                                                                                                  | 3896-11-5   |
| Magnetický Ventil                  | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
| Měch Vzduchového Odpružení         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| Měnič Napětí                       | Melamine                                                                                                                                     | 108-78-1    |
| Modul Vysokonapěťového Akumulátoru | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Modulátor Nápravy                  | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                                                                   | 29420-49-3  |
|                                    | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Motor Stěračů                      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                                                                                              | 25973-55-1  |
| Náprava                            | Boric acid                                                                                                                                   | 10043-35-3  |
|                                    | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                                    | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |

|                                                                  |                                                                  |             |
|------------------------------------------------------------------|------------------------------------------------------------------|-------------|
| <b>Náprava</b>                                                   | 2-Methylimidazole                                                | 693-98-1    |
|                                                                  | Decamethylcyclopentasiloxane                                     | 541-02-6    |
|                                                                  | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | Diboron-trioxide                                                 | 1303-86-2   |
|                                                                  | Tris(nonylphenyl)phosphite                                       | 26523-78-4  |
|                                                                  | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9   |
|                                                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1    |
|                                                                  | Chromium-trioxide                                                | 1333-82-0   |
|                                                                  | Hexahydromethylphthalic-anhydride                                | 25550-51-0  |
|                                                                  | Paraffin oils, chloro                                            | 85422-92-0  |
|                                                                  | TBBA                                                             | 79-94-7     |
|                                                                  | Phenol, methylstyrenated                                         | 68512-30-1  |
|                                                                  | Triphenyl-phosphate                                              | 115-86-6    |
|                                                                  | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0    |
| <b>Obrazovka</b>                                                 | 2-Methylimidazole                                                | 693-98-1    |
|                                                                  | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | Diboron-trioxide                                                 | 1303-86-2   |
| <b>Obrysové Světlo</b>                                           | TBBA                                                             | 79-94-7     |
|                                                                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9   |
| <b>Odpružené Sedadlo</b>                                         | Triphenyl-phosphate                                              | 115-86-6    |
| <b>O-Kroužek</b>                                                 | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1    |
| <b>Osvětlení Vnitřní</b>                                         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9   |
| <b>Ovládací Páka</b>                                             | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | Diboron-trioxide                                                 | 1303-86-2   |
| <b>Ovládací Panel</b>                                            | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | TBBA                                                             | 79-94-7     |
| <b>Pedál Akceleraace</b>                                         | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | TBBA                                                             | 79-94-7     |
| <b>Plstěný Pás</b>                                               | Disodium-octaborate                                              | 12008-41-2  |
| <b>Pracovní Válec</b>                                            | Imidazolidine-2-thione                                           | 96-45-7     |
|                                                                  | Lead-monoxide                                                    | 1317-36-8   |
| <b>Přepínač Světel</b>                                           | Lead-monoxide                                                    | 1317-36-8   |
| <b>Připojovací Jednotka<br/>Multimediálního<br/>Systému</b>      | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | Diboron-trioxide                                                 | 1303-86-2   |
|                                                                  | Lead-monoxide                                                    | 1317-36-8   |
| <b>Přístroj Obslužný</b>                                         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9   |
|                                                                  | C,C'-azodi(formamide)                                            | 123-77-3    |
| <b>Profilové Těsnění</b>                                         | Imidazolidine-2-thione                                           | 96-45-7     |
| <b>Průchodka</b>                                                 | Diboron-trioxide                                                 | 1303-86-2   |
| <b>Reflexní Vesta</b>                                            |                                                                  |             |
| <b>Říd. Jednotka Edrive<br/>Common Powertrain<br/>Controller</b> | Lead-titanium-trioxide                                           | 12060-00-3  |
|                                                                  | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | Diboron-trioxide                                                 | 1303-86-2   |
|                                                                  | TBBA                                                             | 79-94-7     |
|                                                                  | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone               | 119313-12-1 |
| <b>Řídicí Jednotka Airbagu</b>                                   | Lead-monoxide                                                    | 1317-36-8   |
|                                                                  | Diboron-trioxide                                                 | 1303-86-2   |
|                                                                  | TBBA                                                             | 79-94-7     |

|                                                      |                                                          |            |
|------------------------------------------------------|----------------------------------------------------------|------------|
| Řídicí Jednotka<br>Automatické<br>Klimatizace        | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
| Řídicí Jednotka<br>Centrální Gateway                 | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Řídicí Jednotka<br>Dešťového A<br>Světelného Senzoru | Lead-monoxide                                            | 1317-36-8  |
|                                                      |                                                          |            |
| Řídicí Jednotka Displeje                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                      | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | 1-Propanol, 2,3-dibromo-                                 | 96-13-9    |
| Řídicí Jednotka<br>Elektronické Spínací<br>Skříňky   | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
| Řídicí Jednotka<br>Jednotky Úpravy<br>Vzduchu        | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                      | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Řídicí Jednotka Kontroly<br>Tlaku Vzduchu V Pneu     | Lead-monoxide                                            | 1317-36-8  |
|                                                      |                                                          |            |
| Řídicí Jednotka Měníče<br>Dc/Dc, Nízké Napětí 1      | N,N-Dimethylacetamide                                    | 127-19-5   |
|                                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                      | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
|                                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
| Řídicí Jednotka Měníče<br>Frekvence                  | 2-Methylimidazole                                        | 693-98-1   |
|                                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | TBBA                                                     | 79-94-7    |
| Řídicí Jednotka Modulu<br>Dveří Řidiče               | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Řídicí Jednotka Modulu<br>Dveří Spolujezdce          | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Řídicí Jednotka<br>Multifunkční Kamery               | Lead-titanium-trioxide                                   | 12060-00-3 |

|                                |                                                          |            |
|--------------------------------|----------------------------------------------------------|------------|
| <b>Multifunkční Kamery</b>     | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
|                                | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka</b>         |                                                          |            |
| <b>Platformy Telematiky</b>    | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka Radaru</b>  |                                                          |            |
| <b>Krátkého Dosahu</b>         | Lead-monoxide                                            | 1317-36-8  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka</b>         |                                                          |            |
| <b>Regulace Světlé Výšky</b>   | Lead-monoxide                                            | 1317-36-8  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka Řízené</b>  |                                                          |            |
| <b>Přídavné Nápravy</b>        | Lead-monoxide                                            | 1317-36-8  |
|                                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka Řízení</b>  |                                                          |            |
| <b>Nabíjení</b>                | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
|                                | TBBA                                                     | 79-94-7    |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka Řízení</b>  |                                                          |            |
| <b>Převodovky</b>              | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka</b>         |                                                          |            |
| <b>Rozhodovací Jednotky</b>    |                                                          |            |
|                                | <b>Videoradaru</b>                                       |            |
|                                | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka</b>         |                                                          |            |
| <b>Sdruženého Přístroje</b>    | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
|                                | TBBA                                                     | 79-94-7    |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka Snímače</b> |                                                          |            |
| <b>Odstupu</b>                 | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
|                                | TBBA                                                     | 79-94-7    |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka Snímače</b> |                                                          |            |
| <b>Úhlu Rejdu</b>              | Lead-monoxide                                            | 1317-36-8  |
|                                | Diboron-trioxide                                         | 1303-86-2  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka</b>         |                                                          |            |
| <b>Systému Řízení</b>          |                                                          |            |
|                                | <b>Akumulátoru</b>                                       |            |
|                                | Lead-monoxide                                            | 1317-36-8  |
| <hr/>                          |                                                          |            |
| <b>Řídicí Jednotka</b>         |                                                          |            |
| <b>Tachografu</b>              | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                | Lead-titanium-trioxide                                   | 12060-00-3 |

|                                                |                                                    |            |
|------------------------------------------------|----------------------------------------------------|------------|
| Tachografu                                     | Lead-monoxide                                      | 1317-36-8  |
|                                                | Diboron-trioxide                                   | 1303-86-2  |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide    | 75980-60-8 |
|                                                | Triphenyl-phosphate                                | 115-86-6   |
| Řídicí Jedinotka XMC                           | Lead-monoxide                                      | 1317-36-8  |
|                                                | Diboron-trioxide                                   | 1303-86-2  |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride | 19438-60-9 |
|                                                |                                                    |            |
| Řj Sp. Mod. Pro Příjem<br>Sign. a Ovl., Kabina | Lead-titanium-trioxide                             | 12060-00-3 |
|                                                | Lead-monoxide                                      | 1317-36-8  |
|                                                | Diboron-trioxide                                   | 1303-86-2  |
| Rozdělovač Energie                             | Octamethylcyclotetrasiloxane                       | 556-67-2   |
|                                                | Decamethylcyclopentasiloxane                       | 541-02-6   |
|                                                | Dodecamethylcyclohexasiloxane                      | 540-97-6   |
| Sada Klíčů                                     | 1,2-Dimethoxyethane                                | 110-71-4   |
| Sedadlo Řidiče                                 | 4,4'-Isopropylidenediphenol                        | 80-05-7    |
|                                                | Triphenyl-phosphate                                | 115-86-6   |
| Šestihranný Šroub                              | Diboron-trioxide                                   | 1303-86-2  |
| Sít Na Zavazadla                               | N,N-Dimethylacetamide                              | 127-19-5   |
| Snímač Brzdých<br>Hodnot                       | Lead-monoxide                                      | 1317-36-8  |
|                                                | Diboron-trioxide                                   | 1303-86-2  |
| Snímač Teploty                                 | TBBA                                               | 79-94-7    |
| Snímač Tlaku                                   | Lead titanium zirconium oxide                      | 12626-81-2 |
|                                                | Lead-monoxide                                      | 1317-36-8  |
|                                                | 1,2-Dimethoxyethane                                | 110-71-4   |
|                                                | 1,3-Propanesultone                                 | 1120-71-4  |
| Snímač Zrychlení                               | Diboron-trioxide                                   | 1303-86-2  |
| Šroub Torx                                     | Diboron-trioxide                                   | 1303-86-2  |
| Šroubovací Hrdlo                               | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3    |
| Stropní Světlo                                 | Triphenyl-phosphate                                | 115-86-6   |
| Světlomet                                      | Lead-monoxide                                      | 1317-36-8  |
| Těsnění                                        | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3    |
| Tlačítko                                       | Octamethylcyclotetrasiloxane                       | 556-67-2   |
|                                                | Decamethylcyclopentasiloxane                       | 541-02-6   |
|                                                | Lead-monoxide                                      | 1317-36-8  |
|                                                | Dodecamethylcyclohexasiloxane                      | 540-97-6   |
| Tlačítkový Spínač                              | Lead-monoxide                                      | 1317-36-8  |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3    |
| Topení                                         | Lead-titanium-trioxide                             | 12060-00-3 |
|                                                | Lead-monoxide                                      | 1317-36-8  |
|                                                | Diboron-trioxide                                   | 1303-86-2  |
| Uzávěr Chladiče                                | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3    |
| Uzavírací Kotouč                               | Imidazolidine-2-thione                             | 96-45-7    |
| Uzavírací Zátka                                | Bumetrizole                                        | 3896-11-5  |
| Vedlejší Sedadlo U<br>Řidiče                   | C,C'-azodi(formamide)                              | 123-77-3   |
|                                                | Melamine                                           | 108-78-1   |
|                                                | Triphenyl-phosphate                                | 115-86-6   |
| Ventilátor                                     | TBBA                                               | 79-94-7    |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3    |

|                       |                       |           |
|-----------------------|-----------------------|-----------|
| <b>Víko</b>           | C,C'-azodi(formamide) | 123-77-3  |
| <b>Volant</b>         | Lead-monoxide         | 1317-36-8 |
| <b>Výparník</b>       | Lead-monoxide         | 1317-36-8 |
|                       | Diboron-trioxide      | 1303-86-2 |
| <b>Zámek Dveří</b>    | Triphenyl-phosphate   | 115-86-6  |
| <b>Žárovka</b>        | Diboron-trioxide      | 1303-86-2 |
| <b>Zrcátko</b>        | 2-Methylimidazole     | 693-98-1  |
|                       | Lead-monoxide         | 1317-36-8 |
|                       | Diboron-trioxide      | 1303-86-2 |
| <b>Zrcátko Vnější</b> | TBBA                  | 79-94-7   |
|                       | Triphenyl-phosphate   | 115-86-6  |

Kære kunde,

Den lov, der trådte i kraft pr. 1. juni 2007 vedrørende EU-kemikaliereregulativet (EF) nr. 1907/2006, (REACH - Registrering, vurdering, godkendelse og begrænsning af kemikalier, har som formål at beskytte menneskers helbred og miljøet mod mulige risici forårsaget af kemikalier.

Daimler Truck AG understøtter REACHs formål. Artikel 33 i lovgivningen fastsætter at oplyse dig som kunde om særligt bekymrende stoffer (SVHC) i vores produkter. Formålet med dette krav er at sikre en sikker omgang med de definerede stoffer i hele produktets levetid.

På grundlag af lovkrav og under hensyntagen til angivelserne fra leverandører til Daimler Truck AG er følgende stoffer identificeret, som kan befinde sig i mere end 0,1 vægtprocent i enkelte af denne bils produkter. Ved tilsigtet brug af bilen er der ingen risiko for mennesker og miljø. Du finder flere oplysninger om sikker brug af din bil i instruktionsbogen.

Vær opmærksom på, at stoffet bly (CAS-nr. 7439-92-1) desuden er indeholdt i startbatteriet, i legeringer, belægninger, glas-/keramik-/ elastomer-komponenter samt diverse elektronikkomponenter (især lodninger).

| Produktgruppe       | Stof navn                                                        | CAS-nr.    |
|---------------------|------------------------------------------------------------------|------------|
| Accelerationssensor | Diboron-trioxide                                                 | 1303-86-2  |
| Advarselsvest       | Diboron-trioxide                                                 | 1303-86-2  |
| Aksel               | Boric acid                                                       | 10043-35-3 |
|                     | Imidazolidine-2-thione                                           | 96-45-7    |
|                     | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                     | 2-Methylimidazole                                                | 693-98-1   |
|                     | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                     | Lead-monoxide                                                    | 1317-36-8  |
|                     | Diboron-trioxide                                                 | 1303-86-2  |
|                     | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                     | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                     | Chromium-trioxide                                                | 1333-82-0  |
|                     | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                     | Paraffin oils, chloro                                            | 85422-92-0 |
|                     | TBBA                                                             | 79-94-7    |
|                     | Phenol, methylstyrenated                                         | 68512-30-1 |
|                     | Triphenyl-phosphate                                              | 115-86-6   |
|                     | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Akselmodulator      | Lead-monoxide                                                    | 1317-36-8  |
| Antenneforstærker   | Lead-monoxide                                                    | 1317-36-8  |
|                     | Diboron-trioxide                                                 | 1303-86-2  |
| Arbejdscylinger     | Imidazolidine-2-thione                                           | 96-45-7    |
|                     | Lead-monoxide                                                    | 1317-36-8  |
| Bagagenet           | N,N-Dimethylacetamide                                            | 127-19-5   |
| Baglygte            | Lead-monoxide                                                    | 1317-36-8  |
|                     | TBBA                                                             | 79-94-7    |
|                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9  |
| Betjeningsarm       | Lead-monoxide                                                    | 1317-36-8  |
|                     | Diboron-trioxide                                                 | 1303-86-2  |
| Betjeningsenhed     | Lead-monoxide                                                    | 1317-36-8  |
|                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9  |
| Betjeningspanel     | Lead-monoxide                                                    | 1317-36-8  |
|                     | TBBA                                                             | 79-94-7    |

|                      |                                                                                                                                              |             |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Bremseslange         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                      | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Bremseværdiføler     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                      | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Dæktryksantenne      | Lead titanium zirconium oxide                                                                                                                | 12626-81-2  |
| Diode                | TBBA                                                                                                                                         | 79-94-7     |
| Dør                  | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Dørlås               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Drivaksel            | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                      | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                      | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                      | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                      | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                      | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                      | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                      | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                      | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                      | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                      | TBBA                                                                                                                                         | 79-94-7     |
|                      | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                      | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                      | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Elledningssæt        | Melamine                                                                                                                                     | 108-78-1    |
|                      | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Energifordeler       | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                      | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                      | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
| Ethernet-Omformer    | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                      | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Filtstykke           | Disodium-octaborate                                                                                                                          | 12008-41-2  |
| Fjederbælg           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| Fjerdersæde          | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Fordamper            | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                      | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Førersæde            | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                      | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Forlygte             | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Gennemføringstykke   | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| Højvoltsbatterimodul | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Kabinelampe          | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                                                                   | 29420-49-3  |
|                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Kamera               | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                      | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                      | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                      | Lead-monoxide                                                                                                                                | 1317-36-8   |

|                              |                                                             |             |
|------------------------------|-------------------------------------------------------------|-------------|
| Kamera                       | Diboron-trioxide                                            | 1303-86-2   |
|                              | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
|                              | Refractory ceramic fibres                                   | 142844-00-6 |
|                              | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
| Klap                         | C,C'-azodi(formamide)                                       | 123-77-3    |
| Klimaanlæg                   | Lead-monoxide                                               | 1317-36-8   |
| Kølekompressor               | 4,4'-Isopropylidenediphenol                                 | 80-05-7     |
|                              | 2-Methylimidazole                                           | 693-98-1    |
|                              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                              | Lead-monoxide                                               | 1317-36-8   |
|                              | Diboron-trioxide                                            | 1303-86-2   |
| Kølepumpe                    | Tris(nonylphenyl)phosphite                                  | 26523-78-4  |
|                              | Lead-monoxide                                               | 1317-36-8   |
|                              | Diboron-trioxide                                            | 1303-86-2   |
|                              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Kølerdæksel                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Kontrollampe                 | TBBA                                                        | 79-94-7     |
|                              | Melamine                                                    | 108-78-1    |
| Køretøjets Batteri           | Lead-monoxide                                               | 1317-36-8   |
|                              | Diboron-trioxide                                            | 1303-86-2   |
|                              | Lead(II,IV)-oxide                                           | 1314-41-6   |
| Loftslampe                   | Triphenyl-phosphate                                         | 115-86-6    |
| Lukkeprop                    | Bumetrizole                                                 | 3896-11-5   |
| Lukkeskive                   | Imidazolidine-2-thione                                      | 96-45-7     |
| Lyskontakt                   | Lead-monoxide                                               | 1317-36-8   |
| Magnetventil                 | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
| Markeringslygte              | TBBA                                                        | 79-94-7     |
|                              | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| Multimedie-tilslutningsenhed | Lead-monoxide                                               | 1317-36-8   |
|                              | Diboron-trioxide                                            | 1303-86-2   |
| Nøglesæt                     | 1,2-Dimethoxyethane                                         | 110-71-4    |
| O-Ring                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
| Pære                         | Diboron-trioxide                                            | 1303-86-2   |
| Profilpakning                | C,C'-azodi(formamide)                                       | 123-77-3    |
| Rat                          | Lead-monoxide                                               | 1317-36-8   |
| Ratstammekontakt             | Lead-monoxide                                               | 1317-36-8   |
|                              | TBBA                                                        | 79-94-7     |
| Sæde Ved Siden Af Førersæde  | C,C'-azodi(formamide)                                       | 123-77-3    |
|                              | Melamine                                                    | 108-78-1    |
|                              | Triphenyl-phosphate                                         | 115-86-6    |
| Sekskantbolt                 | Diboron-trioxide                                            | 1303-86-2   |
| Sidedør                      | Triphenyl-phosphate                                         | 115-86-6    |
| Siderude                     | Diboron-trioxide                                            | 1303-86-2   |
| Skærm                        | 2-Methylimidazole                                           | 693-98-1    |
|                              | Lead-monoxide                                               | 1317-36-8   |
|                              | Diboron-trioxide                                            | 1303-86-2   |
|                              | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| Skrue Med Sekstakket Hoved   | Diboron-trioxide                                            | 1303-86-2   |
| Skruestuds                   | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |

|                                                       |                                                          |            |
|-------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Spændings-transformer</b>                          | Melamine                                                 | 108-78-1   |
| <b>Speederpedal</b>                                   | Lead-monoxide                                            | 1317-36-8  |
|                                                       | TBBA                                                     | 79-94-7    |
| <b>Spejl</b>                                          | 2-Methylimidazole                                        | 693-98-1   |
|                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Spejl Udv.</b>                                     | TBBA                                                     | 79-94-7    |
|                                                       | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Stikdåsedæksel</b>                                 | Bumetrizole                                              | 3896-11-5  |
| <b>Styreenhed</b>                                     |                                                          |            |
| <b>Afstandssensor</b>                                 | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                       | TBBA                                                     | 79-94-7    |
| <b>Styreenhed Air Processing Unit</b>                 | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                       | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhed Airbag</b>                              | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                       | TBBA                                                     | 79-94-7    |
| <b>Styreenhed Batteri-styringssystem</b>              | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhed Central Gateway</b>                     | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhed Dæktrykskontrol</b>                     | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhed Dc/Dc-Omformer Lavvolt 1</b>            | N,N-Dimethylacetamide                                    | 127-19-5   |
|                                                       | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                       | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
|                                                       | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
| <b>Styreenhed Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                       | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
|                                                       | 1-Propanol, 2,3-dibromo-                                 | 96-13-9    |
| <b>Styreenhed Dørmodul Fører</b>                      | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhed Dørmodul Forsædepassager</b>            | Lead-monoxide                                            | 1317-36-8  |
|                                                       | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhed Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3 |

|                                                  |                                                                 |             |
|--------------------------------------------------|-----------------------------------------------------------------|-------------|
| <b>Common Powertrain</b>                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                  | <b>TBBA</b>                                                     | 79-94-7     |
|                                                  | <b>2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone</b>       | 119313-12-1 |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Elektronisk Tændingslås</b>        | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Fartskriver</b>                    | <b>Lead titanium zirconium oxide</b>                            | 12626-81-2  |
|                                                  | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                  | <b>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide</b>          | 75980-60-8  |
|                                                  | <b>Triphenyl-phosphate</b>                                      | 115-86-6    |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Gearkassestyring</b>               | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Klimaautomatik</b>                 | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Kombiinstrument</b>                | <b>4,4'-Isopropylidenediphenol</b>                              | 80-05-7     |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                  | <b>TBBA</b>                                                     | 79-94-7     |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Ladestyring</b>                    | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                  | <b>TBBA</b>                                                     | 79-94-7     |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Multi-funktionskamera</b>          | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                  | <b>Pitch, coal tar, high-temp.</b>                              | 65996-93-2  |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Nærområderadar</b>                 | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Niveauregulering</b>               | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Omdanner</b>                       | <b>2-Methylimidazole</b>                                        | 693-98-1    |
|                                                  | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5  |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                  | <b>TBBA</b>                                                     | 79-94-7     |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Regn-/Lyssensor</b>                | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <hr/>                                            |                                                                 |             |
| <b>Styreenhed Signalreg.-og Aktiv.-Modul Fhs</b> | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2   |

|                                             |                                                          |            |
|---------------------------------------------|----------------------------------------------------------|------------|
| <b>Styreenhed Styret Ekstra Aksel</b>       | Lead-monoxide                                            | 1317-36-8  |
|                                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Styreenhed Styrevinkelsensor</b>         | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhed Telematikplatform</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                             | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhed Video Radar Decision Unit</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
|                                             |                                                          |            |
| <b>Styreenhed XMC</b>                       | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
|                                             | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |
| <b>Tætning</b>                              | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Temperatursensor</b>                     | TBBA                                                     | 79-94-7    |
| <b>Trykkontakt</b>                          | Lead-monoxide                                            | 1317-36-8  |
|                                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Tryksensor</b>                           | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | 1,2-Dimethoxyethane                                      | 110-71-4   |
|                                             | 1,3-Propanesultone                                       | 1120-71-4  |
|                                             |                                                          |            |
| <b>Tryktast</b>                             | Octamethylcyclotetrasiloxane                             | 556-67-2   |
|                                             | Decamethylcyclopentasiloxane                             | 541-02-6   |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
| <b>Varme</b>                                | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| <b>Ventilator</b>                           | TBBA                                                     | 79-94-7    |
|                                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Vippekontakt</b>                         | Lead-monoxide                                            | 1317-36-8  |
|                                             | TBBA                                                     | 79-94-7    |
| <b>Viskermotor</b>                          | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol          | 25973-55-1 |

Geachte klant,

de op 1 juni 2007 van kracht geworden wet inzake de Europese verordening over chemische stoffen (EG) nr. 1907/2006 (REACH - registratie, beoordeling, autorisatie en beperkingen van chemische stoffen) heeft als doel de menselijke gezondheid en het milieu te beschermen tegen mogelijke risico's als gevolg van het gebruik van chemische stoffen.

Daimler Truck AG ondersteunt de doelstellingen van REACH. Artikel 33 in de wetgeving schrijft voor dat u als klant over zeer zorgwekkende stoffen (SVHC) in onze producten dient te worden geïnformeerd. Het doel van deze richtlijn is om gedurende de gehele levenscyclus van het product voor een veilige omgang met de gedefinieerde stoffen te zorgen.

Op basis van de wettelijke bepalingen en met inachtneming van de gegevens van de leveranciers van Daimler Truck AG zijn de volgende stoffen geïdentificeerd, die mogelijk voor meer dan 0,1 gewichtsprocent aanwezig zijn in de producten die het voertuig afzonderlijk produceert. Wanneer het voertuig volgens de voorschriften wordt gebruikt, bestaat geen gevaar voor mens en milieu. Meer informatie over het veilige gebruik van uw voertuig vindt u in de gebruiksaanwijzing.

Let erop dat de startaccu, legeringen, coatings, glazen/keramische/elastomeer onderdelen en diverse elektronische onderdelen (vooral de soldeerverbindingen) bovendien lood (CAS-nr. 7439-92-1) bevatten.

| Productgroep               | Stofnaam                                                                                                                                     | CAS Nr.     |
|----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Aandrijfas                 | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                            | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                            | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                            | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                            | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                            | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                            | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                            | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                            | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                            | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                            | TBBA                                                                                                                                         | 79-94-7     |
|                            | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                            | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| Acceleratiesensor          | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                            | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Achterlicht                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                            | TBBA                                                                                                                                         | 79-94-7     |
|                            | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Afdichting                 | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Afdichtstop                | Bumetrizole                                                                                                                                  | 3896-11-5   |
| Airconditioning            | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Airconditioning-compressor | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                            | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                            | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                            | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                            | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                            | Tris(nonylphenyl)phosphite                                                                                                                   | 26523-78-4  |
| Antenne                    |                                                                                                                                              |             |
| Bandenspanning             | Lead titanium zirconium oxide                                                                                                                | 12626-81-2  |

|                              |                                                                  |             |
|------------------------------|------------------------------------------------------------------|-------------|
| <b>Antenneversterker</b>     | Lead-monoxide                                                    | 1317-36-8   |
|                              | Diboron-trioxide                                                 | 1303-86-2   |
| <b>As</b>                    | Boric acid                                                       | 10043-35-3  |
|                              | Imidazolidine-2-thione                                           | 96-45-7     |
|                              | Octamethylcyclotetrasiloxane                                     | 556-67-2    |
|                              | 2-Methylimidazole                                                | 693-98-1    |
|                              | Decamethylcyclopentasiloxane                                     | 541-02-6    |
|                              | Lead-monoxide                                                    | 1317-36-8   |
|                              | Diboron-trioxide                                                 | 1303-86-2   |
|                              | Tris(nonylphenyl)phosphite                                       | 26523-78-4  |
|                              | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9   |
|                              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1    |
|                              | Chromium-trioxide                                                | 1333-82-0   |
|                              | Hexahydromethylphthalic-anhydride                                | 25550-51-0  |
|                              | Paraffin oils, chloro                                            | 85422-92-0  |
|                              | TBBA                                                             | 79-94-7     |
|                              | Phenol, methylstyrenated                                         | 68512-30-1  |
|                              | Triphenyl-phosphate                                              | 115-86-6    |
|                              | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0    |
| <b>Asmodulator</b>           | Lead-monoxide                                                    | 1317-36-8   |
| <b>Bagagenet</b>             | N,N-Dimethylacetamide                                            | 127-19-5    |
| <b>Bedieningseenheid</b>     | Lead-monoxide                                                    | 1317-36-8   |
| <b>Bedieningshendel</b>      | Lead-monoxide                                                    | 1317-36-8   |
|                              | Diboron-trioxide                                                 | 1303-86-2   |
| <b>Bedieningsinstrument</b>  | Lead-monoxide                                                    | 1317-36-8   |
|                              | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9   |
| <b>Bedieningspaneel</b>      | Lead-monoxide                                                    | 1317-36-8   |
|                              | TBBA                                                             | 79-94-7     |
| <b>Beeldscherm</b>           | 2-Methylimidazole                                                | 693-98-1    |
|                              | Lead-monoxide                                                    | 1317-36-8   |
|                              | Diboron-trioxide                                                 | 1303-86-2   |
| <b>Bestuurdersstoel</b>      | 4,4'-Isopropylidenediphenol                                      | 80-05-7     |
|                              | Triphenyl-phosphate                                              | 115-86-6    |
| <b>Boordnetaccu</b>          | Lead-monoxide                                                    | 1317-36-8   |
|                              | Diboron-trioxide                                                 | 1303-86-2   |
|                              | Lead(II,IV)-oxide                                                | 1314-41-6   |
| <b>Bout Met Ronde Kop</b>    |                                                                  |             |
| <b>Met Binnentorxprofiel</b> | Diboron-trioxide                                                 | 1303-86-2   |
| <b>Camera</b>                | Octamethylcyclotetrasiloxane                                     | 556-67-2    |
|                              | 2-Methylimidazole                                                | 693-98-1    |
|                              | Decamethylcyclopentasiloxane                                     | 541-02-6    |
|                              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one         | 71868-10-5  |
|                              | Lead-monoxide                                                    | 1317-36-8   |
|                              | Diboron-trioxide                                                 | 1303-86-2   |
|                              | Dodecamethylcyclohexasiloxane                                    | 540-97-6    |
|                              | Refractory ceramic fibres                                        | 142844-00-6 |
| <b>Combischakelaar</b>       | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                  | 75980-60-8  |
|                              | Lead-monoxide                                                    | 1317-36-8   |
|                              | TBBA                                                             | 79-94-7     |
| <b>Controlelampje</b>        | TBBA                                                             | 79-94-7     |

|                                     |                                                                            |            |
|-------------------------------------|----------------------------------------------------------------------------|------------|
| Controlelampje                      | Melamine                                                                   | 108-78-1   |
| Deksel                              |                                                                            |            |
| Stroomaansluiting                   | Bumetrizole                                                                | 3896-11-5  |
| Deurslot                            | Triphenyl-phosphate                                                        | 115-86-6   |
| Diode                               | TBBA                                                                       | 79-94-7    |
| Doorvoertule                        | Imidazolidine-2-thione                                                     | 96-45-7    |
| Druknop                             | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                     | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                     | Lead-monoxide                                                              | 1317-36-8  |
|                                     | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| Druksensor                          | Lead titanium zirconium oxide                                              | 12626-81-2 |
|                                     | Lead-monoxide                                                              | 1317-36-8  |
|                                     | 1,2-Dimethoxyethane                                                        | 110-71-4   |
|                                     | 1,3-Propanesultone                                                         | 1120-71-4  |
|                                     |                                                                            |            |
| Elektrische Kabelboom               | Melamine                                                                   | 108-78-1   |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Energieverdelers                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                     | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                     | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| Ethernetomvormer                    | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                     | Lead-monoxide                                                              | 1317-36-8  |
| Gaspedaal                           | Lead-monoxide                                                              | 1317-36-8  |
|                                     | TBBA                                                                       | 79-94-7    |
| Gloeilamp                           | Diboron-trioxide                                                           | 1303-86-2  |
| Hoogspanningsaccu-module            |                                                                            |            |
|                                     | Lead-monoxide                                                              | 1317-36-8  |
|                                     |                                                                            |            |
| Interieurverlichting                | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
|                                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Klep                                | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Koelvloeistofpomp                   | Lead-monoxide                                                              | 1317-36-8  |
|                                     | Diboron-trioxide                                                           | 1303-86-2  |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Koplamp                             | Lead-monoxide                                                              | 1317-36-8  |
| Lichtschakelaar                     | Lead-monoxide                                                              | 1317-36-8  |
| Luchtgeveerde Stoel                 | Triphenyl-phosphate                                                        | 115-86-6   |
| Magneetklep                         | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| Markeringslichten                   | TBBA                                                                       | 79-94-7    |
|                                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
|                                     |                                                                            |            |
| Multimedia-Aansluitteenheid         | Lead-monoxide                                                              | 1317-36-8  |
|                                     | Diboron-trioxide                                                           | 1303-86-2  |
| O-Ring                              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| Plafondverlichting                  | Triphenyl-phosphate                                                        | 115-86-6   |
| Portier                             | Triphenyl-phosphate                                                        | 115-86-6   |
| Profielafdichting                   | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Radiatorop                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Regeleenheid Accu-managementsysteem |                                                                            |            |
|                                     | Lead-monoxide                                                              | 1317-36-8  |
| Regeleenheid                        |                                                                            |            |
| Afstandssensor                      | Lead-titanium-trioxide                                                     | 12060-00-3 |

|                                                         |                                                                 |             |
|---------------------------------------------------------|-----------------------------------------------------------------|-------------|
| <b>Afstandssensor</b>                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                         | <b>TBBA</b>                                                     | 79-94-7     |
| <b>Regeleenheid Air Processing Unit</b>                 | <b>Lead titanium zirconium oxide</b>                            | 12626-81-2  |
|                                                         | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
| <b>Regeleenheid Airbag</b>                              | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                         | <b>TBBA</b>                                                     | 79-94-7     |
| <b>Regeleenheid Automatische Airconditioning</b>        | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <b>Regeleenheid Banden-spanningscontrole</b>            | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <b>Regeleenheid Centrale Gateway</b>                    | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
| <b>Regeleenheid Combi-Instrument</b>                    | <b>4,4'-Isopropylidenediphenol</b>                              | 80-05-7     |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                         | <b>TBBA</b>                                                     | 79-94-7     |
| <b>Regeleenheid Dc/Dc-Omvormer</b>                      |                                                                 |             |
| <b>Laagspanning 1</b>                                   | <b>N,N-Dimethylacetamide</b>                                    | 127-19-5    |
|                                                         | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5  |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>             | 119-47-1    |
|                                                         | <b>Dodecamethylcyclohexasiloxane</b>                            | 540-97-6    |
|                                                         | <b>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide</b>          | 75980-60-8  |
| <b>Regeleenheid Display</b>                             | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5  |
|                                                         | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                         | <b>1-Propanol, 2,3-dibromo-</b>                                 | 96-13-9     |
| <b>Regeleenheid Edrive Common Powertrain Controller</b> | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                         | <b>TBBA</b>                                                     | 79-94-7     |
|                                                         | <b>2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone</b>       | 119313-12-1 |
| <b>Regeleenheid Elektronisch Contactslot</b>            | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                            | 1317-36-8   |

|                                              |                                                          |            |
|----------------------------------------------|----------------------------------------------------------|------------|
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Gestuurde Extra As</b>                    | Lead-monoxide                                            | 1317-36-8  |
|                                              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                              | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Korteafstandsradar</b>                    | Lead-monoxide                                            | 1317-36-8  |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Multifunctionele Camera</b>               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                              | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
|                                              | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Niveauregeling</b>                        | Lead-monoxide                                            | 1317-36-8  |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Omvormer</b>                              | 2-Methylimidazole                                        | 693-98-1   |
|                                              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                              | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
|                                              | TBBA                                                     | 79-94-7    |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Oplaadregeling</b>                        | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
|                                              | TBBA                                                     | 79-94-7    |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Portiermodule</b>                         |                                                          |            |
| <b>Bestuurder</b>                            | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Portiermodule Bijrijder</b>               | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Regeleenheid Regen-/Lichtsensoren</b>     | Lead-monoxide                                            | 1317-36-8  |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Signaalopname- en Aanst.Module Cabine</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                              | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Stuurhoeksensor</b>                       | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Tachograaf</b>                            | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                              | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                              | Lead-monoxide                                            | 1317-36-8  |
|                                              | Diboron-trioxide                                         | 1303-86-2  |
|                                              | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                                              | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Regeleenheid</b>                          |                                                          |            |
| <b>Telematicaplatform</b>                    | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |

|                       |                                                             |            |
|-----------------------|-------------------------------------------------------------|------------|
| Telematicaplatform    | Lead-titanium-trioxide                                      | 12060-00-3 |
|                       | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Regeleenheid          |                                                             |            |
| Transmissieregeling   | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Regeleenheid Video    |                                                             |            |
| Radar Decision Unit   | Lead-titanium-trioxide                                      | 12060-00-3 |
|                       | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Regeleenheid XMC      | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
|                       | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride          | 19438-60-9 |
| Remslang              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
|                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Remwaardesensor       | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Ruitenwissermotor     | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol             | 25973-55-1 |
| Schroefkoppeling      | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Sleutelset            | 1,2-Dimethoxyethane                                         | 110-71-4   |
| Sluitring             | Imidazolidine-2-thione                                      | 96-45-7    |
| Spanningsomvormer     | Melamine                                                    | 108-78-1   |
| Spatscherm            | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Spiegel               | 2-Methylimidazole                                           | 693-98-1   |
|                       | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Spiegel Buitenzijde   | TBBA                                                        | 79-94-7    |
|                       | Triphenyl-phosphate                                         | 115-86-6   |
| Stoel Naast Chauffeur | C,C'-azodi(formamide)                                       | 123-77-3   |
|                       | Melamine                                                    | 108-78-1   |
|                       | Triphenyl-phosphate                                         | 115-86-6   |
| Stuurwiel             | Lead-monoxide                                               | 1317-36-8  |
| Temperatuursensor     | TBBA                                                        | 79-94-7    |
| Toetsschakelaar       | Lead-monoxide                                               | 1317-36-8  |
|                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Tuimelschakelaar      | Lead-monoxide                                               | 1317-36-8  |
|                       | TBBA                                                        | 79-94-7    |
| Veerbalg              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| Veiligheidsvest       | Diboron-trioxide                                            | 1303-86-2  |
| Ventilator            | TBBA                                                        | 79-94-7    |
|                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Verdamper             | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Verwarming            | Lead-titanium-trioxide                                      | 12060-00-3 |
|                       | Lead-monoxide                                               | 1317-36-8  |
|                       | Diboron-trioxide                                            | 1303-86-2  |
| Viltstrook            | Disodium-octaborate                                         | 12008-41-2 |
| Werkcilinder          | Imidazolidine-2-thione                                      | 96-45-7    |
|                       | Lead-monoxide                                               | 1317-36-8  |
| Zeskantbout           | Diboron-trioxide                                            | 1303-86-2  |
| Zijdeur               | Triphenyl-phosphate                                         | 115-86-6   |



Dear customer,

The law concerning the European Commission's Regulation (EC) No 1907/2006 (REACH – the registration, evaluation, authorization, and restriction of chemicals), which went into effect on June 1, 2007, aims to protect human health and the environment from possible risks due to chemicals.

Daimler Truck AG supports the goals of REACH. Article 33 of the legislation requires our company to inform its customers about “substances of very high concern” (SVHCs) that are contained in our products. The purpose of this regulation is to guarantee the safe use of the defined substances throughout the entire life cycle of the respective product.

In fulfillment of these legal requirements, and taking into account the information provided by the suppliers of Daimler Truck AG, we have identified the following substances that may be present above a concentration of 0.1% (w/w) in the individual articles of this vehicle. The normal use of this vehicle does not create any risks for human beings or the environment. You can find further information about the safe use of your vehicle in the operating instructions.

Please note that in addition the substance lead (CAS No. 7439-92-1) is contained in the starter battery, in alloys, coatings, glass/ceramic/elastomer component parts and various electronic component parts (above all solders).

| Product group           | Substance name                                                   | CAS No.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Brake Value Sensor      | Lead-monoxide                                                    | 1317-36-8  |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Brake Value Sensor</b>                      | Diboron-trioxide                                         | 1303-86-2   |
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Automatic Climate Control</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Central Gateway</b>            | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Electronic Ignition Lock</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Instrument Cluster</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit Rain-Light Sensor</b>          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Video Radar Decision Unit</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Air-Processing Unit</b>       | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                              |             |
|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                         | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | TBBA                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                                         | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                         | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                         | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                         | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                         | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                         | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                         | TBBA                                                                                                                                         | 79-94-7     |
|                                                         | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                         | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | Melamine                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                  |                                                 |            |
|------------------|-------------------------------------------------|------------|
| Wiper Motor      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol | 25973-55-1 |
| Working Cylinder | Imidazolidine-2-thione                          | 96-45-7    |
|                  | Lead-monoxide                                   | 1317-36-8  |

Väga austatud klient,

01. juunil 2007 jõustunud ELi kemikaalimääruse (EÜ) nr 1907/2006 (REACH - kemikaalide registreerimine, hindamine, autoriseerimine ja piiramine) eesmärk on tagada inimeste tervise ja keskkonna kaitse võimalike kemikaalidest tulenevate riskide eest.

Daimler Truck AG toetab REACHi eesmärke. Seaduse artikkel 33 näeb ette, et klienti tuleb teavitada eriti murettekitavatest ainetest (SVHC) meie toodetes. Selle nõude eesmärk on tagada määratud ainetega ohutu ümberkäimine kogu toote eluea jooksul.

Seadusenõuete alusel ja Daimler Truck AG tarnija andmetel on määratletud, et järgmised ained ei tohi moodustada selle sõiduki üksikutes komponentides enam kui 0,1 kaaluprotsenti. Sõiduki sihipärasel kasutamisel ei kaasne mingit ohtu inimesele ja keskkonnale. Lisateavet oma sõiduki ohutu kasutamise kohta leiate oma kasutusjuhendist.

Palun arvestage, et täiendav pliikangas (CAS-nr 7439-92-1) starteriakus, sulamites, pinnakattes, klaasist / keraamilistes / elastomeerist komponentides ja mitmesugustes elektroonilistes komponentides (eelkõige joodised) kuulub komplekti.

| Product group           | Substance name                                                   | CAS no.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Brake Value Sensor      | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit Automatic</b>                  |                                                          |             |
| <b>Climate Control</b>                         | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                |                                                          |             |
| <b>Control Unit Central</b>                    |                                                          |             |
| <b>Gateway</b>                                 | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit Electronic</b>                 |                                                          |             |
| <b>Ignition Lock</b>                           | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                |                                                          |             |
| <b>Control Unit Instrument</b>                 |                                                          |             |
| <b>Cluster</b>                                 | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
|                                                |                                                          |             |
| <b>Control Unit Rain-Light</b>                 |                                                          |             |
| <b>Sensor</b>                                  | Lead-monoxide                                            | 1317-36-8   |
|                                                |                                                          |             |
| <b>Control Unit Video</b>                      |                                                          |             |
| <b>Radar Decision Unit</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
|                                                |                                                          |             |
| <b>Control Unit, Air-Processing Unit</b>       |                                                          |             |
|                                                | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                              |             |
|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                         | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | TBBA                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                                         | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                         | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                         | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                         | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                         | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                         | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                         | TBBA                                                                                                                                         | 79-94-7     |
|                                                         | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                         | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | Melamine                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                         |                                                        |                   |
|-------------------------|--------------------------------------------------------|-------------------|
| <b>Wiper Motor</b>      | <b>2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol</b> | <b>25973-55-1</b> |
| <b>Working Cylinder</b> | <b>Imidazolidine-2-thione</b>                          | <b>96-45-7</b>    |
|                         | <b>Lead-monoxide</b>                                   | <b>1317-36-8</b>  |

Arvoisa asiakas,

01. kesäkuuta 2007 voimaan astunutta EU:n kemikaaliasetusta (EY) nro 1907/2006, (REACH - kemikaalien rekisteröinti, arviointi, lupamenettelyt ja rajoitukset) koskevan lain tavoitteeksi on asetettu ihmisten terveyden ja ympäristön suojaaminen kemikaaleista aiheutuvilta mahdollisilta riskeiltä.

Daimler Truck AG tukee REACH-asetuksen tavoitteita. Lainsäädännön artiklassa 33 määrätään, että sinua on tiedotettava asiakkaana tuotteissamme olevista erityistä huolta aiheuttavista aineista (SVHC). Tämän määräyksen tavoitteena on taata määritettyjen aineiden turvallinen käsittely tuotteen koko elinkaaren ajan.

Lakisääteisten määräysten pohjalta ja Daimler Truck AG:n toimittajien tietoja noudattaen on tunnistettu seuraavat aineet, joita voi esiintyä yli 0,1 painoprosenttia tämän auton yksittäisissä valmisteissa. Kun autoa käytetään määräysten mukaisesti, ihmisiin ja ympäristöön ei kohdistu vaaroja. Autosi turvalliseen käyttöön liittyviä lisätietoja löytyy käyttöohjekirjasta.

Huomaa, että lisäksi myös lyijyä (CAS-nro 7439-92-1) on käynnistysakussa, seoksissa, päällysteaineissa, lasista/keramiikasta/elastomeerista valmistetuissa rakenneosissa sekä erilaisissa elektroniikkarakenneosissa (ennen kaikkea juotuksissa).

| Tuoteryhmä                | Aineen nimi                                                             | CAS-nro    |
|---------------------------|-------------------------------------------------------------------------|------------|
| <b>Akseli</b>             | <b>Boric acid</b>                                                       | 10043-35-3 |
|                           | <b>Imidazolidine-2-thione</b>                                           | 96-45-7    |
|                           | <b>Octamethylcyclotetrasiloxane</b>                                     | 556-67-2   |
|                           | <b>2-Methylimidazole</b>                                                | 693-98-1   |
|                           | <b>Decamethylcyclopentasiloxane</b>                                     | 541-02-6   |
|                           | <b>Lead-monoxide</b>                                                    | 1317-36-8  |
|                           | <b>Diboron-trioxide</b>                                                 | 1303-86-2  |
|                           | <b>Tris(nonylphenyl)phosphite</b>                                       | 26523-78-4 |
|                           | <b>1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione</b> | 2451-62-9  |
|                           | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>                     | 119-47-1   |
|                           | <b>Chromium-trioxide</b>                                                | 1333-82-0  |
|                           | <b>Hexahydromethylphthalic-anhydride</b>                                | 25550-51-0 |
|                           | <b>Paraffin oils, chloro</b>                                            | 85422-92-0 |
|                           | <b>TBBA</b>                                                             | 79-94-7    |
|                           | <b>Phenol, methylstyrenated</b>                                         | 68512-30-1 |
|                           | <b>Triphenyl-phosphate</b>                                              | 115-86-6   |
|                           | <b>O,O,O-Triphenyl phosphorothioate</b>                                 | 597-82-0   |
| <b>Akselimodulaattori</b> | <b>Lead-monoxide</b>                                                    | 1317-36-8  |
| <b>Antennivahvistin</b>   | <b>Lead-monoxide</b>                                                    | 1317-36-8  |
|                           | <b>Diboron-trioxide</b>                                                 | 1303-86-2  |
| <b>Avainsarja</b>         | <b>1,2-Dimethoxyethane</b>                                              | 110-71-4   |
| <b>Diodi</b>              | <b>TBBA</b>                                                             | 79-94-7    |
| <b>Energiajakaja</b>      | <b>Octamethylcyclotetrasiloxane</b>                                     | 556-67-2   |
|                           | <b>Decamethylcyclopentasiloxane</b>                                     | 541-02-6   |
|                           | <b>Dodecamethylcyclohexasiloxane</b>                                    | 540-97-6   |
| <b>Ethernet-Muunnin</b>   | <b>Lead-titanium-trioxide</b>                                           | 12060-00-3 |
|                           | <b>Lead-monoxide</b>                                                    | 1317-36-8  |
| <b>Etuovi</b>             | <b>Triphenyl-phosphate</b>                                              | 115-86-6   |
| <b>Hekkulamppu</b>        | <b>Diboron-trioxide</b>                                                 | 1303-86-2  |
| <b>Höyrystin</b>          | <b>Lead-monoxide</b>                                                    | 1317-36-8  |
|                           | <b>Diboron-trioxide</b>                                                 | 1303-86-2  |
| <b>Huopaliuska</b>        | <b>Disodium-octaborate</b>                                              | 12008-41-2 |
| <b>Ilmastointilaite</b>   | <b>Lead-monoxide</b>                                                    | 1317-36-8  |

|                                    |                                                                            |             |
|------------------------------------|----------------------------------------------------------------------------|-------------|
| Ilmastointilaitteen<br>Kompressori | 4,4'-Isopropylidenediphenol                                                | 80-05-7     |
|                                    | 2-Methylimidazole                                                          | 693-98-1    |
|                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                                    | Lead-monoxide                                                              | 1317-36-8   |
|                                    | Diboron-trioxide                                                           | 1303-86-2   |
|                                    | Tris(nonylphenyl)phosphite                                                 | 26523-78-4  |
| Jäähdyttimen Kansi                 | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Jäähdytysneste-<br>pumppu          | Lead-monoxide                                                              | 1317-36-8   |
|                                    | Diboron-trioxide                                                           | 1303-86-2   |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Jännitteenmuunnin                  | Melamine                                                                   | 108-78-1    |
| Jarruletku                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1    |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Jarrupoljinanturi-<br>yksikkö      | Lead-monoxide                                                              | 1317-36-8   |
|                                    | Diboron-trioxide                                                           | 1303-86-2   |
| Jousipalje                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1    |
| Jousitettu Istuin                  | Triphenyl-phosphate                                                        | 115-86-6    |
| Kaasupoljin                        | Lead-monoxide                                                              | 1317-36-8   |
|                                    | TBBA                                                                       | 79-94-7     |
| Kamera                             | Octamethylcyclotetrasiloxane                                               | 556-67-2    |
|                                    | 2-Methylimidazole                                                          | 693-98-1    |
|                                    | Decamethylcyclopentasiloxane                                               | 541-02-6    |
|                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                                    | Lead-monoxide                                                              | 1317-36-8   |
|                                    | Diboron-trioxide                                                           | 1303-86-2   |
|                                    | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
|                                    | Refractory ceramic fibres                                                  | 142844-00-6 |
| Katkaisin                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                            | 75980-60-8  |
|                                    | Lead-monoxide                                                              | 1317-36-8   |
|                                    | TBBA                                                                       | 79-94-7     |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Katkaisinryhmä                     | Lead-monoxide                                                              | 1317-36-8   |
|                                    | TBBA                                                                       | 79-94-7     |
| Kattovalo                          | Triphenyl-phosphate                                                        | 115-86-6    |
| Käyttölaite                        | Lead-monoxide                                                              | 1317-36-8   |
|                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
| Käyttövipu                         | Lead-monoxide                                                              | 1317-36-8   |
|                                    | Diboron-trioxide                                                           | 1303-86-2   |
| Käyttöyksikkö                      | Lead-monoxide                                                              | 1317-36-8   |
| Kierrelitiin                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Kiihtyvyytunnistin                 | Diboron-trioxide                                                           | 1303-86-2   |
| Korkeajänniteakku-<br>moduuli      | Lead-monoxide                                                              | 1317-36-8   |
|                                    | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3  |
|                                    | 4,4'-Isopropylidenediphenol                                                | 80-05-7     |
| Kuljettajan Istuin                 | Triphenyl-phosphate                                                        | 115-86-6    |
|                                    |                                                                            |             |
| Kuusikulmainen Ruuvi               | Diboron-trioxide                                                           | 1303-86-2   |

|                                                                |                                                             |             |
|----------------------------------------------------------------|-------------------------------------------------------------|-------------|
| <b>Kuusiokantaruuvi</b>                                        | Diboron-trioxide                                            | 1303-86-2   |
| <b>Kuvaruutu</b>                                               | 2-Methylimidazole                                           | 693-98-1    |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
|                                                                | Diboron-trioxide                                            | 1303-86-2   |
| <b>Lämmitys</b>                                                | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
|                                                                | Diboron-trioxide                                            | 1303-86-2   |
| <b>Lämpötilatunnistin</b>                                      | TBBA                                                        | 79-94-7     |
| <b>Läpivientisuojaus</b>                                       | Imidazolidine-2-thione                                      | 96-45-7     |
| <b>Lokasuojat</b>                                              | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| <b>Luukku</b>                                                  | C,C'-azodi(formamide)                                       | 123-77-3    |
| <b>Magneettiventtiili</b>                                      | Dodecamethylcyclotetrasiloxane                              | 540-97-6    |
| <b>Merkkivalo</b>                                              | TBBA                                                        | 79-94-7     |
|                                                                | Melamine                                                    | 108-78-1    |
|                                                                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| <b>Multimedia-<br/>Liitäntäyksikkö</b>                         | Lead-monoxide                                               | 1317-36-8   |
|                                                                | Diboron-trioxide                                            | 1303-86-2   |
| <b>Ohjainlaite Ajopiirturi</b>                                 | Lead titanium zirconium oxide                               | 12626-81-2  |
|                                                                | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
|                                                                | Diboron-trioxide                                            | 1303-86-2   |
|                                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
|                                                                | Triphenyl-phosphate                                         | 115-86-6    |
| <b>Ohjainlaite Akku-<br/>hallintajärjestelmä</b>               | Lead-monoxide                                               | 1317-36-8   |
| <b>Ohjainlaite Dc/Dc-<br/>Muunnin Matalajännite<br/>1</b>      | N,N-Dimethylacetamide                                       | 127-19-5    |
|                                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
|                                                                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
|                                                                | Dodecamethylcyclotetrasiloxane                              | 540-97-6    |
|                                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
| <b>Ohjainlaite Edrive<br/>Common Powertrain<br/>Controller</b> | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
|                                                                | Diboron-trioxide                                            | 1303-86-2   |
|                                                                | TBBA                                                        | 79-94-7     |
|                                                                | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone          | 119313-12-1 |
| <b>Ohjainlaite Elektroninen<br/>Virtalukko</b>                 | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
| <b>Ohjainlaite<br/>Etäisyystunnistin</b>                       | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                                | Lead-monoxide                                               | 1317-36-8   |
|                                                                | Diboron-trioxide                                            | 1303-86-2   |
|                                                                | TBBA                                                        | 79-94-7     |

|                                            |                                                                                                                                                     |                                                               |
|--------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| Ohjainlaite Ilmastointi-<br>automaatiikka  | Lead-titanium-trioxide<br>Lead-monoxide                                                                                                             | 12060-00-3<br>1317-36-8                                       |
| Ohjainlaite Jatkuva<br>Rengaspainevalvonta | Lead-monoxide                                                                                                                                       | 1317-36-8                                                     |
| Ohjainlaite<br>Keskusyhdyskäytävä          | Lead-monoxide<br>Diboron-trioxide                                                                                                                   | 1317-36-8<br>1303-86-2                                        |
| Ohjainlaite<br>Lähialuetutka               | Lead-monoxide                                                                                                                                       | 1317-36-8                                                     |
| Ohjainlaite Latauksen<br>Ohjaus            | Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                                           | 1317-36-8<br>1303-86-2<br>79-94-7                             |
| Ohjainlaite Mittaristo                     | 4,4'-Isopropylidenediphenol<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                            | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7                  |
| Ohjainlaite<br>Monitoimikamera             | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Pitch, coal tar, high-temp.                                                          | 12060-00-3<br>1317-36-8<br>1303-86-2<br>65996-93-2            |
| Ohjainlaite Muunnin                        | 2-Methylimidazole<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                          | 693-98-1<br>71868-10-5<br>1317-36-8<br>1303-86-2<br>79-94-7   |
| Ohjainlaite Näyttö                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>1-Propanol, 2,3-dibromo- | 71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>96-13-9 |
| Ohjainlaite Ohjaava<br>Lisäakseli          | Lead-monoxide<br>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol<br>Bis(alpha,alpha-dimethylbenzyl) peroxide                                           | 1317-36-8<br>119-47-1<br>80-43-3                              |
| Ohjainlaite<br>Ohjauskulmatunnistin        | Lead-monoxide<br>Diboron-trioxide                                                                                                                   | 1317-36-8<br>1303-86-2                                        |
| Ohjainlaite Ovimoduli<br>Etumatkustaja     | Lead-monoxide<br>Diboron-trioxide                                                                                                                   | 1317-36-8<br>1303-86-2                                        |
| Ohjainlaite Ovimoduli<br>Kuljettaja        | Lead-monoxide<br>Diboron-trioxide                                                                                                                   | 1317-36-8<br>1303-86-2                                        |
| Ohjainlaite<br>Paineilmayksikkö            | Lead titanium zirconium oxide                                                                                                                       | 12626-81-2                                                    |

|                                             |                                                          |            |
|---------------------------------------------|----------------------------------------------------------|------------|
| Paineilmayksikkö                            | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| Ohjainlaite Sade-<br>Valotunnistin          | Lead-monoxide                                            | 1317-36-8  |
| Ohjainlaite Sign.Muokk.<br>ja Ohjausmoduuli |                                                          |            |
| Ohjaamo                                     | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| Ohjainlaite Tasonsäätö                      | Lead-monoxide                                            | 1317-36-8  |
| Ohjainlaite                                 |                                                          |            |
| Telematiikka-Alusta                         | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                             | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| Ohjainlaite Turvatyyny                      | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
|                                             | TBBA                                                     | 79-94-7    |
| Ohjainlaite                                 |                                                          |            |
| Vaihteistonohjaus                           | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| Ohjainlaite Video Radar<br>Decision Unit    | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| Ohjainlaite XMC                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
|                                             | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |
| Ohjauspyörä                                 | Lead-monoxide                                            | 1317-36-8  |
| Oppaan Istuin                               | C,C'-azodi(formamide)                                    | 123-77-3   |
|                                             | Melamine                                                 | 108-78-1   |
|                                             | Triphenyl-phosphate                                      | 115-86-6   |
| O-Rengas                                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
| Ovi                                         | Triphenyl-phosphate                                      | 115-86-6   |
| Ovilukko                                    | Triphenyl-phosphate                                      | 115-86-6   |
| Painetunnistin                              | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | 1,2-Dimethoxyethane                                      | 110-71-4   |
|                                             | 1,3-Propanesultone                                       | 1120-71-4  |
| Painonäppäin                                | Octamethylcyclotetrasiloxane                             | 556-67-2   |
|                                             | Decamethylcyclopentasiloxane                             | 541-02-6   |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
| Peili                                       | 2-Methylimidazole                                        | 693-98-1   |
|                                             | Lead-monoxide                                            | 1317-36-8  |
|                                             | Diboron-trioxide                                         | 1303-86-2  |
| Peili Ulko                                  | TBBA                                                     | 79-94-7    |

|                     |                                                                                                                                              |             |
|---------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Peili Ulko          | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Pistorasian Kansi   | Bumetrizole                                                                                                                                  | 3896-11-5   |
| Profiilitiiviste    | C,C'-azodi(formamide)                                                                                                                        | 123-77-3    |
| Pyyhinmoottori      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                                                                                              | 25973-55-1  |
| Rengaspaineantenni  | Lead titanium zirconium oxide                                                                                                                | 12626-81-2  |
| Sähköjohtosarja     | Melamine                                                                                                                                     | 108-78-1    |
|                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Sähkölaiteakku      | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                     | Lead(II,IV)-oxide                                                                                                                            | 1314-41-6   |
| Sisävalo            | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Sivulasi            | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Sulkulevy           | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| Sulkutulppa         | Bumetrizole                                                                                                                                  | 3896-11-5   |
| Takavalo            | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                     | TBBA                                                                                                                                         | 79-94-7     |
|                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Tavaraverkko        | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
| Tiiviste            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Turvalliivi         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Tuuletin            | TBBA                                                                                                                                         | 79-94-7     |
|                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Työsylinteri        | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Valokatkaisin       | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Valonheitin         | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Vetoakseli          | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                     | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                     | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                     | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                     | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                     | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                     | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                     | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                     | TBBA                                                                                                                                         | 79-94-7     |
|                     | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                     | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                     | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Yhdistelmäkatkaisin | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                     | TBBA                                                                                                                                         | 79-94-7     |

Chère cliente, cher client,

En vigueur depuis le 1er juin 2007, la loi en application du règlement (CE) 1907/2006 concernant l'enregistrement, l'évaluation et l'autorisation des substances chimiques, ainsi que les restrictions applicables à ces substances (REACH) a pour objectif de protéger la santé humaine et l'environnement de tout risque potentiel lié à des substances chimiques.

Daimler Truck AG soutient les objectifs de REACH. L'article 33 de la législation prévoit qu'en tant que client(e), vous devez être informé(e) de la présence de substances extrêmement préoccupantes (SVHC) présentes dans nos produits. L'objectif de cette disposition est de garantir la sécurité au contact des substances définies tout au long du cycle de vie du produit.

Sur la base des dispositions légales ainsi que des informations des fournisseurs de Daimler Truck AG, les substances suivantes ont été identifiées dans différents composants du présent véhicule avec un pourcentage du poids respectif de plus de 0,1 %. Si le véhicule est utilisé aux fins prévues, ces substances ne présentent aucun risque pour l'homme et l'environnement. Pour de plus amples informations sur l'utilisation sans risques de votre véhicule, veuillez consulter sa notice d'utilisation.

Veuillez noter que du plomb (no CAS 7439-92-1) est également contenu dans la batterie de démarrage, les alliages, les revêtements, les composants en verre/en céramique/élastomères ainsi que dans divers composants électroniques (notamment du fil à plomb).

| Groupe de produits                      | Nome de la substance                                        | N° CAS     |
|-----------------------------------------|-------------------------------------------------------------|------------|
| Aile                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Amplificateur                           |                                                             |            |
| D'Antenne                               | Lead-monoxide                                               | 1317-36-8  |
|                                         | Diboron-trioxide                                            | 1303-86-2  |
| Ampoule                                 | Diboron-trioxide                                            | 1303-86-2  |
| Antenne De Roue                         | Lead titanium zirconium oxide                               | 12626-81-2 |
| Appareil De Commande                    | Lead-monoxide                                               | 1317-36-8  |
|                                         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Bande De Feutre                         | Disodium-octaborate                                         | 12008-41-2 |
| Batterie Du Réseau De Bord              | Lead-monoxide                                               | 1317-36-8  |
|                                         | Diboron-trioxide                                            | 1303-86-2  |
|                                         | Lead(II,IV)-oxide                                           | 1314-41-6  |
| Bouchon                                 | Bumetrizole                                                 | 3896-11-5  |
| Bouchon De Radiateur                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Bouton-Poussoir                         | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                                         | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                                         | Lead-monoxide                                               | 1317-36-8  |
|                                         | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| Calculateur Caméra Multifonction        | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                         | Lead-monoxide                                               | 1317-36-8  |
|                                         | Diboron-trioxide                                            | 1303-86-2  |
|                                         | Pitch, coal tar, high-temp.                                 | 65996-93-2 |
| Calculateur Capteur D'Angle De Braquage | Lead-monoxide                                               | 1317-36-8  |
|                                         | Diboron-trioxide                                            | 1303-86-2  |
| Calculateur Capteur De Distance         | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                         | Lead-monoxide                                               | 1317-36-8  |

|                                                                |                                                                                                                                                                                                                                                    |                                                                                       |
|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| <b>Distance</b>                                                | <b>Diboron-trioxide<br/>TBBA</b>                                                                                                                                                                                                                   | <b>1303-86-2<br/>79-94-7</b>                                                          |
| <b>Calculateur Capteur De<br/>Pluie Et De Luminosité</b>       | <b>Lead-monoxide</b>                                                                                                                                                                                                                               | <b>1317-36-8</b>                                                                      |
| <b>Calculateur Climatiseur<br/>Automatique</b>                 | <b>Lead-titanium-trioxide<br/>Lead-monoxide</b>                                                                                                                                                                                                    | <b>12060-00-3<br/>1317-36-8</b>                                                       |
| <b>Calculateur Commande<br/>De Boîte</b>                       | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                                                                                                          | <b>1317-36-8<br/>1303-86-2</b>                                                        |
| <b>Calculateur Contacteur<br/>Antivol Electronique</b>         | <b>Lead-titanium-trioxide<br/>Lead-monoxide</b>                                                                                                                                                                                                    | <b>12060-00-3<br/>1317-36-8</b>                                                       |
| <b>Calculateur Contrôle De<br/>La Pression Des Pneus</b>       | <b>Lead-monoxide</b>                                                                                                                                                                                                                               | <b>1317-36-8</b>                                                                      |
| <b>Calculateur<br/>Convertisseur Dc/Dc<br/>Basse Tension 1</b> | <b>N,N-Dimethylacetamide<br/>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-monoxide<br/>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol<br/>Dodecamethylcyclohexasiloxane<br/>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide</b> | <b>127-19-5<br/>71868-10-5<br/>1317-36-8<br/>119-47-1<br/>540-97-6<br/>75980-60-8</b> |
| <b>Calculateur Correcteur<br/>De Niveau</b>                    | <b>Lead-monoxide</b>                                                                                                                                                                                                                               | <b>1317-36-8</b>                                                                      |
| <b>Calculateur D'Airbag</b>                                    | <b>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                                                                                                                                                                                                 | <b>1317-36-8<br/>1303-86-2<br/>79-94-7</b>                                            |
| <b>Calculateur De Module<br/>De Porte Passager</b>             | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                                                                                                          | <b>1317-36-8<br/>1303-86-2</b>                                                        |
| <b>Calculateur De Module<br/>Porte Conducteur</b>              | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                                                                                                          | <b>1317-36-8<br/>1303-86-2</b>                                                        |
| <b>Calculateur D'Écran</b>                                     | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide<br/>1-Propanol, 2,3-dibromo-</b>                                                                                     | <b>71868-10-5<br/>12060-00-3<br/>1317-36-8<br/>1303-86-2<br/>96-13-9</b>              |
| <b>Calculateur Edrive<br/>Common Powertrain<br/>Controller</b> | <b>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                                                                                                                                                                      | <b>12060-00-3<br/>1317-36-8<br/>1303-86-2<br/>79-94-7</b>                             |

|                                                                   |                                                                                                                                                                        |                                                                              |
|-------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>Common Powertrain</b>                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone                                                                                                                     | 119313-12-1                                                                  |
| <b>Calculateur Essieu<br/>Additionnel Directeur</b>               | Lead-monoxide<br>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol<br>Bis(alpha,alpha-dimethylbenzyl) peroxide                                                              | 1317-36-8<br>119-47-1<br>80-43-3                                             |
| <b>Calculateur Gestion De<br/>La Charge</b>                       | Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                                                              | 1317-36-8<br>1303-86-2<br>79-94-7                                            |
| <b>Calculateur Module<br/>Saisie Signaux et<br/>Commande Cab.</b> | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                                                            | 12060-00-3<br>1317-36-8<br>1303-86-2                                         |
| <b>Calculateur Passerelle<br/>Centrale</b>                        | Lead-monoxide<br>Diboron-trioxide                                                                                                                                      | 1317-36-8<br>1303-86-2                                                       |
| <b>Calculateur Plate-Forme<br/>Télématique</b>                    | 4,4'-Isopropylidenediphenol<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                 | 80-05-7<br>71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2                |
| <b>Calculateur Radar De<br/>Proximité</b>                         | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Calculateur Redresseur</b>                                     | 2-Methylimidazole<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                             | 693-98-1<br>71868-10-5<br>1317-36-8<br>1303-86-2<br>79-94-7                  |
| <b>Calculateur Tableau De<br/>Bord</b>                            | 4,4'-Isopropylidenediphenol<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                               | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7                                 |
| <b>Calculateur<br/>Tachygraphe</b>                                | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide<br>Triphenyl-phosphate | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>75980-60-8<br>115-86-6 |
| <b>Calculateur Unité De<br/>Gestion Batterie</b>                  | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Calculateur Unité De<br/>Traitement De L'Air</b>               | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                           | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2                           |

|                                 |                                                          |             |
|---------------------------------|----------------------------------------------------------|-------------|
| <b>Calculateur Video Radar</b>  |                                                          |             |
| <b>Decision Unit</b>            | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                 | Lead-monoxide                                            | 1317-36-8   |
|                                 | Diboron-trioxide                                         | 1303-86-2   |
| <b>Calculateur XMC</b>          | Lead-monoxide                                            | 1317-36-8   |
|                                 | Diboron-trioxide                                         | 1303-86-2   |
|                                 | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Caméra</b>                   | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                 | 2-Methylimidazole                                        | 693-98-1    |
|                                 | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                 | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                 | Lead-monoxide                                            | 1317-36-8   |
|                                 | Diboron-trioxide                                         | 1303-86-2   |
|                                 | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                 | Refractory ceramic fibres                                | 142844-00-6 |
|                                 | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Capteur D'Accélération</b>   | Diboron-trioxide                                         | 1303-86-2   |
| <b>Capteur De Pression</b>      | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                 | Lead-monoxide                                            | 1317-36-8   |
|                                 | 1,2-Dimethoxyethane                                      | 110-71-4    |
|                                 | 1,3-Propanesultone                                       | 1120-71-4   |
| <b>Capteur De Température</b>   | TBBA                                                     | 79-94-7     |
| <b>Chauffage</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                 | Lead-monoxide                                            | 1317-36-8   |
|                                 | Diboron-trioxide                                         | 1303-86-2   |
| <b>Climatiseur</b>              | Lead-monoxide                                            | 1317-36-8   |
| <b>Commodo</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                 | TBBA                                                     | 79-94-7     |
| <b>Commutateur A Touche</b>     | Lead-monoxide                                            | 1317-36-8   |
|                                 | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Commutateur D'Éclairage</b>  | Lead-monoxide                                            | 1317-36-8   |
| <b>Compresseur Frigorifique</b> | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                 | 2-Methylimidazole                                        | 693-98-1    |
|                                 | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                 | Lead-monoxide                                            | 1317-36-8   |
|                                 | Diboron-trioxide                                         | 1303-86-2   |
|                                 | Tris(nonylphenyl)phosphite                               | 26523-78-4  |
| <b>Contacteur</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                 | TBBA                                                     | 79-94-7     |
| <b>Convertisseur De Tension</b> | Melamine                                                 | 108-78-1    |
| <b>Convertisseur Ethernet</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                 | Lead-monoxide                                            | 1317-36-8   |
| <b>Couvercle De Prise</b>       | Bumetrizole                                              | 3896-11-5   |
| <b>Cylindre De Travail</b>      | Imidazolidine-2-thione                                   | 96-45-7     |
|                                 | Lead-monoxide                                            | 1317-36-8   |

|                               |                                                                                                                                              |             |
|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Diode                         | TBBA                                                                                                                                         | 79-94-7     |
| Disque Obturation             | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| Distributeur D'Énergie        | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                               | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                               | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
| Eclairage Interieur           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Écran                         | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Électrovanne                  | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
| Embout De Passage             | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| Essieu                        | Boric acid                                                                                                                                   | 10043-35-3  |
|                               | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                               | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                               | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                               | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                               | Tris(nonylphenyl)phosphite                                                                                                                   | 26523-78-4  |
|                               | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                                                             | 2451-62-9   |
|                               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                               | Chromium-trioxide                                                                                                                            | 1333-82-0   |
|                               | Hexahydromethylphthalic-anhydride                                                                                                            | 25550-51-0  |
|                               | Paraffin oils, chloro                                                                                                                        | 85422-92-0  |
|                               | TBBA                                                                                                                                         | 79-94-7     |
|                               | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                               | O,O,O-Triphenyl phosphorothioate                                                                                                             | 597-82-0    |
| Essieu Moteur                 | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                               | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                               | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                               | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                               | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                               | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                               | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                               | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                               | TBBA                                                                                                                                         | 79-94-7     |
|                               | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                               | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Évaporateur                   | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Faisceau De Câbles Électrique | Melamine                                                                                                                                     | 108-78-1    |

|                                    |                                                                            |            |
|------------------------------------|----------------------------------------------------------------------------|------------|
| Électrique                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Feu Arrière                        | Lead-monoxide                                                              | 1317-36-8  |
|                                    | TBBA                                                                       | 79-94-7    |
|                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Feu Lateral                        | TBBA                                                                       | 79-94-7    |
|                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Filet À Bagages                    | N,N-Dimethylacetamide                                                      | 127-19-5   |
| Flexible De Frein                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Gilet De Sécurité                  | Diboron-trioxide                                                           | 1303-86-2  |
| Glace Laterale                     | Diboron-trioxide                                                           | 1303-86-2  |
| Hayon                              | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Jeu De Cles                        | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| Joint                              | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Joint Profilé                      | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Joint Torique                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| Levier De Commande                 | Lead-monoxide                                                              | 1317-36-8  |
|                                    | Diboron-trioxide                                                           | 1303-86-2  |
| Modulateur D'Essieu                | Lead-monoxide                                                              | 1317-36-8  |
| Module De Batteries Haute Tension  | Lead-monoxide                                                              | 1317-36-8  |
|                                    | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| Moteur D'Essuie-Glace              | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                            | 25973-55-1 |
| Pédale D'Accélérateur              | Lead-monoxide                                                              | 1317-36-8  |
|                                    | TBBA                                                                       | 79-94-7    |
| Phare                              | Lead-monoxide                                                              | 1317-36-8  |
| Plafonnier                         | Triphenyl-phosphate                                                        | 115-86-6   |
| Pompe À Liquide De Refroidissement | Lead-monoxide                                                              | 1317-36-8  |
|                                    | Diboron-trioxide                                                           | 1303-86-2  |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Porte                              | Triphenyl-phosphate                                                        | 115-86-6   |
| Porte Latérale                     | Triphenyl-phosphate                                                        | 115-86-6   |
| Raccord Filete                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Retroviseur                        | 2-Methylimidazole                                                          | 693-98-1   |
|                                    | Lead-monoxide                                                              | 1317-36-8  |
|                                    | Diboron-trioxide                                                           | 1303-86-2  |
| Rétroviseur Ext                    | TBBA                                                                       | 79-94-7    |
|                                    | Triphenyl-phosphate                                                        | 115-86-6   |
| Serrure De Porte                   | Triphenyl-phosphate                                                        | 115-86-6   |
| Siège À Côté Du Conducteur         | C,C'-azodi(formamide)                                                      | 123-77-3   |
|                                    | Melamine                                                                   | 108-78-1   |
|                                    | Triphenyl-phosphate                                                        | 115-86-6   |
| Siège Conducteur                   | 4,4'-Isopropylidenediphenol                                                | 80-05-7    |
|                                    | Triphenyl-phosphate                                                        | 115-86-6   |
| Siege Suspendu                     | Triphenyl-phosphate                                                        | 115-86-6   |

|                                           |                                              |           |
|-------------------------------------------|----------------------------------------------|-----------|
| <b>Soufflet De Suspension</b>             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol | 119-47-1  |
| <b>Temoin De Controle</b>                 | TBBA                                         | 79-94-7   |
|                                           | Melamine                                     | 108-78-1  |
| <b>Transmetteur De Valeur De Freinage</b> | Lead-monoxide                                | 1317-36-8 |
|                                           | Diboron-trioxide                             | 1303-86-2 |
| <b>Unite De Commande</b>                  | Lead-monoxide                                | 1317-36-8 |
|                                           | TBBA                                         | 79-94-7   |
| <b>Unité Raccordement Multimédia</b>      | Lead-monoxide                                | 1317-36-8 |
|                                           | Diboron-trioxide                             | 1303-86-2 |
| <b>Ventilateur</b>                        | TBBA                                         | 79-94-7   |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3   |
| <b>Vistêtehexagonale</b>                  | Diboron-trioxide                             | 1303-86-2 |
| <b>Visttebbéesixpans</b>                  | Diboron-trioxide                             | 1303-86-2 |
| <b>Volant De Direction</b>                | Lead-monoxide                                | 1317-36-8 |

Sehr geehrte Kundin, sehr geehrter Kunde,

die zum 01. Juni 2007 in Kraft getretene Chemikalien-Verordnung (EG) Nr. 1907/2006 (REACH - Registrierung, Bewertung, Zulassung und Beschränkung von Chemikalien) hat sich zum Ziel gesetzt, den Schutz der menschlichen Gesundheit und der Umwelt vor möglichen Risiken auf Grund von Chemikalien zu gewährleisten.

Die Daimler Truck AG unterstützt die Ziele von REACH. Artikel 33 in der Gesetzgebung sieht vor, Sie als Kunden über besonders besorgniserregende Stoffe (SVHC) in unseren Produkten zu informieren. Ziel dieser Vorgabe ist es, den sicheren Umgang mit den definierten Stoffen über den gesamten Lebenszyklus des Produktes hinweg zu gewährleisten.

Auf Grundlage der gesetzlichen Vorgaben und unter Berücksichtigung der Angaben der Lieferanten der Daimler Truck AG wurden folgende Stoffe identifiziert, die sich zu mehr als 0,1 Gewichtsprozent in einzelnen Erzeugnissen dieses Fahrzeuges befinden können. Bei bestimmungsgemäßer Verwendung des Fahrzeugs besteht keine Gefährdung von Mensch und Umwelt. Weitere Informationen zum sicheren Gebrauch Ihres Fahrzeuges finden Sie in Ihrer Betriebsanleitung.

Bitte beachten Sie, dass zusätzlich der Stoff Blei (CAS-Nr. 7439-92-1) in der Starterbatterie, in Legierungen, Beschichtungen, Glas-/Keramik-/Elastomer-Bauteilen sowie diversen Elektronikbauteilen (v.a. Lote) enthalten ist.

| Produktgruppe      | Substanzname                                                                                      | CAS Nr.    |
|--------------------|---------------------------------------------------------------------------------------------------|------------|
| Achse              | Boric acid                                                                                        | 10043-35-3 |
|                    | Imidazolidine-2-thione                                                                            | 96-45-7    |
|                    | Octamethylcyclotetrasiloxane                                                                      | 556-67-2   |
|                    | 2-Methylimidazole                                                                                 | 693-98-1   |
|                    | Decamethylcyclopentasiloxane                                                                      | 541-02-6   |
|                    | Lead-monoxide                                                                                     | 1317-36-8  |
|                    | Diboron-trioxide                                                                                  | 1303-86-2  |
|                    | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4 |
|                    | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                  | 2451-62-9  |
|                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1   |
|                    | Chromium-trioxide                                                                                 | 1333-82-0  |
|                    | Hexahydromethylphthalic-anhydride                                                                 | 25550-51-0 |
|                    | Paraffin oils, chloro                                                                             | 85422-92-0 |
|                    | TBBA                                                                                              | 79-94-7    |
|                    | Phenol, methylstyrenated                                                                          | 68512-30-1 |
|                    | Triphenyl-phosphate                                                                               | 115-86-6   |
|                    | O,O,O-Triphenyl phosphorothioate                                                                  | 597-82-0   |
| Achsmodulator      | Lead-monoxide                                                                                     | 1317-36-8  |
| Antennenverstärker | Lead-monoxide                                                                                     | 1317-36-8  |
|                    | Diboron-trioxide                                                                                  | 1303-86-2  |
| Antriebsachse      | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9 |
|                    | N,N-Dimethylacetamide                                                                             | 127-19-5   |
|                    | Octamethylcyclotetrasiloxane                                                                      | 556-67-2   |
|                    | 2-Methylimidazole                                                                                 | 693-98-1   |
|                    | Decamethylcyclopentasiloxane                                                                      | 541-02-6   |
|                    | Lead-monoxide                                                                                     | 1317-36-8  |
|                    | Diboron-trioxide                                                                                  | 1303-86-2  |
|                    | 4-Nonylphenol, branched                                                                           | 84852-15-3 |
|                    | Nonylphenol                                                                                       | 25154-52-3 |
|                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1   |
|                    | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6   |
|                    | TBBA                                                                                              | 79-94-7    |

|                           |                                                                              |             |
|---------------------------|------------------------------------------------------------------------------|-------------|
| Antriebsachse             | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S- | 255881-94-8 |
|                           | [3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters             |             |
|                           | Phenol, methylstyrenated                                                     | 68512-30-1  |
| Arbeitszylinder           | Triphenyl-phosphate                                                          | 115-86-6    |
|                           | Imidazolidine-2-thione                                                       | 96-45-7     |
|                           | Lead-monoxide                                                                | 1317-36-8   |
| Bedieneinheit             | Lead-monoxide                                                                | 1317-36-8   |
| Bedienfeld                | Lead-monoxide                                                                | 1317-36-8   |
|                           | TBBA                                                                         | 79-94-7     |
| Bediengerät               | Lead-monoxide                                                                | 1317-36-8   |
|                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                  | 3147-75-9   |
| Bedienhebel               | Lead-monoxide                                                                | 1317-36-8   |
|                           | Diboron-trioxide                                                             | 1303-86-2   |
| Beschleunigungs-sensor    | Diboron-trioxide                                                             | 1303-86-2   |
| Bildschirm                | 2-Methylimidazole                                                            | 693-98-1    |
|                           | Lead-monoxide                                                                | 1317-36-8   |
|                           | Diboron-trioxide                                                             | 1303-86-2   |
| Bordnetzbatterie          | Lead-monoxide                                                                | 1317-36-8   |
|                           | Diboron-trioxide                                                             | 1303-86-2   |
|                           | Lead(II,IV)-oxide                                                            | 1314-41-6   |
| Bremschlauch              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                 | 119-47-1    |
|                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                     | 80-43-3     |
| Bremswertgeber            | Lead-monoxide                                                                | 1317-36-8   |
|                           | Diboron-trioxide                                                             | 1303-86-2   |
| Deckenleuchte             | Triphenyl-phosphate                                                          | 115-86-6    |
| Dichtung                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                                     | 80-43-3     |
| Diode                     | TBBA                                                                         | 79-94-7     |
| Drucksensor               | Lead titanium zirconium oxide                                                | 12626-81-2  |
|                           | Lead-monoxide                                                                | 1317-36-8   |
|                           | 1,2-Dimethoxyethane                                                          | 110-71-4    |
|                           | 1,3-Propanesultone                                                           | 1120-71-4   |
| Drucktaster               | Octamethylcyclotetrasiloxane                                                 | 556-67-2    |
|                           | Decamethylcyclopentasiloxane                                                 | 541-02-6    |
|                           | Lead-monoxide                                                                | 1317-36-8   |
|                           | Dodecamethylcyclohexasiloxane                                                | 540-97-6    |
| Durchführungsstülle       | Imidazolidine-2-thione                                                       | 96-45-7     |
| Einschraubstutzen         | Bis(alpha,alpha-dimethylbenzyl) peroxide                                     | 80-43-3     |
| Elektrischer Leitungssatz | Melamine                                                                     | 108-78-1    |
|                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                     | 80-43-3     |
| Energieverteiler          | Octamethylcyclotetrasiloxane                                                 | 556-67-2    |
|                           | Decamethylcyclopentasiloxane                                                 | 541-02-6    |
|                           | Dodecamethylcyclohexasiloxane                                                | 540-97-6    |
| Ethernet-Wandler          | Lead-titanium-trioxide                                                       | 12060-00-3  |
|                           | Lead-monoxide                                                                | 1317-36-8   |
| Fahrernebensitz           | C,C'-azodi(formamide)                                                        | 123-77-3    |
|                           | Melamine                                                                     | 108-78-1    |
|                           | Triphenyl-phosphate                                                          | 115-86-6    |
| Fahrsitz                  | 4,4'-Isopropylidenediphenol                                                  | 80-05-7     |
|                           | Triphenyl-phosphate                                                          | 115-86-6    |

|                                 |                                                                            |             |
|---------------------------------|----------------------------------------------------------------------------|-------------|
| Fahrpedal                       | Lead-monoxide                                                              | 1317-36-8   |
|                                 | TBBA                                                                       | 79-94-7     |
| Federbalg                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1    |
| Filzstreifen                    | Disodium-octaborate                                                        | 12008-41-2  |
| Gepäcknetz                      | N,N-Dimethylacetamide                                                      | 127-19-5    |
| Glühlampe                       | Diboron-trioxide                                                           | 1303-86-2   |
| Heizung                         | Lead-titanium-trioxide                                                     | 12060-00-3  |
|                                 | Lead-monoxide                                                              | 1317-36-8   |
|                                 | Diboron-trioxide                                                           | 1303-86-2   |
|                                 |                                                                            |             |
| Hochvoltbatterie-Modul          | Lead-monoxide                                                              | 1317-36-8   |
|                                 |                                                                            |             |
| Innenleuchte                    | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3  |
|                                 | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
| Kältemittel-<br>verdichter      | 4,4'-Isopropylidenediphenol                                                | 80-05-7     |
|                                 | 2-Methylimidazole                                                          | 693-98-1    |
|                                 | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                                 | Lead-monoxide                                                              | 1317-36-8   |
|                                 | Diboron-trioxide                                                           | 1303-86-2   |
|                                 | Tris(nonylphenyl)phosphite                                                 | 26523-78-4  |
| Kamera                          | Octamethylcyclotetrasiloxane                                               | 556-67-2    |
|                                 | 2-Methylimidazole                                                          | 693-98-1    |
|                                 | Decamethylcyclopentasiloxane                                               | 541-02-6    |
|                                 | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                                 | Lead-monoxide                                                              | 1317-36-8   |
|                                 | Diboron-trioxide                                                           | 1303-86-2   |
|                                 | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
|                                 | Refractory ceramic fibres                                                  | 142844-00-6 |
|                                 | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                            | 75980-60-8  |
| Klappe                          | C,C'-azodi(formamide)                                                      | 123-77-3    |
| Klimaanlage                     | Lead-monoxide                                                              | 1317-36-8   |
| Kontrollleuchte                 | TBBA                                                                       | 79-94-7     |
|                                 | Melamine                                                                   | 108-78-1    |
| Kotflügel                       | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
| Kühlerverschluss-<br>deckel     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Kühlmittelpumpe                 | Lead-monoxide                                                              | 1317-36-8   |
|                                 | Diboron-trioxide                                                           | 1303-86-2   |
|                                 | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Lenkrad                         | Lead-monoxide                                                              | 1317-36-8   |
| Lenkstockschalter               | Lead-monoxide                                                              | 1317-36-8   |
|                                 | TBBA                                                                       | 79-94-7     |
| Lichtschalter                   | Lead-monoxide                                                              | 1317-36-8   |
| Lüfter                          | TBBA                                                                       | 79-94-7     |
|                                 | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Magnetventil                    | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
| Markierungsleuchte              | TBBA                                                                       | 79-94-7     |
|                                 | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
|                                 |                                                                            |             |
| Multimedia-<br>Anschlusseinheit | Lead-monoxide                                                              | 1317-36-8   |
|                                 | Diboron-trioxide                                                           | 1303-86-2   |

|                                                 |                                                             |            |
|-------------------------------------------------|-------------------------------------------------------------|------------|
| O-Ring                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| Profildichtung                                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| Reifendruckantenne                              | Lead titanium zirconium oxide                               | 12626-81-2 |
| Scheinwerfer                                    | Lead-monoxide                                               | 1317-36-8  |
| Schlüsselsatz                                   | 1,2-Dimethoxyethane                                         | 110-71-4   |
| Schlussleuchte                                  | Lead-monoxide                                               | 1317-36-8  |
|                                                 | TBBA                                                        | 79-94-7    |
|                                                 | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Schwingsitz                                     | Triphenyl-phosphate                                         | 115-86-6   |
| Sechskantschraube                               | Diboron-trioxide                                            | 1303-86-2  |
| Sechsrundschrabe                                | Diboron-trioxide                                            | 1303-86-2  |
| Seitenscheibe                                   | Diboron-trioxide                                            | 1303-86-2  |
| Seitentür                                       | Triphenyl-phosphate                                         | 115-86-6   |
| Spannungswandler                                | Melamine                                                    | 108-78-1   |
| Spiegel                                         | 2-Methylimidazole                                           | 693-98-1   |
|                                                 | Lead-monoxide                                               | 1317-36-8  |
|                                                 | Diboron-trioxide                                            | 1303-86-2  |
| Spiegel Au                                      | TBBA                                                        | 79-94-7    |
|                                                 | Triphenyl-phosphate                                         | 115-86-6   |
| Steckdosendeckel                                | Bumetrizole                                                 | 3896-11-5  |
| Steuergerät                                     |                                                             |            |
| Abstandssensor                                  | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                                 | Lead-monoxide                                               | 1317-36-8  |
|                                                 | Diboron-trioxide                                            | 1303-86-2  |
|                                                 | TBBA                                                        | 79-94-7    |
| Steuergerät Airbag                              | Lead-monoxide                                               | 1317-36-8  |
|                                                 | Diboron-trioxide                                            | 1303-86-2  |
|                                                 | TBBA                                                        | 79-94-7    |
| Steuergerät Air-Processing Unit                 | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                                 | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                                 | Lead-monoxide                                               | 1317-36-8  |
|                                                 | Diboron-trioxide                                            | 1303-86-2  |
| Steuergerät Batterie-managementsystem           | Lead-monoxide                                               | 1317-36-8  |
| Steuergerät Dc/Dc-Wandler Niedervolt 1          | N,N-Dimethylacetamide                                       | 127-19-5   |
|                                                 | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                                 | Lead-monoxide                                               | 1317-36-8  |
|                                                 | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
|                                                 | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
|                                                 | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
| Steuergerät Display                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                                 | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                                 | Lead-monoxide                                               | 1317-36-8  |
|                                                 | Diboron-trioxide                                            | 1303-86-2  |
|                                                 | 1-Propanol, 2,3-dibromo-                                    | 96-13-9    |
| Steuergerät Edrive Common Powertrain Controller | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                                 | Lead-monoxide                                               | 1317-36-8  |

|                                                              |                                                                                                           |                                                    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------|
| <b>Common Powertrain</b>                                     | Diboron-trioxide<br>TBBA<br>2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone                            | 1303-86-2<br>79-94-7<br>119313-12-1                |
| <b>Steuergerät<br/>Elektronisches<br/>Zündschloss</b>        | Lead-titanium-trioxide<br>Lead-monoxide                                                                   | 12060-00-3<br>1317-36-8                            |
| <b>Steuergerät Gelenkte<br/>Zusatzachse</b>                  | Lead-monoxide<br>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol<br>Bis(alpha,alpha-dimethylbenzyl) peroxide | 1317-36-8<br>119-47-1<br>80-43-3                   |
| <b>Steuergerät<br/>Getriebesteuerung</b>                     | Lead-monoxide<br>Diboron-trioxide                                                                         | 1317-36-8<br>1303-86-2                             |
| <b>Steuergerät<br/>Klimaautomatik</b>                        | Lead-titanium-trioxide<br>Lead-monoxide                                                                   | 12060-00-3<br>1317-36-8                            |
| <b>Steuergerät<br/>Kombiinstrument</b>                       | 4,4'-Isopropylidenediphenol<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                  | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7       |
| <b>Steuergerät<br/>Ladesteuerung</b>                         | Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                 | 1317-36-8<br>1303-86-2<br>79-94-7                  |
| <b>Steuergerät<br/>Lenkwinkelsensor</b>                      | Lead-monoxide<br>Diboron-trioxide                                                                         | 1317-36-8<br>1303-86-2                             |
| <b>Steuergerät Multi-<br/>funktionskamera</b>                | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Pitch, coal tar, high-temp.                | 12060-00-3<br>1317-36-8<br>1303-86-2<br>65996-93-2 |
| <b>Steuergerät<br/>Nahbereichsradar</b>                      | Lead-monoxide                                                                                             | 1317-36-8                                          |
| <b>Steuergerät<br/>Niveauregelung</b>                        | Lead-monoxide                                                                                             | 1317-36-8                                          |
| <b>Steuergerät Regen-<br/>Lichtsensorm</b>                   | Lead-monoxide                                                                                             | 1317-36-8                                          |
| <b>Steuergerät<br/>Reifendruckkontrolle</b>                  | Lead-monoxide                                                                                             | 1317-36-8                                          |
| <b>Steuergerät<br/>Signalerfass- u<br/>Ansteuermodul Fhs</b> | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                               | 12060-00-3<br>1317-36-8<br>1303-86-2               |
| <b>Steuergerät Tachograf</b>                                 | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide                                  | 12626-81-2<br>12060-00-3<br>1317-36-8              |

|                              |                                                          |            |
|------------------------------|----------------------------------------------------------|------------|
| <b>Steuergerät Tachograf</b> | Diboron-trioxide                                         | 1303-86-2  |
|                              | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                              | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Steuergerät</b>           |                                                          |            |
| <b>Telematikplattform</b>    | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                              | Lead-titanium-trioxide                                   | 12060-00-3 |
|                              | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Steuergerät Türmodul</b>  |                                                          |            |
| <b>Beifahrer</b>             | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Steuergerät Türmodul</b>  |                                                          |            |
| <b>Fahrer</b>                | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Steuergerät Umrichter</b> |                                                          |            |
|                              | 2-Methylimidazole                                        | 693-98-1   |
|                              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                              | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
|                              | TBBA                                                     | 79-94-7    |
| <b>Steuergerät Video</b>     |                                                          |            |
| <b>Radar Decision Unit</b>   | Lead-titanium-trioxide                                   | 12060-00-3 |
|                              | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Steuergerät XMC</b>       | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
|                              | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |
| <b>Steuergerät Zentrales</b> |                                                          |            |
| <b>Gateway</b>               | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Tastenschalter</b>        | Lead-monoxide                                            | 1317-36-8  |
|                              | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Temperatursensor</b>      | TBBA                                                     | 79-94-7    |
| <b>Tür</b>                   | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Türschloss</b>            | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Verdampfer</b>            | Lead-monoxide                                            | 1317-36-8  |
|                              | Diboron-trioxide                                         | 1303-86-2  |
| <b>Verschluss-</b>           |                                                          |            |
| <b>scheibe</b>               | Imidazolidine-2-thione                                   | 96-45-7    |
| <b>Verschlussstopfen</b>     | Bumetrizole                                              | 3896-11-5  |
| <b>Warnweste</b>             | Diboron-trioxide                                         | 1303-86-2  |
| <b>Wippschalter</b>          | Lead-monoxide                                            | 1317-36-8  |
|                              | TBBA                                                     | 79-94-7    |
| <b>Wischermotor</b>          | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol          | 25973-55-1 |

Αγαπητή πελάτισσα, αγαπητέ πελάτη,

ο νόμος που αφορά στον Κανονισμό της Ευρωπαϊκής Επιτροπής (ΕΕ) αρ. 1907/2006 (REACH – για την καταχώριση, την αξιολόγηση, την αδειοδότηση και τους περιορισμούς των χημικών προϊόντων), έχει ως στόχο την προστασία της ανθρώπινης υγείας και του περιβάλλοντος από πιθανούς κινδύνους λόγω των χημικών προϊόντων.

Η Daimler Truck AG υποστηρίζει τους στόχους του REACH. Το άρθρο 33 του νόμου προβλέπει την ενημέρωσή σας ως πελάτες για τις ουσίες στα προϊόντα μας που προκαλούν πολύ μεγάλη ανησυχία. Στόχος αυτής της οδηγίας είναι η διασφάλιση του ασφαλούς χειρισμού των συγκεκριμένων ουσιών σε όλη τη διάρκεια ζωής του προϊόντος.

Βάσει αυτών των νομοθετικών απαιτήσεων και λαμβάνοντας υπόψη τις οδηγίες των προμηθευτών της Daimler Truck AG, ταυτοποιήθηκαν οι παρακάτω ουσίες που ενδέχεται να βρίσκονται σε μεμονωμένα εξαρτήματα αυτού του οχήματος σε ποσοστό πάνω από 0,1 τοις εκατό του βάρους. Κατά την κανονική χρήση του οχήματος δεν προκύπτει κανένας κίνδυνος για τον άνθρωπο και το περιβάλλον. Περισσότερες πληροφορίες για την ασφαλή χρήση του οχήματός σας θα βρείτε στις Οδηγίες Χρήσης σας.

Παρακαλούμε λάβετε υπόψη, ότι η ουσία του μολύβδου (αρ. CAS 7439-92-1) εμπεριέχεται επίσης στην μπαταρία μίζας, σε κράματα, επιστρώσεις, γυάλινα/κεραμικά/ελαστομερή εξαρτήματα, καθώς και διάφορα ηλεκτρονικά εξαρτήματα (κυρίως συγκολλητικά κράματα).

| Ομάδα προϊόντων            | Το όνομά της ουσίας                                              | Αρ. CAS    |
|----------------------------|------------------------------------------------------------------|------------|
| Αισθητήρας<br>Επιτάχυνσης  | Diboron-trioxide                                                 | 1303-86-2  |
| Αισθητήρας<br>Θερμοκρασίας | TBBA                                                             | 79-94-7    |
| Αισθητήρας Πίεσης          | Lead titanium zirconium oxide                                    | 12626-81-2 |
|                            | Lead-monoxide                                                    | 1317-36-8  |
|                            | 1,2-Dimethoxyethane                                              | 110-71-4   |
|                            | 1,3-Propanesultone                                               | 1120-71-4  |
| Αναρτώμενο Κάθισμα         | Triphenyl-phosphate                                              | 115-86-6   |
| Ανεμιστήρας                | TBBA                                                             | 79-94-7    |
|                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Αντλία Ψυκτικού<br>Υγρού   | Lead-monoxide                                                    | 1317-36-8  |
|                            | Diboron-trioxide                                                 | 1303-86-2  |
|                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Άξονας                     | Boric acid                                                       | 10043-35-3 |
|                            | Imidazolidine-2-thione                                           | 96-45-7    |
|                            | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                            | 2-Methylimidazole                                                | 693-98-1   |
|                            | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                            | Lead-monoxide                                                    | 1317-36-8  |
|                            | Diboron-trioxide                                                 | 1303-86-2  |
|                            | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                            | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                            | Chromium-trioxide                                                | 1333-82-0  |
|                            | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                            | Paraffin oils, chloro                                            | 85422-92-0 |
|                            | TBBA                                                             | 79-94-7    |
|                            | Phenol, methylstyrenated                                         | 68512-30-1 |
|                            | Triphenyl-phosphate                                              | 115-86-6   |

|                                                      |                                                    |             |
|------------------------------------------------------|----------------------------------------------------|-------------|
| <b>Άξονας</b>                                        | O,O,O-Triphenyl phosphorothioate                   | 597-82-0    |
| <b>Βίδα Torx</b>                                     | Diboron-trioxide                                   | 1303-86-2   |
| <b>Βιδωτό Στόμιο</b>                                 | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3     |
| <b>Δακτύλιος O</b>                                   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol       | 119-47-1    |
| <b>Διακόπτης</b>                                     | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Bis(alpha,alpha-dimethylbenzyl) peroxide           | 80-43-3     |
| <b>Διακόπτης Δύο Θέσεων</b>                          | Lead-monoxide                                      | 1317-36-8   |
|                                                      | TBBA                                               | 79-94-7     |
| <b>Διακόπτης Κολόνας Τιμονιού</b>                    | Lead-monoxide                                      | 1317-36-8   |
|                                                      | TBBA                                               | 79-94-7     |
| <b>Διακόπτης Φώτων</b>                               | Lead-monoxide                                      | 1317-36-8   |
| <b>Διαμορφωτής Πίεσης Φρένων Άξονα</b>               | Lead-monoxide                                      | 1317-36-8   |
| <b>Διανομέας Ενέργειας</b>                           | Octamethylcyclotetrasiloxane                       | 556-67-2    |
|                                                      | Decamethylcyclopentasiloxane                       | 541-02-6    |
|                                                      | Dodecamethylcyclohexasiloxane                      | 540-97-6    |
| <b>Δίοδος</b>                                        | TBBA                                               | 79-94-7     |
| <b>Δίχτυ Αποσκευών</b>                               | N,N-Dimethylacetamide                              | 127-19-5    |
| <b>Δότης Τιμής Πέδησης</b>                           | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Diboron-trioxide                                   | 1303-86-2   |
| <b>Εγκέφαλος Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                             | 12060-00-3  |
|                                                      | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Diboron-trioxide                                   | 1303-86-2   |
|                                                      | TBBA                                               | 79-94-7     |
|                                                      | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone | 119313-12-1 |
| <b>Εγκέφαλος Video Radar Decision Unit</b>           | Lead-titanium-trioxide                             | 12060-00-3  |
|                                                      | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Diboron-trioxide                                   | 1303-86-2   |
| <b>Εγκέφαλος XMC</b>                                 | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Diboron-trioxide                                   | 1303-86-2   |
|                                                      | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride | 19438-60-9  |
| <b>Εγκέφαλος Αερόσακου</b>                           | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Diboron-trioxide                                   | 1303-86-2   |
|                                                      | TBBA                                               | 79-94-7     |
| <b>Εγκέφαλος Αισθητήρα Απόστασης</b>                 | Lead-titanium-trioxide                             | 12060-00-3  |
|                                                      | Lead-monoxide                                      | 1317-36-8   |
|                                                      | Diboron-trioxide                                   | 1303-86-2   |
|                                                      | TBBA                                               | 79-94-7     |
| <b>Εγκέφαλος Αισθητήρα Βροχής-Φωτός</b>              | Lead-monoxide                                      | 1317-36-8   |

|                                                                  |                                                          |            |
|------------------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Εγκέφαλος Αισθητήρα<br/>Γωνίας Διεύθυνσης</b>                 | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος<br/>Αυτόματου<br/>Συστήματος<br/>Κλιματισμού</b>    | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                  | Lead-monoxide                                            | 1317-36-8  |
| <b>Εγκέφαλος<br/>Διευθυνόμενου<br/>Πρόσθετου Άξονα</b>           | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Εγκέφαλος Ελέγχου<br/>Φόρτισης</b>                            | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | Diboron-trioxide                                         | 1303-86-2  |
|                                                                  | TBBA                                                     | 79-94-7    |
| <b>Εγκέφαλος<br/>Ηλεκτρονικού<br/>Διακόπτη Μίζας</b>             | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                  | Lead-monoxide                                            | 1317-36-8  |
| <b>Εγκέφαλος Κάμερας<br/>Πολλαπλών<br/>Λειτουργιών</b>           | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                  | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | Diboron-trioxide                                         | 1303-86-2  |
|                                                                  | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <b>Εγκέφαλος Κεντρικής<br/>Πύλης</b>                             | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος<br/>Μετατροπέα</b>                                  | 2-Methylimidazole                                        | 693-98-1   |
|                                                                  | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                                  | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | Diboron-trioxide                                         | 1303-86-2  |
|                                                                  | TBBA                                                     | 79-94-7    |
| <b>Εγκέφαλος<br/>Μετατροπέα Dc/Dc<br/>Χαμηλής Τάσης 1</b>        | N,N-Dimethylacetamide                                    | 127-19-5   |
|                                                                  | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                                  | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                                  | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
|                                                                  | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
| <b>Εγκέφαλος Μον.<br/>Καταγρ. Σημ. Και<br/>Ενεργ. Πλ. Οδηγού</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                  | Lead-monoxide                                            | 1317-36-8  |
|                                                                  | Diboron-trioxide                                         | 1303-86-2  |

|                                                               |                                                          |            |
|---------------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Εγκέφαλος Μονάδας<br/>Επεξεργασίας Αέρα</b>                | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                               | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος Μονάδας<br/>Οθόνης</b>                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                               | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
|                                                               | 1-Propanol, 2,3-dibromo-                                 | 96-13-9    |
| <b>Εγκέφαλος Μονάδας<br/>Πόρτας Οδηγού</b>                    | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος Μονάδας<br/>Πόρτας Συνοδηγού</b>                 | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος Οργάνου<br/>Πολλαπλών Ενδείξεων</b>              | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                               | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
|                                                               | TBBA                                                     | 79-94-7    |
| <b>Εγκέφαλος<br/>Πλατφόρμας<br/>Τηλεματικής</b>               | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                               | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                               | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος Ραντάρ<br/>Μικρής Εμβέλειας</b>                  | Lead-monoxide                                            | 1317-36-8  |
| <b>Εγκέφαλος Ρύθμισης<br/>Ύψους Ανάρτησης</b>                 | Lead-monoxide                                            | 1317-36-8  |
| <b>Εγκέφαλος Συσ. Ελ.<br/>Κιβ. Ταχ.</b>                       | Lead-monoxide                                            | 1317-36-8  |
|                                                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Εγκέφαλος<br/>Συστήματος<br/>Διαχείρισης<br/>Μπαταρίας</b> | Lead-monoxide                                            | 1317-36-8  |
| <b>Εγκέφαλος<br/>Συστήματος Ελέγχου<br/>Πίεσης Ελαστικών</b>  | Lead-monoxide                                            | 1317-36-8  |
| <b>Εγκέφαλος<br/>Ταχογράφου</b>                               | Lead titanium zirconium oxide                            | 12626-81-2 |

|                          |                                                                                                   |             |
|--------------------------|---------------------------------------------------------------------------------------------------|-------------|
| Ταχογράφοι               | Lead-titanium-trioxide                                                                            | 12060-00-3  |
|                          | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
|                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                   | 75980-60-8  |
|                          | Triphenyl-phosphate                                                                               | 115-86-6    |
| Ενδεικτική Λυχνία        | TBBA                                                                                              | 79-94-7     |
|                          | Melamine                                                                                          | 108-78-1    |
| Ενισχυτής Κεραίας        | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
| Εξαγωνική Βίδα           | Diboron-trioxide                                                                                  | 1303-86-2   |
| Εξατμιστής               | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
| Εύκαμπτος Σωλήνας Φρένων | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1    |
|                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3     |
| Ηλεκτρομαγνητική Βαλβίδα | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6    |
| Θέρμανση                 | Lead-titanium-trioxide                                                                            | 12060-00-3  |
|                          | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
| Κάθισμα Οδηγού           | 4,4'-Isopropylidenediphenol                                                                       | 80-05-7     |
|                          | Triphenyl-phosphate                                                                               | 115-86-6    |
| Καθρέφτης                | 2-Methylimidazole                                                                                 | 693-98-1    |
|                          | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
| Καθρέφτης Αλουμινίου     | TBBA                                                                                              | 79-94-7     |
|                          | Triphenyl-phosphate                                                                               | 115-86-6    |
|                          | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
| Κάμερα                   | 2-Methylimidazole                                                                                 | 693-98-1    |
|                          | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5  |
|                          | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
|                          | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6    |
|                          | Refractory ceramic fibres                                                                         | 142844-00-6 |
|                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                   | 75980-60-8  |
|                          |                                                                                                   |             |
| Καπάκι Ασφαλείας Ψυγείου | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3     |
| Καπάκι Πρίζας            | Bumetrizole                                                                                       | 3896-11-5   |
| Κεραία Πίεσης Ελαστικών  | Lead titanium zirconium oxide                                                                     | 12626-81-2  |
| Κινητήριος Άξονας        | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9  |
|                          | N,N-Dimethylacetamide                                                                             | 127-19-5    |
|                          | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                          | 2-Methylimidazole                                                                                 | 693-98-1    |
|                          | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                          | Lead-monoxide                                                                                     | 1317-36-8   |
|                          | Diboron-trioxide                                                                                  | 1303-86-2   |
|                          | 4-Nonylphenol, branched                                                                           | 84852-15-3  |

|                                                |                                                                                                                                              |             |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Κινητήριος Άξονας</b>                       | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                | TBBA                                                                                                                                         | 79-94-7     |
|                                                | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                                | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Κλαπέτο</b>                                 | C,C'-azodi(formamide)                                                                                                                        | 123-77-3    |
| <b>Κλειδαριά Πόρτας</b>                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                |                                                                                                                                              |             |
| <b>Κύλινδρος Εργασίας</b>                      | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Λαμπτήρας</b>                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                |                                                                                                                                              |             |
| <b>Μετατροπέας Ethernet</b>                    | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                |                                                                                                                                              |             |
| <b>Μετατροπέας Τάσης</b>                       | Melamine                                                                                                                                     | 108-78-1    |
|                                                |                                                                                                                                              |             |
| <b>Μονάδα Μπαταρίας Υψηλής Τάσης</b>           | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                                                                   | 29420-49-3  |
| <b>Μονάδα Συνδέσεων Πολυμέσων</b>              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Μονάδα Χειρισμού</b>                        | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                |                                                                                                                                              |             |
| <b>Μοτέρ Υαλοκαθαριστήρων</b>                  | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                                                                                              | 25973-55-1  |
| <b>Μοχλός Χειρισμού</b>                        | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                |                                                                                                                                              |             |
| <b>Μπαταρία Ηλεκτρικού Κυκλώματος Οχήματος</b> | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                | Lead(II,IV)-oxide                                                                                                                            | 1314-41-6   |
| <b>Οθόνη</b>                                   | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Πεδίο Χειρισμού</b>                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | TBBA                                                                                                                                         | 79-94-7     |
|                                                |                                                                                                                                              |             |
| <b>Πεντάλ Επιτάχυνσης</b>                      | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | TBBA                                                                                                                                         | 79-94-7     |
| <b>Πίσω Φως</b>                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                | TBBA                                                                                                                                         | 79-94-7     |
|                                                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Πλαϊνή Πόρτα</b>                            | Triphenyl-phosphate                                                                                                                          | 115-86-6    |

|                     |                                                             |            |
|---------------------|-------------------------------------------------------------|------------|
| Πλευρικό Τζάμι      | Diboron-trioxide                                            | 1303-86-2  |
| Πλήκτρο Πίεσης      | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                     | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                     | Lead-monoxide                                               | 1317-36-8  |
|                     | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| Πόρτα               | Triphenyl-phosphate                                         | 115-86-6   |
| Προβολείς           | Lead-monoxide                                               | 1317-36-8  |
| Προειδοποιητικό     |                                                             |            |
| Γιλέκο              | Diboron-trioxide                                            | 1303-86-2  |
| Πτυσσόμενο Συνοδού  | C,C'-azodi(formamide)                                       | 123-77-3   |
|                     | Melamine                                                    | 108-78-1   |
|                     | Triphenyl-phosphate                                         | 115-86-6   |
| Πώμα Ασφάλισης      | Bumetrizole                                                 | 3896-11-5  |
| Ροδέλα Ασφάλισης    | Imidazolidine-2-thione                                      | 96-45-7    |
| Ροδέλα Διέλευσης    |                                                             |            |
| Καλωδίων            | Imidazolidine-2-thione                                      | 96-45-7    |
| Σετ Ηλεκτρικών      |                                                             |            |
| Καλωδίων            | Melamine                                                    | 108-78-1   |
|                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Σετ Κλειδιών        | 1,2-Dimethoxyethane                                         | 110-71-4   |
| Στεγανοποίηση       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Στεγανοποίηση       |                                                             |            |
| Προφίλ              | C,C'-azodi(formamide)                                       | 123-77-3   |
| Συμπιεστής Ψυκτικού |                                                             |            |
| Μέσου               | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                     | 2-Methylimidazole                                           | 693-98-1   |
|                     | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                     | Lead-monoxide                                               | 1317-36-8  |
|                     | Diboron-trioxide                                            | 1303-86-2  |
|                     | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| Συσκευή Χειρισμού   | Lead-monoxide                                               | 1317-36-8  |
|                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Σύστημα Κλιματισμού | Lead-monoxide                                               | 1317-36-8  |
| Τιμόνι              | Lead-monoxide                                               | 1317-36-8  |
| Τσόχινη Λωρίδα      | Disodium-octaborate                                         | 12008-41-2 |
| Φτερό               | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Φυσούννα            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| Φως Όγκου           | TBBA                                                        | 79-94-7    |
|                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Φώτα Εσωτερικού     |                                                             |            |
| Χώρου               | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Φώτα Οροφής         | Triphenyl-phosphate                                         | 115-86-6   |

Tisztelt Ügyfelünk!

Az EU 2007. június 1-jén hatályba léptetett, vegyi anyagokra vonatkozó, 1907/2006/EK sz. törvényének (REACH - a vegyi anyagok regisztrálása, értékelése, engedélyezése és korlátozása) célja, hogy biztosítsa az emberi egészség és a környezet védelmét a vegyi anyagokból adódó lehetséges kockázatoktól.

A Daimler Truck AG támogatja a REACH céljait. A törvényhozás 33. cikke előírja, hogy Önt mint ügyfelünket a termékeinkben lévő, különös aggodalomra okot adó anyagokról (SVHC) tájékoztassuk. Ennek az előírásnak a célja, hogy biztosítsa a meghatározott anyagok biztonságos kezelését a termék egész életciklusa alatt.

A törvényi előírások alapján és a Daimler Truck AG szállítói által megadott adatok figyelembe vételével a következő olyan anyagokat azonosítottuk, amelyek több mint 0,1 tömegszázalékban fordulhatnak elő ennek a gépkocsinak az egyes gyártmányaiban. A gépkocsi rendeltetésszerű használata esetén nem áll fenn az ember és a környezet veszélyeztetése. További információkat talál gépkocsija biztonságos használatáról a Kezelési útmutatóban.

Ügyeljen arra, hogy kiegészítőleg ólom (CAS-sz. 7439-92-1) van az indítóakkumulátorban, az ötvözetekben, a bevonatokban, az üveg-/kerámia-/ elasztomer-alkatrészekben, valamint különböző elektronikus alkatrészekben (mindenekelőtt a forrasztanyagokban).

| Termékcsoporthat                        | Anyag neve                                               | CAS-szám   |
|-----------------------------------------|----------------------------------------------------------|------------|
| 1. Kisfeszültségű<br>Dc/Dc-Átalakító Ve | N,N-Dimethylacetamide                                    | 127-19-5   |
|                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                         | Lead-monoxide                                            | 1317-36-8  |
|                                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                         | Dodecamethylcyclhexasiloxane                             | 540-97-6   |
|                                         | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
| Ablaktörlőmotor                         | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol          | 25973-55-1 |
| Air-Processing Unit<br>Vezérlőegység    | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                         | Lead-monoxide                                            | 1317-36-8  |
|                                         | Diboron-trioxide                                         | 1303-86-2  |
| Ajto                                    | Triphenyl-phosphate                                      | 115-86-6   |
| Ajtózár                                 | Triphenyl-phosphate                                      | 115-86-6   |
| Akkumulátor-<br>menedzsment-Rendszer    |                                                          |            |
| Vezérlőegység                           | Lead-monoxide                                            | 1317-36-8  |
| Alakos Tömítés                          | C,C'-azodi(formamide)                                    | 123-77-3   |
| Antennaerősítő                          | Lead-monoxide                                            | 1317-36-8  |
|                                         | Diboron-trioxide                                         | 1303-86-2  |
| Átalakító Vezérlőegység                 | 2-Methylimidazole                                        | 693-98-1   |
|                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                         | Lead-monoxide                                            | 1317-36-8  |
|                                         | Diboron-trioxide                                         | 1303-86-2  |
|                                         | TBBA                                                     | 79-94-7    |
| Átvezetőhüvely                          | Imidazolidine-2-thione                                   | 96-45-7    |
| Automatikus<br>Klímaberendezés          |                                                          |            |
| Vezérlőegység                           | Lead-titanium-trioxide                                   | 12060-00-3 |

|                                     |                                                             |             |
|-------------------------------------|-------------------------------------------------------------|-------------|
| Klímbaberendezés                    | Lead-monoxide                                               | 1317-36-8   |
| Becsavarható Csőcsonk               | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Belso Vilagitas                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| Billenőkapcsoló                     | Lead-monoxide                                               | 1317-36-8   |
|                                     | TBBA                                                        | 79-94-7     |
| Common Powertrain Controller Edrive |                                                             |             |
| Vezérlőegység                       | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                     | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
|                                     | TBBA                                                        | 79-94-7     |
|                                     | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone          | 119313-12-1 |
| Csatlakozóalj-Fedél                 | Bumetrizole                                                 | 3896-11-5   |
| Csomagháló                          | N,N-Dimethylacetamide                                       | 127-19-5    |
| Dióda                               | TBBA                                                        | 79-94-7     |
| Elektromos Hálózat                  |                                                             |             |
| Akkumulátor                         | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
|                                     | Lead(II,IV)-oxide                                           | 1314-41-6   |
| Elektromos Vezetékköteg             | Melamine                                                    | 108-78-1    |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Elektronikus Gyűjtáskapcsoló        |                                                             |             |
| Vezérlőegység                       | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                     | Lead-monoxide                                               | 1317-36-8   |
| Ellenőrző Lámpa                     | TBBA                                                        | 79-94-7     |
|                                     | Melamine                                                    | 108-78-1    |
| Elpárologtató                       | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
| Energiaelosztó                      | Octamethylcyclotetrasiloxane                                | 556-67-2    |
|                                     | Decamethylcyclopentasiloxane                                | 541-02-6    |
|                                     | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
| Eső-/Fényszensor                    |                                                             |             |
| Vezérlőegység                       | Lead-monoxide                                               | 1317-36-8   |
| Ethernet-Átalakító                  | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                     | Lead-monoxide                                               | 1317-36-8   |
| Fedél                               | C,C'-azodi(formamide)                                       | 123-77-3    |
| Fékcső                              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Fékértékeladó                       | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
| Fényszóró                           | Lead-monoxide                                               | 1317-36-8   |
| Feszültségátalakító                 | Melamine                                                    | 108-78-1    |
| Figyelmeztető Mellény               | Diboron-trioxide                                            | 1303-86-2   |
| Filccsíkok                          | Disodium-octaborate                                         | 12008-41-2  |
| Fűtés                               | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                     | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
| Gázpedál                            | Lead-monoxide                                               | 1317-36-8   |

|                                          |                                                                                                                                                                                                                                                                                                                                                                                             |                                                                                                                                                     |
|------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Gázpedál</b>                          | TBBA                                                                                                                                                                                                                                                                                                                                                                                        | 79-94-7                                                                                                                                             |
| <b>Gumiabroncsnyomás-<br/>Antenna</b>    | Lead titanium zirconium oxide                                                                                                                                                                                                                                                                                                                                                               | 12626-81-2                                                                                                                                          |
| <b>Gumiabroncsnyomás-<br/>Ellenőrzés</b> |                                                                                                                                                                                                                                                                                                                                                                                             |                                                                                                                                                     |
| <b>Vezérlőegység</b>                     | Lead-monoxide                                                                                                                                                                                                                                                                                                                                                                               | 1317-36-8                                                                                                                                           |
| <b>Gyorsulásszenzor</b>                  | Diboron-trioxide                                                                                                                                                                                                                                                                                                                                                                            | 1303-86-2                                                                                                                                           |
| <b>Hajtott Tengely</b>                   | 1,6,7,8,9,14,15,16,17,17,18,18-<br>Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene<br>N,N-Dimethylacetamide<br>Octamethylcyclotetrasiloxane<br>2-Methylimidazole<br>Decamethylcyclopentasiloxane<br>Lead-monoxide<br>Diboron-trioxide<br>4-Nonylphenol, branched<br>Nonylphenol<br>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol<br>Dodecamethylcyclohexasiloxane<br>TBBA | 13560-89-9<br>127-19-5<br>556-67-2<br>693-98-1<br>541-02-6<br>1317-36-8<br>1303-86-2<br>84852-15-3<br>25154-52-3<br>119-47-1<br>540-97-6<br>79-94-7 |
|                                          | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-<br>[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters<br>Phenol, methylstyrenated<br>Triphenyl-phosphate                                                                                                                                                                                         | 255881-94-8<br>68512-30-1<br>115-86-6                                                                                                               |
| <b>Hatlapfejű Csavar</b>                 | Diboron-trioxide                                                                                                                                                                                                                                                                                                                                                                            | 1303-86-2                                                                                                                                           |
| <b>Hátsó Világítás</b>                   | Lead-monoxide<br>TBBA<br>2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                                                                                                                                                                                                                                        | 1317-36-8<br>79-94-7<br>3147-75-9                                                                                                                   |
| <b>Hőmérsékletszenzor</b>                | TBBA                                                                                                                                                                                                                                                                                                                                                                                        | 79-94-7                                                                                                                                             |
| <b>Hűtő Zárófedél</b>                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                                                                                                                                                                                                                                                                    | 80-43-3                                                                                                                                             |
| <b>Hűtőfolyadék-Szivattyú</b>            | Lead-monoxide<br>Diboron-trioxide<br>Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                                                                                                                                                                                                                               | 1317-36-8<br>1303-86-2<br>80-43-3                                                                                                                   |
| <b>Hűtőközeg-<br/>kompresszor</b>        | 4,4'-Isopropylidenediphenol<br>2-Methylimidazole<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-monoxide<br>Diboron-trioxide<br>Tris(nonylphenyl)phosphite                                                                                                                                                                                                             | 80-05-7<br>693-98-1<br>71868-10-5<br>1317-36-8<br>1303-86-2<br>26523-78-4                                                                           |
| <b>Izzó</b>                              | Diboron-trioxide                                                                                                                                                                                                                                                                                                                                                                            | 1303-86-2                                                                                                                                           |
| <b>Jelzővilágítás</b>                    | TBBA<br>2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                                                                                                                                                                                                                                                         | 79-94-7<br>3147-75-9                                                                                                                                |
| <b>Kamera</b>                            | Octamethylcyclotetrasiloxane<br>2-Methylimidazole<br>Decamethylcyclopentasiloxane<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-monoxide<br>Diboron-trioxide                                                                                                                                                                                                          | 556-67-2<br>693-98-1<br>541-02-6<br>71868-10-5<br>1317-36-8<br>1303-86-2                                                                            |

|                                         |                                                             |             |
|-----------------------------------------|-------------------------------------------------------------|-------------|
| Kamera                                  | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
|                                         | Refractory ceramic fibres                                   | 142844-00-6 |
|                                         | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
| Kapcsológomb                            | Lead-monoxide                                               | 1317-36-8   |
|                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Képernyő                                | 2-Methylimidazole                                           | 693-98-1    |
|                                         | Lead-monoxide                                               | 1317-36-8   |
|                                         | Diboron-trioxide                                            | 1303-86-2   |
| Kezeloegység                            | Lead-monoxide                                               | 1317-36-8   |
| Kezelokeszulek                          | Lead-monoxide                                               | 1317-36-8   |
|                                         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| Kezelőmező                              | Lead-monoxide                                               | 1317-36-8   |
|                                         | TBBA                                                        | 79-94-7     |
| Kijelző Vezérlőegység                   | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                         | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                         | Lead-monoxide                                               | 1317-36-8   |
|                                         | Diboron-trioxide                                            | 1303-86-2   |
|                                         | 1-Propanol, 2,3-dibromo-                                    | 96-13-9     |
| Kísérő Ajtómodul Vezérlőegység          | Lead-monoxide                                               | 1317-36-8   |
|                                         | Diboron-trioxide                                            | 1303-86-2   |
| Klímaberendezés                         | Lead-monoxide                                               | 1317-36-8   |
| Kombináltműszer Vezérlőegység           | 4,4'-Isopropylidenediphenol                                 | 80-05-7     |
|                                         | Lead-monoxide                                               | 1317-36-8   |
|                                         | Diboron-trioxide                                            | 1303-86-2   |
|                                         | TBBA                                                        | 79-94-7     |
|                                         | Lead-monoxide                                               | 1317-36-8   |
| Kormánykerék                            | Lead-monoxide                                               | 1317-36-8   |
| Kormányoszlop-kapcsoló                  | Lead-monoxide                                               | 1317-36-8   |
|                                         | TBBA                                                        | 79-94-7     |
| Kormányzott Segéd tengely Vezérlőegység | Lead-monoxide                                               | 1317-36-8   |
|                                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
|                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Közeli Tartomány Radar Vezérlőegység    | Lead-monoxide                                               | 1317-36-8   |
|                                         | Lead-monoxide                                               | 1317-36-8   |
| Központi Gateway Vezérlőegység          | Diboron-trioxide                                            | 1303-86-2   |
|                                         | Lead-monoxide                                               | 1317-36-8   |
| Kulcskészlet                            | 1,2-Dimethoxyethane                                         | 110-71-4    |
| Külső Visszapillantó Tükör              | TBBA                                                        | 79-94-7     |
|                                         | Triphenyl-phosphate                                         | 115-86-6    |
| Légrugó                                 | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
| Légzsák-Vezérlőegység                   | Lead-monoxide                                               | 1317-36-8   |
|                                         | Diboron-trioxide                                            | 1303-86-2   |
|                                         | TBBA                                                        | 79-94-7     |

|                                         |                                                                            |            |
|-----------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Lekerekített Élű</b>                 |                                                                            |            |
| <b>Hatlapfejű Csavar</b>                | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Lengőülés</b>                        | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Mágnesszelep</b>                     | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Mennyezetvilágítás</b>               | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Működtetőkar</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Multifunkciós Kamera</b>             |                                                                            |            |
| <b>Vezérlőegység</b>                    | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                         | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Diboron-trioxide                                                           | 1303-86-2  |
|                                         | Pitch, coal tar, high-temp.                                                | 65996-93-2 |
| <b>Multimédia-</b>                      |                                                                            |            |
| <b>Csatlakozóegység</b>                 | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Munkahenger</b>                      | Imidazolidine-2-thione                                                     | 96-45-7    |
|                                         | Lead-monoxide                                                              | 1317-36-8  |
| <b>Nagyfeszültségűakkumulátor-Modul</b> | Lead-monoxide                                                              | 1317-36-8  |
| <b>Nyomásszenzor</b>                    | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
|                                         | Lead titanium zirconium oxide                                              | 12626-81-2 |
|                                         | Lead-monoxide                                                              | 1317-36-8  |
|                                         | 1,2-Dimethoxyethane                                                        | 110-71-4   |
|                                         | 1,3-Propanesultone                                                         | 1120-71-4  |
| <b>Nyomókapcsoló</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                         | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                         | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>O Gyűrű</b>                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Oldalablak</b>                       | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Oldalajtó</b>                        | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Sárvédő</b>                          | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Sebességváltó-Vezérlés</b>           |                                                                            |            |
| <b>Vezérlőegység</b>                    | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Szintszabályozás</b>                 |                                                                            |            |
| <b>Vezérlőegység</b>                    | Lead-monoxide                                                              | 1317-36-8  |
| <b>Tachográf</b>                        |                                                                            |            |
| <b>Vezérlőegység</b>                    | Lead titanium zirconium oxide                                              | 12626-81-2 |
|                                         | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                         | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Diboron-trioxide                                                           | 1303-86-2  |
|                                         | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                            | 75980-60-8 |
|                                         | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Távolságszenzor</b>                  |                                                                            |            |
| <b>Vezérlőegység</b>                    | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                         | Lead-monoxide                                                              | 1317-36-8  |
|                                         | Diboron-trioxide                                                           | 1303-86-2  |
|                                         | TBBA                                                                       | 79-94-7    |

|                                                                     |                                                                  |            |
|---------------------------------------------------------------------|------------------------------------------------------------------|------------|
| <b>Telematikaplatform</b><br><b>Vezérlőegység</b>                   | 4,4'-Isopropylidenediphenol                                      | 80-05-7    |
|                                                                     | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one         | 71868-10-5 |
|                                                                     | Lead-titanium-trioxide                                           | 12060-00-3 |
|                                                                     | Lead-monoxide                                                    | 1317-36-8  |
|                                                                     | Diboron-trioxide                                                 | 1303-86-2  |
| <b>Tengely</b>                                                      | Boric acid                                                       | 10043-35-3 |
|                                                                     | Imidazolidine-2-thione                                           | 96-45-7    |
|                                                                     | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                                                                     | 2-Methylimidazole                                                | 693-98-1   |
|                                                                     | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                                                                     | Lead-monoxide                                                    | 1317-36-8  |
|                                                                     | Diboron-trioxide                                                 | 1303-86-2  |
|                                                                     | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                                                                     | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                                                                     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                                                                     | Chromium-trioxide                                                | 1333-82-0  |
|                                                                     | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                                                                     | Paraffin oils, chloro                                            | 85422-92-0 |
|                                                                     | TBBA                                                             | 79-94-7    |
|                                                                     | Phenol, methylstyrenated                                         | 68512-30-1 |
| <b>Tengelymodulátor</b>                                             | Triphenyl-phosphate                                              | 115-86-6   |
|                                                                     | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| <b>Töltésvezérlés</b><br><b>Vezérlőegység</b>                       | Lead-monoxide                                                    | 1317-36-8  |
|                                                                     | Diboron-trioxide                                                 | 1303-86-2  |
|                                                                     | TBBA                                                             | 79-94-7    |
|                                                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| <b>Tömítés</b>                                                      | TBBA                                                             | 79-94-7    |
| <b>Ventilátor</b>                                                   | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| <b>Vezérlőegység</b><br><b>Kormányzóghelyzet-</b><br><b>Szenzor</b> | Lead-monoxide                                                    | 1317-36-8  |
|                                                                     | Diboron-trioxide                                                 | 1303-86-2  |
| <b>Vezető Ajtómodul</b><br><b>Vezérlőegység</b>                     | Lead-monoxide                                                    | 1317-36-8  |
|                                                                     | Diboron-trioxide                                                 | 1303-86-2  |
| <b>Vezető Melletti Ülészék</b>                                      | C,C'-azodi(formamide)                                            | 123-77-3   |
|                                                                     | Melamine                                                         | 108-78-1   |
|                                                                     | Triphenyl-phosphate                                              | 115-86-6   |
| <b>Vezetőfülké Jelérzékelő- és Vezérlőmodul</b>                     | Lead-titanium-trioxide                                           | 12060-00-3 |
|                                                                     | Lead-monoxide                                                    | 1317-36-8  |
|                                                                     | Diboron-trioxide                                                 | 1303-86-2  |
| <b>Vezetőülés</b>                                                   | 4,4'-Isopropylidenediphenol                                      | 80-05-7    |
|                                                                     | Triphenyl-phosphate                                              | 115-86-6   |
| <b>Video Radar Decision</b><br><b>Unit Vezérlőegység</b>            | Lead-titanium-trioxide                                           | 12060-00-3 |
|                                                                     | Lead-monoxide                                                    | 1317-36-8  |

|                             |                                                    |            |
|-----------------------------|----------------------------------------------------|------------|
| <b>Unit Vezérlőegység</b>   | Diboron-trioxide                                   | 1303-86-2  |
| <b>Világításkapcsoló</b>    | Lead-monoxide                                      | 1317-36-8  |
| <b>Visszapillantó Tükör</b> | 2-Methylimidazole                                  | 693-98-1   |
|                             | Lead-monoxide                                      | 1317-36-8  |
|                             | Diboron-trioxide                                   | 1303-86-2  |
| <b>XMC Vezérlőegység</b>    | Lead-monoxide                                      | 1317-36-8  |
|                             | Diboron-trioxide                                   | 1303-86-2  |
|                             | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride | 19438-60-9 |
| <b>Záródugó</b>             | Bumetrizole                                        | 3896-11-5  |
| <b>Zárótárcsa</b>           | Imidazolidine-2-thione                             | 96-45-7    |

Ágæti viðskiptavinur,

Efnareglugerð Evrópusambandsins (EB) nr. 1907/2006 (REACH - um skráningu, mat, leyfisveitingu og takmarkanir, að því er varðar efni) sem tók gildi 1. júní 2007 hefur að markmiði að vernda heilsu manna og umhverfið gegn hugsanlegri hættu af völdum iðefna.

Daimler Truck AG styður markmið REACH-reglugerðarinnar. Í 33. grein reglugerðarinnar er kveðið á um að okkur sé skylt að veita viðskiptavinum upplýsingar um sérlega varasöm efni (SVHC) í vörum okkar. Markmiðið með þessu ákvæði er að tryggja örugga meðhöndlun tilgreindu efnanna meðan á líftíma vörunnar stendur.

Á grundvelli lagaákvæða og með hliðsjón af upplýsingum frá birgjum Daimler Truck AG hafa verið borin kennsl á eftirfarandi efni sem kunna að vera fyrir hendi í meiri styrk en sem nemur 0,1% massahlutfalli í tilteknum hlutum þessarar bifreiðar. Ef notkun bílsins er með fyrirhuguðum hætti stafar hvorki fólki né umhverfi hættu af henni. Frekari upplýsingar um örugga notkun bifreiðarinnar er að finna í notendahandbók hennar.

Vinsamlegast athugið að efnið blý (CAS-númer 7439-92-1) er einnig að finna í rafgeyminum, málmblöndum, húðun, íhlutum úrgleri, keramíki eða teygjuefnum sem og hinum ýmsu rafeindaíhlutum (einkum í lóðun).

| Product group           | Substance name                                                   | CAS no.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Brake Value Sensor      | Lead-monoxide                                                    | 1317-36-8  |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Brake Value Sensor</b>                      | Diboron-trioxide                                         | 1303-86-2   |
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Automatic Climate Control</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Central Gateway</b>            | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Electronic Ignition Lock</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Instrument Cluster</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit Rain-Light Sensor</b>          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Video Radar Decision Unit</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Air-Processing Unit</b>       | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                                     |             |
|---------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | <b>4,4'-Isopropylidenediphenol</b>                                                                                                                  | 80-05-7     |
|                                                         | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b>                                                                                     | 71868-10-5  |
|                                                         | <b>Lead-titanium-trioxide</b>                                                                                                                       | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
|                                                         | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | <b>Lead-titanium-trioxide</b>                                                                                                                       | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | <b>TBBA</b>                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | <b>1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene</b>                                            | 13560-89-9  |
|                                                         | <b>N,N-Dimethylacetamide</b>                                                                                                                        | 127-19-5    |
|                                                         | <b>Octamethylcyclotetrasiloxane</b>                                                                                                                 | 556-67-2    |
|                                                         | <b>2-Methylimidazole</b>                                                                                                                            | 693-98-1    |
|                                                         | <b>Decamethylcyclopentasiloxane</b>                                                                                                                 | 541-02-6    |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
|                                                         | <b>4-Nonylphenol, branched</b>                                                                                                                      | 84852-15-3  |
|                                                         | <b>Nonylphenol</b>                                                                                                                                  | 25154-52-3  |
|                                                         | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>                                                                                                 | 119-47-1    |
|                                                         | <b>Dodecamethylcyclohexasiloxane</b>                                                                                                                | 540-97-6    |
|                                                         | <b>TBBA</b>                                                                                                                                         | 79-94-7     |
|                                                         | <b>Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters</b> | 255881-94-8 |
|                                                         | <b>Phenol, methylstyrenated</b>                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
|                                                         | <b>4,4'-Isopropylidenediphenol</b>                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
|                                                         | <b>Melamine</b>                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                  |                                                 |            |
|------------------|-------------------------------------------------|------------|
| Wiper Motor      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol | 25973-55-1 |
| Working Cylinder | Imidazolidine-2-thione                          | 96-45-7    |
|                  | Lead-monoxide                                   | 1317-36-8  |

Gentile Cliente,

la legge entrata in vigore il 1° giugno 2007 in applicazione del Regolamento dell'Unione Europea sulle sostanze chimiche (CE) n. 1907/2006, (REACH - registrazione, valutazione, autorizzazione e restrizione delle sostanze chimiche), ha lo scopo di garantire la tutela della salute delle persone e dell'ambiente dai possibili rischi derivanti dalle sostanze chimiche.

Daimler Truck AG sostiene gli obiettivi del REACH. L'articolo 33 della norma prevede che i Clienti siano informati della presenza di sostanze estremamente preoccupanti (SVHC) nei nostri prodotti. L'obiettivo di questa disposizione è garantire un uso sicuro di tali sostanze nell'arco dell'intero ciclo di vita del prodotto.

Sulla base delle norme di legge e in considerazione dei dati rilasciati dai fornitori di Daimler Truck AG sono state identificate le seguenti sostanze che possono essere presenti in singoli componenti di questo veicolo con una concentrazione superiore allo 0,1% del peso. Se il veicolo viene utilizzato in normali condizioni di impiego, per le persone e l'ambiente non sussiste alcun pericolo. Ulteriori informazioni per un utilizzo sicuro della vettura sono disponibili nelle relative Istruzioni d'uso.

Si fa notare che nella batteria di avviamento, in leghe, in rivestimenti, in componenti di vetro/ceramica/elastomero e in diversi componenti elettronici (soprattutto piombature) è contenuta anche la sostanza piombo (n. CAS 7439-92-1).

| Gruppo di prodotti                        | Nome della sostanza                                                | N.° CAS    |
|-------------------------------------------|--------------------------------------------------------------------|------------|
| <b>Amplificatore Per Antenna</b>          | Lead-monoxide                                                      | 1317-36-8  |
|                                           | Diboron-trioxide                                                   | 1303-86-2  |
| <b>Antenna Della Pressione Pneumatici</b> | Lead titanium zirconium oxide                                      | 12626-81-2 |
| <b>Apparecchiatura Di Comando</b>         | Lead-monoxide                                                      | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol        | 3147-75-9  |
| <b>Asse</b>                               | Boric acid                                                         | 10043-35-3 |
|                                           | Imidazolidine-2-thione                                             | 96-45-7    |
|                                           | Octamethylcyclotetrasiloxane                                       | 556-67-2   |
|                                           | 2-Methylimidazole                                                  | 693-98-1   |
|                                           | Decamethylcyclopentasiloxane                                       | 541-02-6   |
|                                           | Lead-monoxide                                                      | 1317-36-8  |
|                                           | Diboron-trioxide                                                   | 1303-86-2  |
|                                           | Tris(nonylphenyl)phosphite                                         | 26523-78-4 |
|                                           | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione   | 2451-62-9  |
|                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                       | 119-47-1   |
|                                           | Chromium-trioxide                                                  | 1333-82-0  |
|                                           | Hexahydromethylphthalic-anhydride                                  | 25550-51-0 |
|                                           | Paraffin oils, chloro                                              | 85422-92-0 |
|                                           | TBBA                                                               | 79-94-7    |
|                                           | Phenol, methylstyrenated                                           | 68512-30-1 |
|                                           | Triphenyl-phosphate                                                | 115-86-6   |
|                                           | O,O,O-Triphenyl phosphorothioate                                   | 597-82-0   |
|                                           | 1,6,7,8,9,14,15,16,17,17,18,18-                                    |            |
|                                           | Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9 |
| <b>Asse Motore</b>                        | N,N-Dimethylacetamide                                              | 127-19-5   |
|                                           | Octamethylcyclotetrasiloxane                                       | 556-67-2   |
|                                           | 2-Methylimidazole                                                  | 693-98-1   |
|                                           | Decamethylcyclopentasiloxane                                       | 541-02-6   |
|                                           | Lead-monoxide                                                      | 1317-36-8  |
|                                           | Diboron-trioxide                                                   | 1303-86-2  |

|                                                           |                                                                                                                                              |             |
|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Asse Motore</b>                                        | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                           | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                           | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                           | TBBA                                                                                                                                         | 79-94-7     |
|                                                           | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                           | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| <b>Batteria Della Rete Di Bordo</b>                       | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                           | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                           | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                           | Lead(II,IV)-oxide                                                                                                                            | 1314-41-6   |
| <b>Centralina Com. Blocchetto Accensione Elettronico</b>  | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                           | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Centralina Com. Convertitore Cc/Cc Basso Volt. 1</b>   | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                           | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                           | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                           | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                                                              | 75980-60-8  |
| <b>Centralina Comando Controllo Pressione Pneumatici</b>  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                           |                                                                                                                                              |             |
| <b>Centralina Comando Sensore Dell'Angolo Di Sterzata</b> | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                           | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Centralina Controllo Aut. Della Climatizzazione</b>    | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                           | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Centralina Di Comando Airbag</b>                       | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                           | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                           | TBBA                                                                                                                                         | 79-94-7     |
| <b>Centralina Di Comando Asse Aggiunto Sterzante</b>      | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Centralina Di Comando Convertitore</b>                 | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                           | Lead-monoxide                                                                                                                                | 1317-36-8   |

|                                                                   |                                                                                                                                                                   |                                                               |
|-------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Convertitore</b>                                               | <b>Diboron-trioxide<br/>TBBA</b>                                                                                                                                  | 1303-86-2<br>79-94-7                                          |
| <b>Centralina Di Comando<br/>Display</b>                          | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide<br/>1-Propanol, 2,3-dibromo-</b>    | 71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>96-13-9 |
| <b>Centralina Di Comando<br/>Gateway Centrale</b>                 | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Centralina Di Comando<br/>Gestione Del Cambio</b>              | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Centralina Di Comando<br/>Gestione Della Ricarica</b>          | <b>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                                                                                                                | 1317-36-8<br>1303-86-2<br>79-94-7                             |
| <b>Centralina Di Comando<br/>Modulo Porta<br/>Conducente</b>      | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Centralina Di Comando<br/>Modulo Porta<br/>Passeggero Ant.</b> | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Centralina Di Comando<br/>Piattaforma Telematica</b>           | <b>4,4'-Isopropylidenediphenol<br/>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide</b> | 80-05-7<br>71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2 |
| <b>Centralina Di Comando<br/>Radar A Corto Raggio</b>             | <b>Lead-monoxide</b>                                                                                                                                              | 1317-36-8                                                     |
| <b>Centralina Di Comando<br/>Sensore Di Distanza</b>              | <b>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                                                                                     | 12060-00-3<br>1317-36-8<br>1303-86-2<br>79-94-7               |
| <b>Centralina Di Comando<br/>Sensore Pioggia E Luce</b>           | <b>Lead-monoxide</b>                                                                                                                                              | 1317-36-8                                                     |

|                                                          |                                                                                                                                                                        |                                                                              |
|----------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| Centralina Di Comando<br>Sistema Regolazione<br>Livello  | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| Centralina Di Comando<br>Strumentazione                  | 4,4'-Isopropylidenediphenol<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                               | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7                                 |
| Centralina Di Comando<br>Tachigrafo                      | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide<br>Triphenyl-phosphate | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>75980-60-8<br>115-86-6 |
| Centralina Di Comando<br>Telecamera<br>Multifunzione     | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Pitch, coal tar, high-temp.                                                                             | 12060-00-3<br>1317-36-8<br>1303-86-2<br>65996-93-2                           |
| Centralina Di Comando<br>Video Radar Decision<br>Unit    | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                                                            | 12060-00-3<br>1317-36-8<br>1303-86-2                                         |
| Centralina Di Comando<br>XMC                             | Lead-monoxide<br>Diboron-trioxide<br>4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride                                                                                | 1317-36-8<br>1303-86-2<br>19438-60-9                                         |
| Centralina Edrive<br>Common Powertrain<br>Controller     | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA<br>2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone                                              | 12060-00-3<br>1317-36-8<br>1303-86-2<br>79-94-7<br>119313-12-1               |
| Centralina Modulo<br>Rilev. Segnale e<br>Comando Fhs     | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                                                            | 12060-00-3<br>1317-36-8<br>1303-86-2                                         |
| Centralina Sistema Di<br>Gestione Della Batteria         | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| Centralina Unità<br>Integrata Di<br>Trattamento Aria Apu | Lead titanium zirconium oxide<br>Lead-titanium-trioxide                                                                                                                | 12626-81-2<br>12060-00-3                                                     |

|                                            |                                                                    |            |
|--------------------------------------------|--------------------------------------------------------------------|------------|
| <b>Integrata Di</b>                        | <b>Lead-monoxide</b>                                               | 1317-36-8  |
|                                            | <b>Diboron-trioxide</b>                                            | 1303-86-2  |
| <b>Cilindro Di Lavoro</b>                  | <b>Imidazolidine-2-thione</b>                                      | 96-45-7    |
|                                            | <b>Lead-monoxide</b>                                               | 1317-36-8  |
| <b>Climatizzatore</b>                      | <b>Lead-monoxide</b>                                               | 1317-36-8  |
| <b>Compressore Del Fluido Refrigerante</b> | <b>4,4'-Isopropylidenediphenol</b>                                 | 80-05-7    |
|                                            | <b>2-Methylimidazole</b>                                           | 693-98-1   |
|                                            | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b>    | 71868-10-5 |
|                                            | <b>Lead-monoxide</b>                                               | 1317-36-8  |
|                                            | <b>Diboron-trioxide</b>                                            | 1303-86-2  |
|                                            | <b>Tris(nonylphenyl)phosphite</b>                                  | 26523-78-4 |
| <b>Convertitore Di Tensione</b>            | <b>Melamine</b>                                                    | 108-78-1   |
| <b>Convertitore Ethernet</b>               | <b>Lead-titanium-trioxide</b>                                      | 12060-00-3 |
|                                            | <b>Lead-monoxide</b>                                               | 1317-36-8  |
| <b>Coperchio Della Presa Di Corrente</b>   | <b>Bumetrizole</b>                                                 | 3896-11-5  |
| <b>Coperchio Di Chiusura Del Radiatore</b> | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                    | 80-43-3    |
| <b>Cristallo Laterale</b>                  | <b>Diboron-trioxide</b>                                            | 1303-86-2  |
| <b>Devioguida</b>                          | <b>Lead-monoxide</b>                                               | 1317-36-8  |
|                                            | <b>TBBA</b>                                                        | 79-94-7    |
| <b>Diodo</b>                               | <b>TBBA</b>                                                        | 79-94-7    |
| <b>Disco Di Chiusura</b>                   | <b>Imidazolidine-2-thione</b>                                      | 96-45-7    |
| <b>Distributore Di Energia</b>             | <b>Octamethylcyclotetrasiloxane</b>                                | 556-67-2   |
|                                            | <b>Decamethylcyclopentasiloxane</b>                                | 541-02-6   |
|                                            | <b>Dodecamethylcyclohexasiloxane</b>                               | 540-97-6   |
| <b>Evaporatore</b>                         | <b>Lead-monoxide</b>                                               | 1317-36-8  |
|                                            | <b>Diboron-trioxide</b>                                            | 1303-86-2  |
| <b>Fanale Di Posizione Posteriore</b>      | <b>Lead-monoxide</b>                                               | 1317-36-8  |
|                                            | <b>TBBA</b>                                                        | 79-94-7    |
|                                            | <b>2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol</b> | 3147-75-9  |
| <b>Faro</b>                                | <b>Lead-monoxide</b>                                               | 1317-36-8  |
| <b>Fascio Di Cavi Elettrici</b>            | <b>Melamine</b>                                                    | 108-78-1   |
|                                            | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                    | 80-43-3    |
| <b>Flessibile Del Freno</b>                | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>                | 119-47-1   |
|                                            | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                    | 80-43-3    |
| <b>Giubbotto Ad Alta Visibilità</b>        | <b>Diboron-trioxide</b>                                            | 1303-86-2  |
| <b>Guarnizione Di Tenuta</b>               | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                    | 80-43-3    |
| <b>Guarnizione Profilata</b>               | <b>C,C'-azodi(formamide)</b>                                       | 123-77-3   |
| <b>Interruttore A Pulsante</b>             | <b>Lead-monoxide</b>                                               | 1317-36-8  |
|                                            | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                    | 80-43-3    |

|                                            |                                                                                                                |                                               |
|--------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------|
| <b>Interruttore Basculante</b>             | Lead-monoxide<br>TBBA                                                                                          | 1317-36-8<br>79-94-7                          |
| <b>Interruttore Delle Luci</b>             | Lead-monoxide                                                                                                  | 1317-36-8                                     |
| <b>Lampada</b>                             | Diboron-trioxide                                                                                               | 1303-86-2                                     |
| <b>Leva Di Comando</b>                     | Lead-monoxide<br>Diboron-trioxide                                                                              | 1317-36-8<br>1303-86-2                        |
| <b>Luce D'Ingombro</b>                     | TBBA<br>2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                            | 79-94-7<br>3147-75-9                          |
| <b>Luce Interna</b>                        | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                    | 3147-75-9                                     |
| <b>Modulatore Dell'Asse</b>                | Lead-monoxide                                                                                                  | 1317-36-8                                     |
| <b>Modulo Batteria Ad Alto Voltaggio</b>   | Lead-monoxide<br>1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                    | 1317-36-8<br>29420-49-3                       |
| <b>Motorino Del Tergicristallo</b>         | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                                                                | 25973-55-1                                    |
| <b>Nastro Di Feltro</b>                    | Disodium-octaborate                                                                                            | 12008-41-2                                    |
| <b>O-Ring</b>                              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                   | 119-47-1                                      |
| <b>Pannello Interruttori</b>               | Lead-monoxide<br>TBBA                                                                                          | 1317-36-8<br>79-94-7                          |
| <b>Parafango</b>                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                    | 3147-75-9                                     |
| <b>Passacavo In Materiale Elastico</b>     | Imidazolidine-2-thione                                                                                         | 96-45-7                                       |
| <b>Pedale Dell'Acceleratore</b>            | Lead-monoxide<br>TBBA                                                                                          | 1317-36-8<br>79-94-7                          |
| <b>Plafoniera</b>                          | Triphenyl-phosphate                                                                                            | 115-86-6                                      |
| <b>Pompa Del Liquido Di Raffreddamento</b> | Lead-monoxide<br>Diboron-trioxide<br>Bis(alpha,alpha-dimethylbenzyl) peroxide                                  | 1317-36-8<br>1303-86-2<br>80-43-3             |
| <b>Porta</b>                               | Triphenyl-phosphate                                                                                            | 115-86-6                                      |
| <b>Porta Laterale</b>                      | Triphenyl-phosphate                                                                                            | 115-86-6                                      |
| <b>Pulsante</b>                            | Octamethylcyclotetrasiloxane<br>Decamethylcyclopentasiloxane<br>Lead-monoxide<br>Dodecamethylcyclohexasiloxane | 556-67-2<br>541-02-6<br>1317-36-8<br>540-97-6 |
| <b>Raccordo Filettato</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                       | 80-43-3                                       |
| <b>Rete Per Bagagli</b>                    | N,N-Dimethylacetamide                                                                                          | 127-19-5                                      |
| <b>Retrovisore Esterno</b>                 | TBBA<br>Triphenyl-phosphate                                                                                    | 79-94-7<br>115-86-6                           |
| <b>Riscaldamento</b>                       | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                    | 12060-00-3<br>1317-36-8<br>1303-86-2          |
| <b>Schermo</b>                             | 2-Methylimidazole<br>Lead-monoxide<br>Diboron-trioxide                                                         | 693-98-1<br>1317-36-8<br>1303-86-2            |
| <b>Sedile A Sospensione Pneumatica</b>     | Triphenyl-phosphate                                                                                            | 115-86-6                                      |

|                                                         |                                                          |             |
|---------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Sedile Lato Guida</b>                                | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                         | Triphenyl-phosphate                                      | 115-86-6    |
| <b>Sedile Per<br/>L'Accompagnatore</b>                  | C,C'-azodi(formamide)                                    | 123-77-3    |
|                                                         | Melamine                                                 | 108-78-1    |
|                                                         | Triphenyl-phosphate                                      | 115-86-6    |
| <b>Sensore Di<br/>Accelerazione</b>                     | Diboron-trioxide                                         | 1303-86-2   |
| <b>Sensore Di Pressione</b>                             | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                         | Lead-monoxide                                            | 1317-36-8   |
|                                                         | 1,2-Dimethoxyethane                                      | 110-71-4    |
|                                                         | 1,3-Propanesultone                                       | 1120-71-4   |
| <b>Sensore Di<br/>Temperatura</b>                       | TBBA                                                     | 79-94-7     |
| <b>Serie Di Chiavi</b>                                  | 1,2-Dimethoxyethane                                      | 110-71-4    |
| <b>Serratura Della Porta</b>                            | Triphenyl-phosphate                                      | 115-86-6    |
| <b>Soffietto Della<br/>Sospensione</b>                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
| <b>Specchi</b>                                          | 2-Methylimidazole                                        | 693-98-1    |
|                                                         | Lead-monoxide                                            | 1317-36-8   |
|                                                         | Diboron-trioxide                                         | 1303-86-2   |
| <b>Spia Di Controllo</b>                                | TBBA                                                     | 79-94-7     |
|                                                         | Melamine                                                 | 108-78-1    |
| <b>Sportello</b>                                        | C,C'-azodi(formamide)                                    | 123-77-3    |
| <b>Tappo</b>                                            | Bumetrizole                                              | 3896-11-5   |
| <b>Telecamera</b>                                       | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                         | 2-Methylimidazole                                        | 693-98-1    |
|                                                         | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                         | Lead-monoxide                                            | 1317-36-8   |
|                                                         | Diboron-trioxide                                         | 1303-86-2   |
|                                                         | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                         | Refractory ceramic fibres                                | 142844-00-6 |
|                                                         | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Trasduttore Della Corsa<br/>Del Pedale Del Freno</b> | Lead-monoxide                                            | 1317-36-8   |
|                                                         | Diboron-trioxide                                         | 1303-86-2   |
| <b>Unità Di Collegamento<br/>Multimediale</b>           | Lead-monoxide                                            | 1317-36-8   |
|                                                         | Diboron-trioxide                                         | 1303-86-2   |
| <b>Unità Di Comando</b>                                 | Lead-monoxide                                            | 1317-36-8   |
| <b>Valvola<br/>Elettromagnetica</b>                     | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
| <b>Ventola</b>                                          | TBBA                                                     | 79-94-7     |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Vite A Testa Esagonale</b>                           | Diboron-trioxide                                         | 1303-86-2   |
| <b>Viti A Testa Esalobata</b>                           | Diboron-trioxide                                         | 1303-86-2   |



Cienījamā kliente, godātais klient!

2007. gada 1. jūlijā spēkā stājās likums saistībā ar Eiropas ķīmikāliju regulu (EK) Nr. 1907/2006 (REACH – par ķīmikāliju reģistrēšanu, vērtēšanu, licencēšanu un ierobežošanu), kura mērķis ir aizsargāt cilvēku veselību un apkārtējo vidi no iespējamajiem ķīmisko vielu riskiem.

Daimler Truck AG atbalsta REACH mērķus. Likuma 33. pantā noteikts, ka jums kā klientam jābūt informētam par vielām, kas rada lielas bažas (SVHC), mūsu produktos. Šī nosacījuma mērķis ir nodrošināt drošu rīcību ar noteiktajām vielām visā produkta dzīves cikla laikā.

Pamatojoties uz likuma nosacījumiem un ņemot vērā Daimler Truck AG piegādātāju datus, tikušas identificētas tālāk norādītās vielas, kuras atsevišķos šī transportlīdzekļa izstrādājumos varētu būt vairāk nekā 0,1 % no produkta masas. Pareizi lietojot transportlīdzekli, nepastāv nekāda bīstamība cilvēku veselībai vai apkārtējai videi. Papildu informāciju par drošu jūsu transportlīdzekļa lietošanu skatiet lietošanas instrukcijā.

Lūdzu, ņemiet vērā, ka startera akumulators, sakausējumi, stikla/keramikas/elastomēru konstrukcijas elementi, kā arī dažādi elektroniskie konstrukcijas elementi (jo īpaši lodējumi) papildus satur svinu (CAS Nr. 7439-92-1).

| Product group           | Substance name                                                   | CAS no.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |
| Brake Value Sensor      | Lead-monoxide                                                    | 1317-36-8  |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Brake Value Sensor</b>                      | Diboron-trioxide                                         | 1303-86-2   |
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Automatic Climate Control</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Central Gateway</b>            | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit Electronic Ignition Lock</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Instrument Cluster</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit Rain-Light Sensor</b>          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Video Radar Decision Unit</b>  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Air-Processing Unit</b>       | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclotetrasiloxane                           | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                                     |             |
|---------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | <b>4,4'-Isopropylidenediphenol</b>                                                                                                                  | 80-05-7     |
|                                                         | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b>                                                                                     | 71868-10-5  |
|                                                         | <b>Lead-titanium-trioxide</b>                                                                                                                       | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
|                                                         | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | <b>Lead-titanium-trioxide</b>                                                                                                                       | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | <b>TBBA</b>                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | <b>1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene</b>                                            | 13560-89-9  |
|                                                         | <b>N,N-Dimethylacetamide</b>                                                                                                                        | 127-19-5    |
|                                                         | <b>Octamethylcyclotetrasiloxane</b>                                                                                                                 | 556-67-2    |
|                                                         | <b>2-Methylimidazole</b>                                                                                                                            | 693-98-1    |
|                                                         | <b>Decamethylcyclopentasiloxane</b>                                                                                                                 | 541-02-6    |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
|                                                         | <b>4-Nonylphenol, branched</b>                                                                                                                      | 84852-15-3  |
|                                                         | <b>Nonylphenol</b>                                                                                                                                  | 25154-52-3  |
|                                                         | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>                                                                                                 | 119-47-1    |
|                                                         | <b>Dodecamethylcyclohexasiloxane</b>                                                                                                                | 540-97-6    |
|                                                         | <b>TBBA</b>                                                                                                                                         | 79-94-7     |
|                                                         | <b>Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters</b> | 255881-94-8 |
|                                                         | <b>Phenol, methylstyrenated</b>                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
|                                                         | <b>4,4'-Isopropylidenediphenol</b>                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
|                                                         | <b>Melamine</b>                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                  |                                                 |            |
|------------------|-------------------------------------------------|------------|
| Wiper Motor      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol | 25973-55-1 |
| Working Cylinder | Imidazolidine-2-thione                          | 96-45-7    |
|                  | Lead-monoxide                                   | 1317-36-8  |

Gerb. kliente,

2017 m. birželio 1 d. įsigaliojęs įstatymas dėl ES cheminių medžiagų reglamento (EB) Nr. 1907/2006, (REACH – cheminių medžiagų registracija, įvertinimas, autorizacija ir apribojimai) užsibrėžė tikslą saugoti žmonių sveikatą ir aplinką nuo cheminių medžiagų galimai keliamų rizikų.

Daimler Truck AG taip pat remia REACH tikslus. Įstatymo 33 straipsnis numato, kad turime Jus, kaip klientą, informuoti apie mūsų gaminiuose esančias, labai didelį susirūpinimą keliančias medžiagas (SVHC). Šio reikalavimo tikslas – užtikrinti, kad per visą gaminio gyvavimo ciklą bus saugiai elgiamasi su nurodytomis medžiagomis.

Remiantis teisiniais reikalavimais ir atsižvelgiant į Daimler Truck AG tiekėjų pateiktą informaciją, buvo nustatytos šios medžiagos, kurių atskirose šios transporto priemonės dalyse gali būti daugiau nei 0,1 masės procentinės dalies. Naudojant transporto priemonę pagal paskirtį, pavojaus žmonėms ir aplinkai nėra. Daugiau informacijos apie saugų Jūsų transporto priemonės naudojimą rasite savo naudojimo instrukcijoje.

Prašome atkreipti dėmesį, kad yra naudojamas švinas (CAS-Nr. 7439-92-1), kuris randamas starterio akumuliatoriuje, lydinuose, sluoksniuose, stikle / keramikos / elastomero komponentuose ir įvairiuose elektroniniuose komponentuose (ypač lydmetaluose).

| Product group           | Substance name                                                   | CAS no.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Brake Value Sensor</b>                      | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit Automatic</b>                  |                                                          |             |
| <b>Climate Control</b>                         | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Central</b>                    |                                                          |             |
| <b>Gateway</b>                                 | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit Electronic</b>                 |                                                          |             |
| <b>Ignition Lock</b>                           | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Instrument</b>                 |                                                          |             |
| <b>Cluster</b>                                 | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit Rain-Light</b>                 |                                                          |             |
| <b>Sensor</b>                                  | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Video</b>                      |                                                          |             |
| <b>Radar Decision Unit</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Air-Processing Unit</b>       |                                                          |             |
|                                                | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                              |             |
|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                         | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | TBBA                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                                         | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                         | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                         | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                         | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                         | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                         | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                         | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                         | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                         | TBBA                                                                                                                                         | 79-94-7     |
|                                                         | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                         | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                         | Melamine                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                  |                                                 |            |
|------------------|-------------------------------------------------|------------|
| Wiper Motor      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol | 25973-55-1 |
| Working Cylinder | Imidazolidine-2-thione                          | 96-45-7    |
|                  | Lead-monoxide                                   | 1317-36-8  |

Gheżież klijenti,

Il-liġi li dahlet fis-seħħ. fl-1 ta' Ġunju 2007 dwar ir-Regolament fuq is-Sustanzi Kimiċi (KE) Nru 1907/2006 (REACH - reġistrazzjoni, valutazzjoni, awtorizzazzjoni u restrizzjoni ta' sustanzi kimiċi), għandha l-għan li tħares is-saħħa tal-bniedem u l-ambjent minn riskji li jistgħu jiġu mis-sustanzi kimiċi.

Id- Daimler Truck AG tirrispetta l-għanijiet ta' REACH. L-Artikolu 33 fil-leġiżlazzjoni jinkludi d-dritt li intom bħala klijenti tkunu infurmati dwar sustanzi ta' tħassib serju ħafna (SVHC) fil-prodotti tagħna. L-għan ta' din il-liġi hu li jkun ipprovdut l-użu sigur ta' sustanzi definiti matul iċ-ċiklu tal-ħajja kollu tal-prodott.

Abbażi tad-dispożizzjonijiet legali u skont l-informazzjoni mogħtija mill-fornituri ta' Daimler Truck AG, ġew identifikati dawn is-sustanzi li ġejjin bħala sustanzi li jista' jkollhom piż ta' iktar minn 0.1% f'ċertu prodotti f'din il-vettura. Waqt l-użu kif suppost tal-vettura m'hemm l-ebda periklu għall-bniedem jew l-ambjent. Iktar informazzjoni dwar l-użu sigur tal-vettura tagħkom tistgħu ssibuha fil-manwal għall-operatur.

Jekk jogħġbok innota li ċ-ċomb (Nru tas-CAS 7439-92-1) huwa sustanza li tinsab mhux biss fil-batterija tal-istarter iżda wkoll f'liġi, kisi, komponenti tal-ħġieġ, taċ-ċeramika jew tal-elastomeri kif ukoll f'diversi komponenti elettronici (speċjalment l-istann).

| Product group           | Substance name                                                   | CAS no.    |
|-------------------------|------------------------------------------------------------------|------------|
| Acceleration Sensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Accelerator Pedal       | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
| Adjacent Driver Seat    | C,C'-azodi(formamide)                                            | 123-77-3   |
|                         | Melamine                                                         | 108-78-1   |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
| Air Conditioning System | Lead-monoxide                                                    | 1317-36-8  |
| Air Suspension Bellows  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
| Antenna Amplifier       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Axle                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axle Modulator          | Lead-monoxide                                                    | 1317-36-8  |
| Brake Hose              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Brake Value Sensor</b>                      | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Bulb</b>                                    | Diboron-trioxide                                         | 1303-86-2   |
| <b>Button Switch</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Camera</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                | Refractory ceramic fibres                                | 142844-00-6 |
|                                                | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Device</b>                          | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Lever</b>                           | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit Automatic</b>                  |                                                          |             |
| <b>Climate Control</b>                         | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Central</b>                    |                                                          |             |
| <b>Gateway</b>                                 | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                |                                                          |             |
| <b>Control Unit Electronic</b>                 |                                                          |             |
| <b>Ignition Lock</b>                           | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Instrument</b>                 |                                                          |             |
| <b>Cluster</b>                                 | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit Rain-Light</b>                 |                                                          |             |
| <b>Sensor</b>                                  | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit Video</b>                      |                                                          |             |
| <b>Radar Decision Unit</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit XMC</b>                        | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| <b>Control Unit, Airbag</b>                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Air-Processing Unit</b>       |                                                          |             |
|                                                | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Battery Management System</b> | Lead-monoxide                                            | 1317-36-8   |

|                                                          |                                                          |             |
|----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Control Unit, Dc/Dc Converter, Low Voltage 1</b>      | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Control Unit, Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Control Unit, Distance Sensor</b>                     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Driver Door Module</b>                  | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
|                                                          | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Control Unit, Frequency Converter</b>                 | 2-Methylimidazole                                        | 693-98-1    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | TBBA                                                     | 79-94-7     |
| <b>Control Unit, Level Control</b>                       | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Multifunction Camera</b>                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                          | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
|                                                          | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Control Unit, Passenger Door Module</b>               | Lead-monoxide                                            | 1317-36-8   |
|                                                          | Diboron-trioxide                                         | 1303-86-2   |
| <b>Control Unit, Short-Range Radar</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Control Unit, Steered Additional Axle</b>             | Lead-monoxide                                            | 1317-36-8   |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |

|                                                         |                                                                                                                                                     |             |
|---------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Control Unit, Steering Angle Sensor</b>              | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Telematics Platform</b>                | <b>4,4'-Isopropylidenediphenol</b>                                                                                                                  | 80-05-7     |
|                                                         | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b>                                                                                     | 71868-10-5  |
|                                                         | <b>Lead-titanium-trioxide</b>                                                                                                                       | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Control Unit, Tire Pressure Monitoring System</b>    | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
| <b>Control Unit, Transmission Control</b>               | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Coolant Pump</b>                                     | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
|                                                         | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                                                                                                     | 80-43-3     |
| <b>Cu, Signal Acquisition and Actuation Module, Cab</b> | <b>Lead-titanium-trioxide</b>                                                                                                                       | 12060-00-3  |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
| <b>Diode</b>                                            | <b>TBBA</b>                                                                                                                                         | 79-94-7     |
| <b>Dome Lamp</b>                                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Door</b>                                             | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Door Lock</b>                                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
| <b>Drive Axle</b>                                       | <b>1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene</b>                                            | 13560-89-9  |
|                                                         | <b>N,N-Dimethylacetamide</b>                                                                                                                        | 127-19-5    |
|                                                         | <b>Octamethylcyclotetrasiloxane</b>                                                                                                                 | 556-67-2    |
|                                                         | <b>2-Methylimidazole</b>                                                                                                                            | 693-98-1    |
|                                                         | <b>Decamethylcyclopentasiloxane</b>                                                                                                                 | 541-02-6    |
|                                                         | <b>Lead-monoxide</b>                                                                                                                                | 1317-36-8   |
|                                                         | <b>Diboron-trioxide</b>                                                                                                                             | 1303-86-2   |
|                                                         | <b>4-Nonylphenol, branched</b>                                                                                                                      | 84852-15-3  |
|                                                         | <b>Nonylphenol</b>                                                                                                                                  | 25154-52-3  |
|                                                         | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>                                                                                                 | 119-47-1    |
|                                                         | <b>Dodecamethylcyclohexasiloxane</b>                                                                                                                | 540-97-6    |
|                                                         | <b>TBBA</b>                                                                                                                                         | 79-94-7     |
|                                                         | <b>Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters</b> | 255881-94-8 |
|                                                         | <b>Phenol, methylstyrenated</b>                                                                                                                     | 68512-30-1  |
| <b>Driver's Seat</b>                                    | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
|                                                         | <b>4,4'-Isopropylidenediphenol</b>                                                                                                                  | 80-05-7     |
| <b>Electrical Wiring Harness</b>                        | <b>Triphenyl-phosphate</b>                                                                                                                          | 115-86-6    |
|                                                         | <b>Melamine</b>                                                                                                                                     | 108-78-1    |

|                                           |                                                                            |            |
|-------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Harness</b>                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Ethernet Converter</b>                 | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Evaporator</b>                         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Fan</b>                                | TBBA                                                                       | 79-94-7    |
|                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| <b>Feed-Through Grommet</b>               | Imidazolidine-2-thione                                                     | 96-45-7    |
| <b>Felt Strip</b>                         | Disodium-octaborate                                                        | 12008-41-2 |
| <b>Fender</b>                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Flap</b>                               | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Headlamp</b>                           | Lead-monoxide                                                              | 1317-36-8  |
| <b>Heating</b>                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexagon Head Bolt</b>                  | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Hexalobular Bolt</b>                   | Diboron-trioxide                                                           | 1303-86-2  |
| <b>High-Voltage Battery Module</b>        | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Indicator Light</b>                    | TBBA                                                                       | 79-94-7    |
|                                           | Melamine                                                                   | 108-78-1   |
| <b>Interior Light</b>                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Key Kit</b>                            | 1,2-Dimethoxyethane                                                        | 110-71-4   |
| <b>Light Switch</b>                       | Lead-monoxide                                                              | 1317-36-8  |
| <b>Luggage Net</b>                        | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Marker Lamp</b>                        | TBBA                                                                       | 79-94-7    |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Mirror</b>                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                           | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Mirror Otr</b>                         | TBBA                                                                       | 79-94-7    |
|                                           | Triphenyl-phosphate                                                        | 115-86-6   |
| <b>Multimedia Connection Unit</b>         | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
| <b>On-Board Electrical System Battery</b> | Lead-monoxide                                                              | 1317-36-8  |
|                                           | Diboron-trioxide                                                           | 1303-86-2  |
|                                           | Lead(II,IV)-oxide                                                          | 1314-41-6  |
| <b>Operating Unit</b>                     | Lead-monoxide                                                              | 1317-36-8  |
|                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>O-Ring</b>                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| <b>Panel</b>                              | Lead-monoxide                                                              | 1317-36-8  |
|                                           | TBBA                                                                       | 79-94-7    |
| <b>Power Distributor</b>                  | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| <b>Pressure Button</b>                    | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                           | Decamethylcyclopentasiloxane                                               | 541-02-6   |

|                                      |                                                             |            |
|--------------------------------------|-------------------------------------------------------------|------------|
| <b>Pressure Button</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Pressure Sensor</b>               | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                      | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Profile Seal</b>                  | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Radiator Cap</b>                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Refrigerant Compressor</b>        | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                      | 2-Methylimidazole                                           | 693-98-1   |
|                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Rocker Switch</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Safety Vest</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screen</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
| <b>Screw-In Fitting</b>              | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Seal</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Sealing Washer</b>                | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Side Door</b>                     | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Side Window Pane</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Socket Cover</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Solenoid Valve</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Steering Column Switch</b>        | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
| <b>Steering Wheel</b>                | Lead-monoxide                                               | 1317-36-8  |
| <b>Stop Plug</b>                     | Bumetrizole                                                 | 3896-11-5  |
| <b>Suspension Seat</b>               | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tachograph Control Unit</b>       | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                      | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                      | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8 |
|                                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Tail Lamp</b>                     | Lead-monoxide                                               | 1317-36-8  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Temperature Sensor</b>            | TBBA                                                        | 79-94-7    |
| <b>Tire Pressure Antenna</b>         | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Vehicle Charging Control Unit</b> | Lead-monoxide                                               | 1317-36-8  |
|                                      | Diboron-trioxide                                            | 1303-86-2  |
|                                      | TBBA                                                        | 79-94-7    |
|                                      | Melamine                                                    | 108-78-1   |

|                  |                                                 |            |
|------------------|-------------------------------------------------|------------|
| Wiper Motor      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol | 25973-55-1 |
| Working Cylinder | Imidazolidine-2-thione                          | 96-45-7    |
|                  | Lead-monoxide                                   | 1317-36-8  |

Kjære kunde,

den 01. juni 2007 trådte det i kraft en lov om EU-kjemikaliedirektiv (EG) Nr. 1907/2006, (REACH - registrering, evaluering, tillatelse og begrensning av kjemikalier, har som mål å garantere at mennesker helse og miljøet er beskyttet mot mulig risiko på grunn av kjemikalier.

Daimler Truck AG støtter målene til REACH. Artikkel 33 i loven pålegger at du som kunde skal informeres om spesielt bekymringsfulle stoffer (SVHC) i våre produkter. Formålet med denne spesifikasjonen er å garantere sikker håndtering av de angitte stoffene gjennom hele produktets livssyklus.

Med utgangspunkt i gjeldende lovbestemmelser og opplysninger gitt av leverandørene til Daimler A er følgende stoffer identifisert som enkelte produkter i denne bilen kan inneholde mer enn 0,1 vektprosent av. Ved tiltenkt bruk av bilen er det ikke noen fare for mennesker eller miljø. Ytterligere informasjon om sikker bruk av din bil, finner du i bruksanvisningen.

Vær oppmerksom på at også stoffet bly (CAS-nr. 7439-92-1) finnes i startbatteriet, i legeringer, belegg, glass-/keramikk-/elastomer-komponenter samt diverse elektronikkomponenter (først og fremst lodding).

| Product group         | Substans navn                                                    | CAS nr.    |
|-----------------------|------------------------------------------------------------------|------------|
| Aksel                 | Boric acid                                                       | 10043-35-3 |
|                       | Imidazolidine-2-thione                                           | 96-45-7    |
|                       | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                       | 2-Methylimidazole                                                | 693-98-1   |
|                       | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                       | Lead-monoxide                                                    | 1317-36-8  |
|                       | Diboron-trioxide                                                 | 1303-86-2  |
|                       | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                       | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                       | Chromium-trioxide                                                | 1333-82-0  |
|                       | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                       | Paraffin oils, chloro                                            | 85422-92-0 |
|                       | TBBA                                                             | 79-94-7    |
|                       | Phenol, methylstyrenated                                         | 68512-30-1 |
|                       | Triphenyl-phosphate                                              | 115-86-6   |
| Akselerasjonssensor   | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Akselmodulator        | Diboron-trioxide                                                 | 1303-86-2  |
| Antenne For Dekktrykk | Lead-monoxide                                                    | 1317-36-8  |
| Antenneforsterker     | Lead titanium zirconium oxide                                    | 12626-81-2 |
| Arbeidssylinder       | Lead-monoxide                                                    | 1317-36-8  |
|                       | Diboron-trioxide                                                 | 1303-86-2  |
| Avfjæret Sete         | Imidazolidine-2-thione                                           | 96-45-7    |
|                       | Lead-monoxide                                                    | 1317-36-8  |
| Bagasjenett           | Triphenyl-phosphate                                              | 115-86-6   |
| Baklykt               | N,N-Dimethylacetamide                                            | 127-19-5   |
|                       | Lead-monoxide                                                    | 1317-36-8  |
|                       | TBBA                                                             | 79-94-7    |
| Betjeningsenhet       | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9  |
|                       | Lead-monoxide                                                    | 1317-36-8  |
|                       | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9  |
| Betjeningsspak        | Lead-monoxide                                                    | 1317-36-8  |
|                       | Diboron-trioxide                                                 | 1303-86-2  |
| Bilbatteri            | Lead-monoxide                                                    | 1317-36-8  |

|                        |                                                                                                                                              |             |
|------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Bilbatteri             | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                        | Lead(II,IV)-oxide                                                                                                                            | 1314-41-6   |
| Bremseslange           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Bremseverdiger         | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Bryter                 | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Bryterfelt             | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | TBBA                                                                                                                                         | 79-94-7     |
| Diode                  | TBBA                                                                                                                                         | 79-94-7     |
| Dør                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Dørlås                 | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Drivaksel              | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                        | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                        | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                        | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                        | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                        | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                        | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                        | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                        | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                        | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                        | TBBA                                                                                                                                         | 79-94-7     |
|                        | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                        | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Elektrisk Ledningssett | Melamine                                                                                                                                     | 108-78-1    |
|                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Ethernet-Omformer      | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                        | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Filtbånd               | Disodium-octaborate                                                                                                                          | 12008-41-2  |
| Fjærbelg               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| Fordamper              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Førersete              | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Frontlykter            | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Gasspedal              | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | TBBA                                                                                                                                         | 79-94-7     |
| Guidesete              | C,C'-azodi(formamide)                                                                                                                        | 123-77-3    |
|                        | Melamine                                                                                                                                     | 108-78-1    |
|                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Høyvoltbatterimodul    | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                        | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                                                                   | 29420-49-3  |

|                                    |                                                             |             |
|------------------------------------|-------------------------------------------------------------|-------------|
| <b>Kabelgjennomføring</b>          | Imidazolidine-2-thione                                      | 96-45-7     |
| <b>Kamera</b>                      | Octamethylcyclotetrasiloxane                                | 556-67-2    |
|                                    | 2-Methylimidazole                                           | 693-98-1    |
|                                    | Decamethylcyclopentasiloxane                                | 541-02-6    |
|                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                    | Lead-monoxide                                               | 1317-36-8   |
|                                    | Diboron-trioxide                                            | 1303-86-2   |
|                                    | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
|                                    | Refractory ceramic fibres                                   | 142844-00-6 |
|                                    | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
| <b>Kjølemiddel-kompressor</b>      | 4,4'-Isopropylidenediphenol                                 | 80-05-7     |
|                                    | 2-Methylimidazole                                           | 693-98-1    |
|                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                    | Lead-monoxide                                               | 1317-36-8   |
|                                    | Diboron-trioxide                                            | 1303-86-2   |
|                                    | Tris(nonylphenyl)phosphite                                  | 26523-78-4  |
| <b>Kjølevæskepumpe</b>             | Lead-monoxide                                               | 1317-36-8   |
|                                    | Diboron-trioxide                                            | 1303-86-2   |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Kjølevifte</b>                  | TBBA                                                        | 79-94-7     |
|                                    | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Klimaanlegg</b>                 | Lead-monoxide                                               | 1317-36-8   |
| <b>Kontrolllampe</b>               | TBBA                                                        | 79-94-7     |
|                                    | Melamine                                                    | 108-78-1    |
| <b>Kontrollpanel</b>               | Lead-monoxide                                               | 1317-36-8   |
| <b>Lampe, Innvendig</b>            | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| <b>Låseskive</b>                   | Imidazolidine-2-thione                                      | 96-45-7     |
| <b>Lysbryter</b>                   | Lead-monoxide                                               | 1317-36-8   |
| <b>Lyspære</b>                     | Diboron-trioxide                                            | 1303-86-2   |
| <b>Magnetventil</b>                | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
| <b>Markeringslys</b>               | TBBA                                                        | 79-94-7     |
|                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| <b>Multimedie-tilkoblingsenhet</b> | Lead-monoxide                                               | 1317-36-8   |
|                                    | Diboron-trioxide                                            | 1303-86-2   |
| <b>Nøkkelsekk</b>                  | 1,2-Dimethoxyethane                                         | 110-71-4    |
| <b>O-Ring</b>                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
| <b>Pakning</b>                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Profiltetning</b>               | C,C'-azodi(formamide)                                       | 123-77-3    |
| <b>Radiatorlokk</b>                | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Ratt</b>                        | Lead-monoxide                                               | 1317-36-8   |
| <b>Rattstammebryter</b>            | Lead-monoxide                                               | 1317-36-8   |
|                                    | TBBA                                                        | 79-94-7     |
| <b>Refleksvest</b>                 | Diboron-trioxide                                            | 1303-86-2   |
| <b>Sekskantskrue</b>               | Diboron-trioxide                                            | 1303-86-2   |
| <b>Sidedør</b>                     | Triphenyl-phosphate                                         | 115-86-6    |
| <b>Sidevindu</b>                   | Diboron-trioxide                                            | 1303-86-2   |
| <b>Skjerm</b>                      | 2-Methylimidazole                                           | 693-98-1    |
|                                    | Lead-monoxide                                               | 1317-36-8   |
|                                    | Diboron-trioxide                                            | 1303-86-2   |
|                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |

|                                                       |                                                          |             |
|-------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Skruestuss</b>                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Speil</b>                                          | 2-Methylimidazole                                        | 693-98-1    |
|                                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
| <b>Speil Ut</b>                                       | TBBA                                                     | 79-94-7     |
|                                                       | Triphenyl-phosphate                                      | 115-86-6    |
| <b>Spenningsomformer</b>                              | Melamine                                                 | 108-78-1    |
| <b>Spjeld</b>                                         | C,C'-azodi(formamide)                                    | 123-77-3    |
| <b>Stikkontakdeksel</b>                               | Bumetrizole                                              | 3896-11-5   |
| <b>Strømfordeler</b>                                  | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                       | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                       | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
| <b>Styreenhet Air-Processing Unit</b>                 | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                       | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
| <b>Styreenhet Avstandssensor</b>                      | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
|                                                       | TBBA                                                     | 79-94-7     |
| <b>Styreenhet Batteri-styringssystem</b>              | Lead-monoxide                                            | 1317-36-8   |
| <b>Styreenhet Dc/Dc-Omformer Lavvolt 1</b>            | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                       | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                       | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                       | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Styreenhet Dekktrykkkontroll</b>                   | Lead-monoxide                                            | 1317-36-8   |
| <b>Styreenhet Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                       | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
|                                                       | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Styreenhet Dørmodul Fører</b>                      | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
| <b>Styreenhet Dørmodul Forsetepassasjer</b>           | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
| <b>Styreenhet Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                       | Diboron-trioxide                                         | 1303-86-2   |
|                                                       | TBBA                                                     | 79-94-7     |
|                                                       | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |

|                                           |                                                          |            |
|-------------------------------------------|----------------------------------------------------------|------------|
| <b>Styreenhet Elektronisk Tenningslås</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                           | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhet Fartsskriver</b>            | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                           | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                           | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
|                                           | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                                           | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Styreenhet Girkassestyring</b>         | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styreenhet Klimaautomatikk</b>         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                           | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhet Kollisjonspute</b>          | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
|                                           | TBBA                                                     | 79-94-7    |
| <b>Styreenhet Kombiinstrument</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                           | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
|                                           | TBBA                                                     | 79-94-7    |
| <b>Styreenhet Ladestyring</b>             | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
|                                           | TBBA                                                     | 79-94-7    |
| <b>Styreenhet Multi-funksjonskamera</b>   | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                           | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
|                                           | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <b>Styreenhet Nærområderadar</b>          | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhet Nivåregulering</b>          | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhet Omformer</b>                | 2-Methylimidazole                                        | 693-98-1   |
|                                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                           | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |
|                                           | TBBA                                                     | 79-94-7    |
| <b>Styreenhet Regn-/Lyssensor</b>         | Lead-monoxide                                            | 1317-36-8  |
| <b>Styreenhet Sentral Gateway</b>         | Lead-monoxide                                            | 1317-36-8  |
|                                           | Diboron-trioxide                                         | 1303-86-2  |

|                                                      |                                                          |            |
|------------------------------------------------------|----------------------------------------------------------|------------|
| Styreenhet Signalreg.-<br>og Aktiveringsmodul<br>Fhs | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Styreenhet<br>Styrevinkelsensor                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Styreenhet Styrt<br>Tilleggsaksel                    | Lead-monoxide                                            | 1317-36-8  |
|                                                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                      | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| Styreenhet<br>Telematikkplattform                    | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                      | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Styreenhet Video Radar<br>Decision Unit              | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Styreenhet XMC                                       | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
|                                                      | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |
| Taklampe                                             | Triphenyl-phosphate                                      | 115-86-6   |
| Temperatursensor                                     | TBBA                                                     | 79-94-7    |
| Tetningsplugg                                        | Bumetrizole                                              | 3896-11-5  |
| Trykknapp                                            | Octamethylcyclotetrasiloxane                             | 556-67-2   |
|                                                      | Decamethylcyclopentasiloxane                             | 541-02-6   |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
| Trykksensor                                          | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | 1,2-Dimethoxyethane                                      | 110-71-4   |
|                                                      | 1,3-Propanesultone                                       | 1120-71-4  |
| Utvendig Torxskrue                                   | Diboron-trioxide                                         | 1303-86-2  |
| Varmesystem                                          | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                      | Lead-monoxide                                            | 1317-36-8  |
|                                                      | Diboron-trioxide                                         | 1303-86-2  |
| Vippebryter                                          | Lead-monoxide                                            | 1317-36-8  |
|                                                      | TBBA                                                     | 79-94-7    |
| Viskermotor                                          | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol          | 25973-55-1 |

Szanowna Klientko, Szanowny Kliencie,

Ustawa, która weszła w życie 1 czerwca 2007 r., dotycząca rozporządzenia UE w sprawie stosowania chemikaliów (WE) nr 1907/2006, (REACH - rejestracja, ocena, zezwolenie i ograniczanie obrotu chemikaliów) ma na celu zapewnienie ochrony zdrowia ludzkiego oraz środowiska naturalnego przed potencjalnymi ryzykami związanymi z chemikaliami.

Daimler Truck AG wspiera realizację celów REACH. W art. 33 tego aktu prawnego przewidziano informowanie klientów o substancjach w naszych produktach, wzbudzających szczególnie duże obawy (SVHC). Celem tej wytycznej regulacji jest zapewnienie bezpiecznego obchodzenia się ze zdefiniowanymi substancjami przez cały cykl życia produktu.

Na podstawie wytycznej ustawowej i z uwzględnieniem informacji dostawców Daimler Truck AG zidentyfikowane zostały następujące substancje, których zawartość w poszczególnych wyrobach tego pojazdu przekracza 0,1 procenta wagowego. W przypadku użytkowania pojazdu zgodnie z przeznaczeniem nie ma zagrożenia dla ludzi i środowiska naturalnego. Dalsze informacje w zakresie bezpiecznego użytkowania pojazdu są dostępne w instrukcji obsługi.

Proszę pamiętać, że w akumulatorze rozruchowym, w stopach, powłokach, elementach szklanych/ceramicznych/elastomerowych oraz w różnych elementach elektronicznych (przede wszystkim w lutach) zawarty jest ołów (nr CAS 7439-92-1).

| Grupa produktów                     | Nazwa substancji                                            | Nr CAS     |
|-------------------------------------|-------------------------------------------------------------|------------|
| <b>Akumulator Sieci Pokładowej</b>  | Lead-monoxide                                               | 1317-36-8  |
|                                     | Diboron-trioxide                                            | 1303-86-2  |
|                                     | Lead(II,IV)-oxide                                           | 1314-41-6  |
| <b>Amortyzowany Fotel</b>           | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Antena Ciśnienia W Oponach</b>   | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Błotnik</b>                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Cylinder Roboczy</b>             | Imidazolidine-2-thione                                      | 96-45-7    |
|                                     | Lead-monoxide                                               | 1317-36-8  |
| <b>Czujnik Ciśnienia</b>            | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                     | Lead-monoxide                                               | 1317-36-8  |
|                                     | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                     | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Czujnik Przyspieszenia</b>       | Diboron-trioxide                                            | 1303-86-2  |
| <b>Czujnik Siły Hamowania</b>       | Lead-monoxide                                               | 1317-36-8  |
|                                     | Diboron-trioxide                                            | 1303-86-2  |
| <b>Czujnik Temperatury</b>          | TBBA                                                        | 79-94-7    |
| <b>Dioda</b>                        | TBBA                                                        | 79-94-7    |
| <b>Drzwi</b>                        | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Drzwi Boczne</b>                 | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Dźwignia Obsługowa</b>           | Lead-monoxide                                               | 1317-36-8  |
|                                     | Diboron-trioxide                                            | 1303-86-2  |
| <b>Ekran</b>                        | 2-Methylimidazole                                           | 693-98-1   |
|                                     | Lead-monoxide                                               | 1317-36-8  |
|                                     | Diboron-trioxide                                            | 1303-86-2  |
| <b>Elastyczny Przewód Hamulcowy</b> | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Fotel Kierowcy</b>               | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                     | Triphenyl-phosphate                                         | 115-86-6   |

|                                                           |                                                                            |             |
|-----------------------------------------------------------|----------------------------------------------------------------------------|-------------|
| <b>Kamera</b>                                             | Octamethylcyclotetrasiloxane                                               | 556-67-2    |
|                                                           | 2-Methylimidazole                                                          | 693-98-1    |
|                                                           | Decamethylcyclopentasiloxane                                               | 541-02-6    |
|                                                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                                                           | Lead-monoxide                                                              | 1317-36-8   |
|                                                           | Diboron-trioxide                                                           | 1303-86-2   |
|                                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
|                                                           | Refractory ceramic fibres                                                  | 142844-00-6 |
| <b>Kamizelka Odblaskowa</b>                               | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                            | 75980-60-8  |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
| <b>Kierownica</b>                                         | Diboron-trioxide                                                           | 1303-86-2   |
| <b>Klapa</b>                                              | Lead-monoxide                                                              | 1317-36-8   |
| <b>Konwerter Ethernet</b>                                 | C,C'-azodi(formamide)                                                      | 123-77-3    |
| <b>Korek Chłodnicy</b>                                    | Lead-titanium-trioxide                                                     | 12060-00-3  |
|                                                           | Lead-monoxide                                                              | 1317-36-8   |
| <b>Króciec Wkręcany</b>                                   | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| <b>Lampa Sufitowa</b>                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| <b>Lampka Kontrolna</b>                                   | Triphenyl-phosphate                                                        | 115-86-6    |
| <b>Lampka Wewnętrzna</b>                                  | TBBA                                                                       | 79-94-7     |
|                                                           | Melamine                                                                   | 108-78-1    |
| <b>Lusterko</b>                                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
| <b>Lusterko Zew</b>                                       | 2-Methylimidazole                                                          | 693-98-1    |
|                                                           | Lead-monoxide                                                              | 1317-36-8   |
|                                                           | Diboron-trioxide                                                           | 1303-86-2   |
|                                                           | TBBA                                                                       | 79-94-7     |
| <b>Moduł Akumulatora Wysokiego Napięcia</b>               | Triphenyl-phosphate                                                        | 115-86-6    |
|                                                           |                                                                            |             |
| <b>Moduł Ster. Edrive Common Powertrain Controller</b>    | Lead-monoxide                                                              | 1317-36-8   |
|                                                           |                                                                            |             |
|                                                           | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3  |
|                                                           |                                                                            |             |
|                                                           |                                                                            |             |
| <b>Moduł Steruj. Przetwornika Dc/Dc Niskie Napięcie 1</b> | Lead-titanium-trioxide                                                     | 12060-00-3  |
|                                                           | Lead-monoxide                                                              | 1317-36-8   |
|                                                           | Diboron-trioxide                                                           | 1303-86-2   |
|                                                           | TBBA                                                                       | 79-94-7     |
|                                                           | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone                         | 119313-12-1 |
|                                                           |                                                                            |             |
| <b>Moduł Sterujący Air-Processing Unit</b>                | N,N-Dimethylacetamide                                                      | 127-19-5    |
|                                                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                                                           | Lead-monoxide                                                              | 1317-36-8   |
|                                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1    |
|                                                           | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
|                                                           | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                            | 75980-60-8  |
| <b>Moduł Sterujący Air-Processing Unit</b>                |                                                                            |             |
|                                                           | Lead titanium zirconium oxide                                              | 12626-81-2  |
|                                                           | Lead-titanium-trioxide                                                     | 12060-00-3  |
|                                                           | Lead-monoxide                                                              | 1317-36-8   |
| <b>Moduł Sterujący Air-Processing Unit</b>                | Diboron-trioxide                                                           | 1303-86-2   |
|                                                           |                                                                            |             |

|                                                                   |                                                          |            |
|-------------------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Moduł Sterujący<br/>Automatycznej<br/>Klimatyzacji</b>         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                   | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący Bramki<br/>Centralnej</b>                      | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |
| <b>Moduł Sterujący<br/>Czujnika Deszczu i<br/>Światła</b>         | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący<br/>Czujnika Odległości</b>                    | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                   | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |
|                                                                   | TBBA                                                     | 79-94-7    |
| <b>Moduł Sterujący<br/>Czujnika Radar.<br/>Bliskiego Zasięgu</b>  | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący<br/>Elektronicznej Stacyjki<br/>Zapłonu</b>    | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                   | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący<br/>Falownika</b>                              | 2-Methylimidazole                                        | 693-98-1   |
|                                                                   | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                                   | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |
|                                                                   | TBBA                                                     | 79-94-7    |
| <b>Moduł Sterujący<br/>Kamery<br/>Wielofunkcyjnej</b>             | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                   | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |
|                                                                   | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <b>Moduł Sterujący<br/>Kierowanej Osi<br/>Dodatkowej</b>          | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                                   | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Moduł Sterujący M.<br/>Odczyt. Sygn. i Real.<br/>Zast. Fhs</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                                   | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |
| <b>Moduł Sterujący<br/>Modułu Drzwi Kierowcy</b>                  | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |
| <b>Moduł Sterujący<br/>Modułu Drzwi Pasażera<br/>Z Przodu</b>     | Lead-monoxide                                            | 1317-36-8  |
|                                                                   | Diboron-trioxide                                         | 1303-86-2  |

|                                                          |                                                          |            |
|----------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Moduł Sterujący Platformy Telematycznej</b>           | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                          | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
| <b>Moduł Sterujący Poduszki Powietrznej</b>              | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
|                                                          | TBBA                                                     | 79-94-7    |
| <b>Moduł Sterujący Sterowania Ładowaniem</b>             | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
|                                                          | TBBA                                                     | 79-94-7    |
| <b>Moduł Sterujący Syst. Zarządz. Wydaj. Akumulatora</b> | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący Tachografu</b>                        | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                          | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
|                                                          | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                                                          | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Moduł Sterujący Ukl. Kontroli Ciśnienia W Oponach</b> | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący Układu Poziomowania Nadwozia</b>      | Lead-monoxide                                            | 1317-36-8  |
| <b>Moduł Sterujący Układu Ster. Pracą Skrzyni Biegów</b> | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
| <b>Moduł Sterujący Video Radar Decision Unit</b>         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                          | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
| <b>Moduł Sterujący Wyświetlacza</b>                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                          | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                          | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
|                                                          | 1-Propanol, 2,3-dibromo-                                 | 96-13-9    |
| <b>Moduł Sterujący XMC</b>                               | Lead-monoxide                                            | 1317-36-8  |
|                                                          | Diboron-trioxide                                         | 1303-86-2  |
|                                                          | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |

|                                                     |                                                                                                                                              |             |
|-----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Moduł Sterujący</b><br><b>Zestawu Wskaźników</b> | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                     | TBBA                                                                                                                                         | 79-94-7     |
| <b>Modulator Osi</b>                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Oś</b>                                           | Boric acid                                                                                                                                   | 10043-35-3  |
|                                                     | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                                                     | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                     | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                     | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                     | Tris(nonylphenyl)phosphite                                                                                                                   | 26523-78-4  |
|                                                     | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                                                             | 2451-62-9   |
|                                                     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                     | Chromium-trioxide                                                                                                                            | 1333-82-0   |
|                                                     | Hexahydromethylphthalic-anhydride                                                                                                            | 25550-51-0  |
|                                                     | Paraffin oils, chloro                                                                                                                        | 85422-92-0  |
|                                                     | TBBA                                                                                                                                         | 79-94-7     |
|                                                     | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                                     | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                     | O,O,O-Triphenyl phosphorothioate                                                                                                             | 597-82-0    |
| <b>Oś Napędzana</b>                                 | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                                     | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                     | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                     | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                     | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                     | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                     | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                     | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                     | TBBA                                                                                                                                         | 79-94-7     |
|                                                     | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                     | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                                     | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Panel Obsługi</b>                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Panel Sterowania</b>                             | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | TBBA                                                                                                                                         | 79-94-7     |
| <b>Parownik</b>                                     | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Paski Filcu</b>                                  | Disodium-octaborate                                                                                                                          | 12008-41-2  |
| <b>Pedał Gazu</b>                                   | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                     | TBBA                                                                                                                                         | 79-94-7     |

|                                |                                                             |            |
|--------------------------------|-------------------------------------------------------------|------------|
| <b>Pierścień Typu O</b>        | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| <b>Podkładka</b>               |                                                             |            |
| <b>Zabezpieczająca</b>         | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Poduszka</b>                |                                                             |            |
| <b>Pneumatyczna</b>            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| <b>Pokrywa Gniazda</b>         | Bumetrizole                                                 | 3896-11-5  |
| <b>Pompa Wodna</b>             | Lead-monoxide                                               | 1317-36-8  |
|                                | Diboron-trioxide                                            | 1303-86-2  |
|                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Przełącznik Klawiszowy</b>  | Lead-monoxide                                               | 1317-36-8  |
|                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Przełącznik Kolumny</b>     |                                                             |            |
| <b>Kierownicy</b>              | Lead-monoxide                                               | 1317-36-8  |
|                                | TBBA                                                        | 79-94-7    |
| <b>Przełącznik Kołyskowy</b>   | Lead-monoxide                                               | 1317-36-8  |
|                                | TBBA                                                        | 79-94-7    |
| <b>Przetwornik Napięcia</b>    | Melamine                                                    | 108-78-1   |
| <b>Przycisk</b>                | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                                | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                                | Lead-monoxide                                               | 1317-36-8  |
|                                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Reflektor</b>               | Lead-monoxide                                               | 1317-36-8  |
| <b>Rozdzielacz Energii</b>     | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                                | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                                | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Sąsiedni Fotel Kierowcy</b> | C,C'-azodi(formamide)                                       | 123-77-3   |
|                                | Melamine                                                    | 108-78-1   |
|                                | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Siatka Na Bagaże</b>        | N,N-Dimethylacetamide                                       | 127-19-5   |
| <b>Silnik Wycieraczek</b>      | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol             | 25973-55-1 |
| <b>Sprężarka Układu</b>        |                                                             |            |
| <b>Klimatyzacji</b>            | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                | 2-Methylimidazole                                           | 693-98-1   |
|                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5 |
|                                | Lead-monoxide                                               | 1317-36-8  |
|                                | Diboron-trioxide                                            | 1303-86-2  |
|                                | Tris(nonylphenyl)phosphite                                  | 26523-78-4 |
| <b>Śruba Z Łbem</b>            |                                                             |            |
| <b>Sześciokątnym</b>           | Diboron-trioxide                                            | 1303-86-2  |
| <b>Śruba Z Okrągłym Łbem</b>   |                                                             |            |
| <b>Sześciokątnym</b>           | Diboron-trioxide                                            | 1303-86-2  |
| <b>Światło Obrysowe</b>        | TBBA                                                        | 79-94-7    |
|                                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Szyba Boczna</b>            | Diboron-trioxide                                            | 1303-86-2  |
| <b>Tuleja Prowadząca</b>       | Imidazolidine-2-thione                                      | 96-45-7    |
| <b>Tylne Światło Pozycyjne</b> | Lead-monoxide                                               | 1317-36-8  |
|                                | TBBA                                                        | 79-94-7    |
|                                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |

|                                       |                                          |            |
|---------------------------------------|------------------------------------------|------------|
| <b>Układ Klimatyzacji</b>             | Lead-monoxide                            | 1317-36-8  |
| <b>Układ Ogrzewania</b>               | Lead-titanium-trioxide                   | 12060-00-3 |
|                                       | Lead-monoxide                            | 1317-36-8  |
|                                       | Diboron-trioxide                         | 1303-86-2  |
| <b>Urządzenie Sterujące</b>           |                                          |            |
| <b>Czujnika Kąta Skrętu</b>           | Lead-monoxide                            | 1317-36-8  |
|                                       | Diboron-trioxide                         | 1303-86-2  |
| <b>Uszczelka</b>                      | Bis(alpha,alpha-dimethylbenzyl) peroxide | 80-43-3    |
| <b>Uszczelka Profilowana</b>          | C,C'-azodi(formamide)                    | 123-77-3   |
| <b>Wentylator</b>                     | TBBA                                     | 79-94-7    |
|                                       | Bis(alpha,alpha-dimethylbenzyl) peroxide | 80-43-3    |
| <b>Wiązka Przewodów Elektrycznych</b> | Melamine                                 | 108-78-1   |
|                                       | Bis(alpha,alpha-dimethylbenzyl) peroxide | 80-43-3    |
| <b>Włącznik Światła</b>               | Lead-monoxide                            | 1317-36-8  |
| <b>Wzmacniacz Anteny</b>              | Lead-monoxide                            | 1317-36-8  |
|                                       | Diboron-trioxide                         | 1303-86-2  |
| <b>Zamek Drzwi</b>                    | Triphenyl-phosphate                      | 115-86-6   |
| <b>Żarówka</b>                        | Diboron-trioxide                         | 1303-86-2  |
| <b>Zaślepka</b>                       | Bumetrizole                              | 3896-11-5  |
| <b>Zawór</b>                          |                                          |            |
| <b>Elektromagnetyczny</b>             | Dodecamethylcyclohexasiloxane            | 540-97-6   |
| <b>Zespół Złączy</b>                  |                                          |            |
| <b>Multimedialnych</b>                | Lead-monoxide                            | 1317-36-8  |
|                                       | Diboron-trioxide                         | 1303-86-2  |
| <b>Zestaw Kluczy</b>                  | 1,2-Dimethoxyethane                      | 110-71-4   |

Caro/a cliente,

A legislação relativa ao regulamento de produtos químicos na UE (CE) n.º 1907/2006 (REACH - registo, avaliação, autorização e restrição dos produtos químicos), em vigor desde 1 de junho de 2007, tem como objetivo garantir a proteção da saúde humana e do ambiente contra os eventuais riscos resultantes de produtos químicos.

A Daimler Truck AG apoia os objetivos do REACH. O artigo 33.º da legislação prevê que, enquanto cliente, deverá estar informado sobre a presença de substâncias que suscitem elevada preocupação (SVHC) nos nossos produtos. Esta diretriz tem como objetivo assegurar o manuseamento seguro dos materiais definidos ao longo da vida útil do produto.

Com base nos requisitos legais e tendo em conta as informações dos fornecedores da Daimler Truck AG, foram identificados os seguintes materiais que acusaram mais de 0,1% (percentagem em peso) em produtos deste veículo. Não há qualquer perigo para pessoas e para o ambiente nas condições de utilização previstas para o veículo. Poderá encontrar mais informações sobre a utilização segura do seu veículo no manual de instruções.

Ter atenção à presença adicional da substância chumbo (n.º CAS 7439-92-1) na bateria do motor de arranque, em ligas, revestimentos, componentes de vidro/cerâmica/elastómeros, bem como em diversos componentes eletrónicos (sobretudo na solda).

| Grupo de produtos                           | Nome da substância                                          | N.º CAS    |
|---------------------------------------------|-------------------------------------------------------------|------------|
| <b>Acumulador Elétrico Da Rede De Bordo</b> | Lead-monoxide                                               | 1317-36-8  |
|                                             | Diboron-trioxide                                            | 1303-86-2  |
|                                             | Lead(II,IV)-oxide                                           | 1314-41-6  |
| <b>Alavanca De Comando</b>                  | Lead-monoxide                                               | 1317-36-8  |
|                                             | Diboron-trioxide                                            | 1303-86-2  |
| <b>Amplificador De Antena</b>               | Lead-monoxide                                               | 1317-36-8  |
|                                             | Diboron-trioxide                                            | 1303-86-2  |
| <b>Anel O-Ring</b>                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| <b>Antena Do Sensor De Pressão Do Pneu</b>  | Lead titanium zirconium oxide                               | 12626-81-2 |
| <b>Aparelho De Operacao</b>                 | Lead-monoxide                                               | 1317-36-8  |
|                                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Aquecimento</b>                          | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                             | Lead-monoxide                                               | 1317-36-8  |
|                                             | Diboron-trioxide                                            | 1303-86-2  |
| <b>Ar-Condicionado</b>                      | Lead-monoxide                                               | 1317-36-8  |
| <b>Banco Do Acompanhante</b>                | C,C'-azodi(formamide)                                       | 123-77-3   |
|                                             | Melamine                                                    | 108-78-1   |
|                                             | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Banco Do Motorista</b>                   | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                             | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Banco Oscilante</b>                      | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Bocal Roscado</b>                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Bomba Do Líquido De Arrefecimento</b>    | Lead-monoxide                                               | 1317-36-8  |
|                                             | Diboron-trioxide                                            | 1303-86-2  |
|                                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Bujao De Fechamento</b>                  | Bumetrizole                                                 | 3896-11-5  |
| <b>Câmera</b>                               | Octamethylcyclotetrasiloxane                                | 556-67-2   |

|                                   |                                                                                                   |             |
|-----------------------------------|---------------------------------------------------------------------------------------------------|-------------|
| Câmera                            | 2-Methylimidazole                                                                                 | 693-98-1    |
|                                   | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                                   | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5  |
|                                   | Lead-monoxide                                                                                     | 1317-36-8   |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2   |
|                                   | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6    |
|                                   | Refractory ceramic fibres                                                                         | 142844-00-6 |
| Chicote Elétrico                  | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                   | 75980-60-8  |
|                                   | Melamine                                                                                          | 108-78-1    |
|                                   | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                          | 80-43-3     |
| Cilindro De Acionamento           | Imidazolidine-2-thione                                                                            | 96-45-7     |
|                                   | Lead-monoxide                                                                                     | 1317-36-8   |
| Colete Refletivo                  | Diboron-trioxide                                                                                  | 1303-86-2   |
| Compressor Do Agente Refrigerante | 4,4'-Isopropylidenediphenol                                                                       | 80-05-7     |
|                                   | 2-Methylimidazole                                                                                 | 693-98-1    |
|                                   | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5  |
|                                   | Lead-monoxide                                                                                     | 1317-36-8   |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2   |
|                                   | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4  |
| Conversor De Ethernet             | Lead-titanium-trioxide                                                                            | 12060-00-3  |
|                                   | Lead-monoxide                                                                                     | 1317-36-8   |
| Diodo                             | TBBA                                                                                              | 79-94-7     |
| Disco Obturador                   | Imidazolidine-2-thione                                                                            | 96-45-7     |
| Distribuidor De Energia           | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                                   | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                                   | Dodecamethylcyclohexasiloxane                                                                     | 540-97-6    |
| Eixo                              | Boric acid                                                                                        | 10043-35-3  |
|                                   | Imidazolidine-2-thione                                                                            | 96-45-7     |
|                                   | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                                   | 2-Methylimidazole                                                                                 | 693-98-1    |
|                                   | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                                   | Lead-monoxide                                                                                     | 1317-36-8   |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2   |
|                                   | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4  |
|                                   | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                  | 2451-62-9   |
|                                   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1    |
|                                   | Chromium-trioxide                                                                                 | 1333-82-0   |
|                                   | Hexahydromethylphthalic-anhydride                                                                 | 25550-51-0  |
|                                   | Paraffin oils, chloro                                                                             | 85422-92-0  |
|                                   | TBBA                                                                                              | 79-94-7     |
|                                   | Phenol, methylstyrenated                                                                          | 68512-30-1  |
|                                   | Triphenyl-phosphate                                                                               | 115-86-6    |
| Eixo Motriz                       | O,O,O-Triphenyl phosphorothioate                                                                  | 597-82-0    |
|                                   | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9  |
|                                   | N,N-Dimethylacetamide                                                                             | 127-19-5    |
|                                   | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |

|                                                          |                                                                                                                                              |             |
|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Eixo Motriz</b>                                       | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                          | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                          | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                          | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                          | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                          | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                          | TBBA                                                                                                                                         | 79-94-7     |
|                                                          | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
| <b>Espelho</b>                                           | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                                          | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                          | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Espelho Externo</b>                                   | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                          | TBBA                                                                                                                                         | 79-94-7     |
| <b>Evaporador</b>                                        | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Farol</b>                                             | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Fechadura Da Porta</b>                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Fita De Filtro</b>                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Fole Da Suspensão</b>                                 | Disodium-octaborate                                                                                                                          | 12008-41-2  |
| <b>Interruptor</b>                                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                          | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                          | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                          | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                          | TBBA                                                                                                                                         | 79-94-7     |
| <b>Interruptor Combinado</b>                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Interruptor Das Luzes</b>                             | TBBA                                                                                                                                         | 79-94-7     |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Jogo De Chaves</b>                                    | 1,2-Dimethoxyethane                                                                                                                          | 110-71-4    |
| <b>Lâmp.Incan</b>                                        | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Lampada Interna</b>                                   | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Lanterna De Marcação</b>                              | TBBA                                                                                                                                         | 79-94-7     |
|                                                          | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Lanterna Do Teto</b>                                  | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Lanterna Traseira</b>                                 | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                          | TBBA                                                                                                                                         | 79-94-7     |
|                                                          | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Luz-Piloto</b>                                        | TBBA                                                                                                                                         | 79-94-7     |
|                                                          | Melamine                                                                                                                                     | 108-78-1    |
| <b>Mód. De Com. Do Mód. De Reg. e Ativ. Do Sinal Fhs</b> | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                          | Lead-monoxide                                                                                                                                | 1317-36-8   |

|                                             |                                                                                                                            |                                                             |
|---------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| De Reg. e Ativ. Do Sinal                    | Diboron-trioxide                                                                                                           | 1303-86-2                                                   |
| Modulador Do Eixo                           | Lead-monoxide                                                                                                              | 1317-36-8                                                   |
| Módulo Comando, Climatização Automática     | Lead-titanium-trioxide<br>Lead-monoxide                                                                                    | 12060-00-3<br>1317-36-8                                     |
| Módulo Comando, Controle Pressão Pneus      | Lead-monoxide                                                                                                              | 1317-36-8                                                   |
| Módulo Comando, Unidade Processamento Ar    | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                               | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2          |
| Módulo Da Bateria De Alta Voltagem          | Lead-monoxide                                                                                                              | 1317-36-8                                                   |
|                                             | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                                                 | 29420-49-3                                                  |
| Módulo De Comando Da Câmera Multifuncional  | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Pitch, coal tar, high-temp.                                 | 12060-00-3<br>1317-36-8<br>1303-86-2<br>65996-93-2          |
| Módulo De Comando Da Porta Motorista        | Lead-monoxide<br>Diboron-trioxide                                                                                          | 1317-36-8<br>1303-86-2                                      |
| Módulo De Comando Da Regulagem Do Nível     | Lead-monoxide                                                                                                              | 1317-36-8                                                   |
| Módulo De Comando Do Airbag                 | Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                  | 1317-36-8<br>1303-86-2<br>79-94-7                           |
| Módulo De Comando Do Comando Da Transmissão | Lead-monoxide<br>Diboron-trioxide                                                                                          | 1317-36-8<br>1303-86-2                                      |
| Módulo De Comando Do Controle De Recarga    | Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                  | 1317-36-8<br>1303-86-2<br>79-94-7                           |
| Módulo De Comando Do Conversor              | 2-Methylimidazole<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA | 693-98-1<br>71868-10-5<br>1317-36-8<br>1303-86-2<br>79-94-7 |
| Módulo De Comando Do Display                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                   | 71868-10-5                                                  |

|                                                  |                                                          |             |
|--------------------------------------------------|----------------------------------------------------------|-------------|
| Display                                          | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                  | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
|                                                  | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| Módulo De Comando Do Edrive Do Cpc               | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                  | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
|                                                  | TBBA                                                     | 79-94-7     |
|                                                  | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| Módulo De Comando Do Gateway Central             | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
| Módulo De Comando Do Sensor De Ângulo De Viragem | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
| Módulo De Comando Do Sensor De Distância         | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                  | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
|                                                  | TBBA                                                     | 79-94-7     |
| Módulo De Comando Do Sensor De Luz-Chuva         | Lead-monoxide                                            | 1317-36-8   |
| Módulo De Comando Do Tacógrafo                   | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                  | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                  | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
|                                                  | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
|                                                  | Triphenyl-phosphate                                      | 115-86-6    |
| Modulo De Comando XMC                            | Lead-monoxide                                            | 1317-36-8   |
|                                                  | Diboron-trioxide                                         | 1303-86-2   |
|                                                  | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9  |
| Módulo De Comando, Conversor Dc/Dc               | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                  | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                  | Lead-monoxide                                            | 1317-36-8   |
|                                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                  | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                  | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| Módulo De Comando, Eixo Dirigível                | Lead-monoxide                                            | 1317-36-8   |
|                                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| Módulo De Comando, Ignição Eletrônica            | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                  | Lead-monoxide                                            | 1317-36-8   |

|                                                      |                                                                                                                                                        |                                                               |
|------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Módulo De Comando,<br/>Painel Instrumentos</b>    | 4,4'-Isopropylidenediphenol<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                               | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7                  |
| <b>Módulo De Comando,<br/>Plataforma Telemática</b>  | 4,4'-Isopropylidenediphenol<br>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide | 80-05-7<br>71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2 |
| <b>Módulo De Comando,<br/>Porta Acompanhante</b>     | Lead-monoxide<br>Diboron-trioxide                                                                                                                      | 1317-36-8<br>1303-86-2                                        |
| <b>Módulo De Comando,<br/>Sistema Da Bateria</b>     | Lead-monoxide                                                                                                                                          | 1317-36-8                                                     |
| <b>Módulo De Comando,<br/>Unidade Vídeo Radar</b>    | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                                            | 12060-00-3<br>1317-36-8<br>1303-86-2                          |
| <b>Módulo De<br/>Comando,Radar Curto<br/>Alcance</b> | Lead-monoxide                                                                                                                                          | 1317-36-8                                                     |
| <b>Motor Do Limpador</b>                             | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                                                                                                        | 25973-55-1                                                    |
| <b>Painel De Interruptores</b>                       | Lead-monoxide<br>TBBA                                                                                                                                  | 1317-36-8<br>79-94-7                                          |
| <b>Paraf.Cab.Sextav.</b>                             | Diboron-trioxide                                                                                                                                       | 1303-86-2                                                     |
| <b>Paraf.Sextav.Red.</b>                             | Diboron-trioxide                                                                                                                                       | 1303-86-2                                                     |
| <b>Para-Lama</b>                                     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                            | 3147-75-9                                                     |
| <b>Passa Cabo</b>                                    | Imidazolidine-2-thione                                                                                                                                 | 96-45-7                                                       |
| <b>Pedal Do Acelerador</b>                           | Lead-monoxide<br>TBBA                                                                                                                                  | 1317-36-8<br>79-94-7                                          |
| <b>Porta</b>                                         | Triphenyl-phosphate                                                                                                                                    | 115-86-6                                                      |
| <b>Porta Lateral</b>                                 | Triphenyl-phosphate                                                                                                                                    | 115-86-6                                                      |
| <b>Portinhola</b>                                    | C,C'-azodi(formamide)                                                                                                                                  | 123-77-3                                                      |
| <b>Rede Para Bagagens</b>                            | N,N-Dimethylacetamide                                                                                                                                  | 127-19-5                                                      |
| <b>Sensor Da Potência De<br/>Frenagem</b>            | Lead-monoxide<br>Diboron-trioxide                                                                                                                      | 1317-36-8<br>1303-86-2                                        |
| <b>Sensor De Aceleração</b>                          | Diboron-trioxide                                                                                                                                       | 1303-86-2                                                     |
| <b>Sensor De Pressão</b>                             | Lead titanium zirconium oxide<br>Lead-monoxide<br>1,2-Dimethoxyethane<br>1,3-Propanesultone                                                            | 12626-81-2<br>1317-36-8<br>110-71-4<br>1120-71-4              |
| <b>Sensor De Temperatura</b>                         | TBBA                                                                                                                                                   | 79-94-7                                                       |
| <b>Tampa Da Tomada</b>                               | Bumetrizole                                                                                                                                            | 3896-11-5                                                     |

|                               |                                              |           |
|-------------------------------|----------------------------------------------|-----------|
| <b>Tampa De Fechamento</b>    |                                              |           |
| <b>Do Radiador</b>            | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3   |
| <b>Tela</b>                   | 2-Methylimidazole                            | 693-98-1  |
|                               | Lead-monoxide                                | 1317-36-8 |
|                               | Diboron-trioxide                             | 1303-86-2 |
| <b>Transformador De</b>       |                                              |           |
| <b>Tensão</b>                 | Melamine                                     | 108-78-1  |
| <b>Tubo Flexível Do Freio</b> | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol | 119-47-1  |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3   |
| <b>Unidade De Conexão Da</b>  |                                              |           |
| <b>Multimídia</b>             | Lead-monoxide                                | 1317-36-8 |
|                               | Diboron-trioxide                             | 1303-86-2 |
| <b>Unidade De Operacao</b>    | Lead-monoxide                                | 1317-36-8 |
| <b>Válvula</b>                |                                              |           |
| <b>Eletromagnética</b>        | Dodecamethylcyclohexasiloxane                | 540-97-6  |
| <b>Vedação</b>                | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3   |
| <b>Vedação De Perfil</b>      | C,C'-azodi(formamide)                        | 123-77-3  |
| <b>Ventilador</b>             | TBBA                                         | 79-94-7   |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide     | 80-43-3   |
| <b>Vidro Lateral</b>          | Diboron-trioxide                             | 1303-86-2 |
| <b>Volante</b>                | Lead-monoxide                                | 1317-36-8 |

Stimată clientă, stimate client,

Legea care a intrat în vigoare la 1 iunie 2007 referitoare la Regulamentul UE (CE) nr. 1907/2006 privind substanțele chimice (REACH - înregistrarea, evaluarea, autorizarea și restricționarea substanțelor chimice) și-a stabilit drept obiectiv protecția sănătății oamenilor și a mediului înconjurător împotriva potențialelor riscuri cauzate de substanțele chimice.

Daimler Truck AG susține obiectivele REACH. Articolul 33 din lege prevede informarea dumneavoastră, în calitate de client, cu privire la substanțele care prezintă motive de îngrijorare deosebită (SVHC) conținute în produsele noastre. Obiectivul acestei cerințe este de a asigura manipularea în siguranță a substanțelor definite, pe tot parcursul ciclului de viață al produsului.

Pe baza cerințelor legale și luând în considerare informațiile puse la dispoziție de furnizorii Daimler Truck AG, au fost identificate următoarele substanțe, care se pot găsi într-un procent de greutate mai mare de 0,1 în componentele individuale ale acestui autovehicul. În cazul utilizării corespunzătoare a autovehiculului, nu există niciun pericol pentru om și mediu. Informații suplimentare despre utilizarea sigură a autovehiculului pot fi găsite în manualul de utilizare.

Vă rugăm să aveți în vedere faptul că în bateria de pornire, în aliaje, în diverse straturi, în componentele din sticlă/ceramică/elastomer, precum și în diverse componente electronice (din toate versiunile) este conținut în plus plumb (nr. CAS 7439-92-1).

| Grup de produse        | Numele substanței                                           | Nr. CAS    |
|------------------------|-------------------------------------------------------------|------------|
| Amplificator Antenă    | Lead-monoxide                                               | 1317-36-8  |
|                        | Diboron-trioxide                                            | 1303-86-2  |
| Antenă Presiune        |                                                             |            |
| Anvelope               | Lead titanium zirconium oxide                               | 12626-81-2 |
| Aparat De Comandă      | Lead-monoxide                                               | 1317-36-8  |
|                        | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Aripă                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Bandă Pâslă            | Disodium-octaborate                                         | 12008-41-2 |
| Baterie Rețea De Bord  | Lead-monoxide                                               | 1317-36-8  |
|                        | Diboron-trioxide                                            | 1303-86-2  |
|                        | Lead(II,IV)-oxide                                           | 1314-41-6  |
| Burdof Pneumatic       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| Buton Cu Apăsare       | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                        | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                        | Lead-monoxide                                               | 1317-36-8  |
|                        | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| Cabla Electric         | Melamine                                                    | 108-78-1   |
|                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Calculator Airbag      | Lead-monoxide                                               | 1317-36-8  |
|                        | Diboron-trioxide                                            | 1303-86-2  |
|                        | TBBA                                                        | 79-94-7    |
| Calculator Climatizare |                                                             |            |
| Automată               | Lead-titanium-trioxide                                      | 12060-00-3 |
|                        | Lead-monoxide                                               | 1317-36-8  |
| Calculator Control     |                                                             |            |
| Presiune Anvelope      | Lead-monoxide                                               | 1317-36-8  |
| Calculator Gateway     |                                                             |            |
| Central                | Lead-monoxide                                               | 1317-36-8  |
|                        | Diboron-trioxide                                            | 1303-86-2  |
| Calculator Senzor De   |                                                             |            |
| Lumină Și Ploaie       | Lead-monoxide                                               | 1317-36-8  |

|                                                        |                                                          |             |
|--------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Calculator Senzor Unghi</b>                         |                                                          |             |
| <b>Bracare</b>                                         | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Diboron-trioxide                                         | 1303-86-2   |
| <b>Calculator Sistem De Comandă A Cutiei De Viteze</b> |                                                          |             |
|                                                        | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Diboron-trioxide                                         | 1303-86-2   |
| <b>Calculator Sistem Management Baterie</b>            | Lead-monoxide                                            | 1317-36-8   |
| <b>Calculator Tahograf</b>                             | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                        | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                        | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Diboron-trioxide                                         | 1303-86-2   |
|                                                        | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
|                                                        | Triphenyl-phosphate                                      | 115-86-6    |
| <b>Calculator Video Radar Decision Unit</b>            | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                        | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Diboron-trioxide                                         | 1303-86-2   |
| <b>Cameră Video</b>                                    | Octamethylcyclotetrasiloxane                             | 556-67-2    |
|                                                        | 2-Methylimidazole                                        | 693-98-1    |
|                                                        | Decamethylcyclopentasiloxane                             | 541-02-6    |
|                                                        | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                        | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Diboron-trioxide                                         | 1303-86-2   |
|                                                        | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                        | Refractory ceramic fibres                                | 142844-00-6 |
|                                                        | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Capac De Închidere Radiator</b>                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Capac Priză</b>                                     | Bumetrizole                                              | 3896-11-5   |
| <b>Cilindru Mobil</b>                                  | Imidazolidine-2-thione                                   | 96-45-7     |
|                                                        | Lead-monoxide                                            | 1317-36-8   |
| <b>Clapetă</b>                                         | C,C'-azodi(formamide)                                    | 123-77-3    |
| <b>Comutator</b>                                       | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Comutator Basculant</b>                             | Lead-monoxide                                            | 1317-36-8   |
|                                                        | TBBA                                                     | 79-94-7     |
| <b>Comutator Levier Pitman</b>                         | Lead-monoxide                                            | 1317-36-8   |
|                                                        | TBBA                                                     | 79-94-7     |
| <b>Comutator Lumină</b>                                | Lead-monoxide                                            | 1317-36-8   |
| <b>Condensator Agent Frigorific</b>                    | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                        | 2-Methylimidazole                                        | 693-98-1    |
|                                                        | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                        | Lead-monoxide                                            | 1317-36-8   |
|                                                        | Diboron-trioxide                                         | 1303-86-2   |
|                                                        | Tris(nonylphenyl)phosphite                               | 26523-78-4  |
| <b>Convertizor Tensiune</b>                            | Melamine                                                 | 108-78-1    |
| <b>Convertor Ethernet</b>                              | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                        | Lead-monoxide                                            | 1317-36-8   |

|                                  |                                                                            |            |
|----------------------------------|----------------------------------------------------------------------------|------------|
| Diodă                            | TBBA                                                                       | 79-94-7    |
| Distribuitor De Energie          | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                  | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                  | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| Dop De Închidere                 | Bumetrizole                                                                | 3896-11-5  |
| Ecran                            | 2-Methylimidazole                                                          | 693-98-1   |
|                                  | Lead-monoxide                                                              | 1317-36-8  |
|                                  | Diboron-trioxide                                                           | 1303-86-2  |
| Far                              | Lead-monoxide                                                              | 1317-36-8  |
| Furtun De Frână                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
|                                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Garnitură Etanșare               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Garnitură Profil                 | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Geam Lateral                     | Diboron-trioxide                                                           | 1303-86-2  |
| Încălzire                        | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                  | Lead-monoxide                                                              | 1317-36-8  |
|                                  | Diboron-trioxide                                                           | 1303-86-2  |
| Încuietoare Ușă                  | Triphenyl-phosphate                                                        | 115-86-6   |
| Instalație De Climatizare        | Lead-monoxide                                                              | 1317-36-8  |
| Lampă Cu Incandescență           | Diboron-trioxide                                                           | 1303-86-2  |
| Lampă De Control                 | TBBA                                                                       | 79-94-7    |
|                                  | Melamine                                                                   | 108-78-1   |
| Lampă De Marcaj                  | TBBA                                                                       | 79-94-7    |
|                                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Lampă Habitaclu                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Lampă Plafon                     | Triphenyl-phosphate                                                        | 115-86-6   |
| Lampă Spate                      | Lead-monoxide                                                              | 1317-36-8  |
|                                  | TBBA                                                                       | 79-94-7    |
|                                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| Manetă Comandă                   | Lead-monoxide                                                              | 1317-36-8  |
|                                  | Diboron-trioxide                                                           | 1303-86-2  |
| Modul Baterie De Înaltă Tensiune | Lead-monoxide                                                              | 1317-36-8  |
|                                  | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| Modulator Punte                  | Lead-monoxide                                                              | 1317-36-8  |
| Motor Ștergători                 | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                            | 25973-55-1 |
| Oglindă                          | 2-Methylimidazole                                                          | 693-98-1   |
|                                  | Lead-monoxide                                                              | 1317-36-8  |
|                                  | Diboron-trioxide                                                           | 1303-86-2  |
| Oglindă Ext                      | TBBA                                                                       | 79-94-7    |
|                                  | Triphenyl-phosphate                                                        | 115-86-6   |
| O-Ring                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
| Panou De Comandă                 | Lead-monoxide                                                              | 1317-36-8  |
|                                  | TBBA                                                                       | 79-94-7    |
| Pedală Accelerație               | Lead-monoxide                                                              | 1317-36-8  |
|                                  | TBBA                                                                       | 79-94-7    |
| Plasă Bagaje                     | N,N-Dimethylacetamide                                                      | 127-19-5   |

|                               |                                                                                                                                              |             |
|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Pompă Lichid De Răcire</b> | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Punte</b>                  | Boric acid                                                                                                                                   | 10043-35-3  |
|                               | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                               | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                               | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                               | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                               | Tris(nonylphenyl)phosphite                                                                                                                   | 26523-78-4  |
|                               | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                                                             | 2451-62-9   |
|                               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                               | Chromium-trioxide                                                                                                                            | 1333-82-0   |
|                               | Hexahydromethylphthalic-anhydride                                                                                                            | 25550-51-0  |
|                               | Paraffin oils, chloro                                                                                                                        | 85422-92-0  |
|                               | TBBA                                                                                                                                         | 79-94-7     |
|                               | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                               | O,O,O-Triphenyl phosphorothioate                                                                                                             | 597-82-0    |
| <b>Punte Motrice</b>          | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                               | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                               | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                               | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                               | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                               | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                               | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                               | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                               | TBBA                                                                                                                                         | 79-94-7     |
|                               | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                               | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Șaibă De Blocare</b>       | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| <b>Scaun Alăturat Șofer</b>   | C,C'-azodi(formamide)                                                                                                                        | 123-77-3    |
|                               | Melamine                                                                                                                                     | 108-78-1    |
|                               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Scaun Pivotant</b>         | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Scaun Șofer</b>            | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                               | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Senzor Accelerație</b>     | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Senzor De Presiune</b>     | Lead titanium zirconium oxide                                                                                                                | 12626-81-2  |
|                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                               | 1,2-Dimethoxyethane                                                                                                                          | 110-71-4    |
|                               | 1,3-Propanesultone                                                                                                                           | 1120-71-4   |

|                                                           |                                                          |             |
|-----------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Senzor De Temperatură</b>                              | TBBA                                                     | 79-94-7     |
| <b>Senzor Valoare De</b>                                  |                                                          |             |
| <b>Frânare</b>                                            | Lead-monoxide                                            | 1317-36-8   |
|                                                           | Diboron-trioxide                                         | 1303-86-2   |
| <b>Set Chei</b>                                           | 1,2-Dimethoxyethane                                      | 110-71-4    |
| <b>Ștuț Cu Înfiletare</b>                                 | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| <b>Supapă Magnetică</b>                                   | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
| <b>Șurub Cu Cap Hexagonal</b>                             | Diboron-trioxide                                         | 1303-86-2   |
| <b>Șurub Cu Cap Hexalobular</b>                           | Diboron-trioxide                                         | 1303-86-2   |
| <b>Trecere Pentru Cabluri</b>                             | Imidazolidine-2-thione                                   | 96-45-7     |
| <b>Unit Cdă Modul Înreg Semnal si Comandă Cab</b>         |                                                          |             |
| <b>Șofer</b>                                              | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                           | Lead-monoxide                                            | 1317-36-8   |
|                                                           | Diboron-trioxide                                         | 1303-86-2   |
| <b>Unit Comandă Edrive Common Powertrain Controller</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                           | Lead-monoxide                                            | 1317-36-8   |
|                                                           | Diboron-trioxide                                         | 1303-86-2   |
|                                                           | TBBA                                                     | 79-94-7     |
|                                                           | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| <b>Unitate Comandă Convertizor Cc/Cc Joasă Tensiune 1</b> | N,N-Dimethylacetamide                                    | 127-19-5    |
|                                                           | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                           | Lead-monoxide                                            | 1317-36-8   |
|                                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                           | Dodecamethylcyclohexasiloxane                            | 540-97-6    |
|                                                           | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8  |
| <b>Unitate Conectare Multimedia</b>                       | Lead-monoxide                                            | 1317-36-8   |
|                                                           | Diboron-trioxide                                         | 1303-86-2   |
| <b>Unitate De Comandă</b>                                 | Lead-monoxide                                            | 1317-36-8   |
| <b>Unitate De Comandă Afișaj</b>                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                           | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                           | Lead-monoxide                                            | 1317-36-8   |
|                                                           | Diboron-trioxide                                         | 1303-86-2   |
|                                                           | 1-Propanol, 2,3-dibromo-                                 | 96-13-9     |
| <b>Unitate De Comandă Cameră Video Multifuncțională</b>   | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                           | Lead-monoxide                                            | 1317-36-8   |
|                                                           | Diboron-trioxide                                         | 1303-86-2   |
|                                                           | Pitch, coal tar, high-temp.                              | 65996-93-2  |
| <b>Unitate De Comandă Contact Electronic</b>              | Lead-titanium-trioxide                                   | 12060-00-3  |

|                               |                                                          |            |
|-------------------------------|----------------------------------------------------------|------------|
| <b>Contact Electronic</b>     | Lead-monoxide                                            | 1317-36-8  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Control Încărcare</b>      | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
|                               | TBBA                                                     | 79-94-7    |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Convertizor</b>            | 2-Methylimidazole                                        | 693-98-1   |
|                               | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                               | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
|                               | TBBA                                                     | 79-94-7    |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Modul Ușă Însotitor</b>    | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Modul Ușă Șofer</b>        | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Platformă Sistem</b>       |                                                          |            |
| <b>Telematic</b>              | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                               | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                               | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Punte Suplimentară</b>     |                                                          |            |
| <b>Conducătoare</b>           | Lead-monoxide                                            | 1317-36-8  |
|                               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Radar Pentru Distanțe</b>  |                                                          |            |
| <b>Scurte</b>                 | Lead-monoxide                                            | 1317-36-8  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Senzor Distanță</b>        | Lead-titanium-trioxide                                   | 12060-00-3 |
|                               | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
|                               | TBBA                                                     | 79-94-7    |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Sistem Reglare Nivel</b>   | Lead-monoxide                                            | 1317-36-8  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Tablou De Bord</b>         | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                               | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
|                               | TBBA                                                     | 79-94-7    |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>Unitate De Procesare A</b> |                                                          |            |
| <b>Aerului</b>                | Lead titanium zirconium oxide                            | 12626-81-2 |
|                               | Lead-titanium-trioxide                                   | 12060-00-3 |
|                               | Lead-monoxide                                            | 1317-36-8  |
|                               | Diboron-trioxide                                         | 1303-86-2  |
| <b>Unitate De Comandă</b>     |                                                          |            |
| <b>XMC</b>                    | Lead-monoxide                                            | 1317-36-8  |

|                              |                                                           |            |
|------------------------------|-----------------------------------------------------------|------------|
| <b>XMC</b>                   | <b>Diboron-trioxide</b>                                   | 1303-86-2  |
|                              | <b>4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride</b> | 19438-60-9 |
| <b>Ușă</b>                   | <b>Triphenyl-phosphate</b>                                | 115-86-6   |
| <b>Ușă Laterală</b>          | <b>Triphenyl-phosphate</b>                                | 115-86-6   |
| <b>Vaporizator</b>           | <b>Lead-monoxide</b>                                      | 1317-36-8  |
|                              | <b>Diboron-trioxide</b>                                   | 1303-86-2  |
| <b>Ventilator</b>            | <b>TBBA</b>                                               | 79-94-7    |
|                              | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>           | 80-43-3    |
| <b>Vestă Reflectorizantă</b> | <b>Diboron-trioxide</b>                                   | 1303-86-2  |
| <b>Volan</b>                 | <b>Lead-monoxide</b>                                      | 1317-36-8  |

Vážená zákazníčka, vážený zákazník,

cieľom zákona, ktorý vstúpil do platnosti dňa 1. júna 2007 a ktorým sa implementuje nariadenie EÚ (ES) č. 1907/2006 o chemikáliách (REACH - registrácia, hodnotenie, autorizácia a obmedzenie chemikálií), je zabezpečiť ochranu ľudského zdravia a životného prostredia pred možnými rizikami vyplývajúcimi z chemikálií.

Spoločnosť Daimler Truck AG podporuje ciele REACH. Článok 33 vo vyššie uvedenom nariadení stanovuje povinnosť informovať vás ako zákazníkov o látkach vzbudzujúcich veľmi veľké obavy (Substances of Very High Concern - SVHC), ktoré sa nachádzajú v našich výrobkoch. Cieľom tohto nariadenia je zabezpečiť bezpečnú manipuláciu so zadanými látkami počas celej doby životnosti výrobku.

Na základe zákonných nariadení a pri zohľadnení údajov od dodávateľov spoločnosti Daimler Truck AG boli identifikované nasledujúce látky, ktoré sa v koncentrácii vyššej ako 0,1 hmotnostného percenta môžu nachádzať v jednotlivých výrobkoch tvoriacich toto vozidlo. Pri používaní vozidla v súlade s jeho určením nehrozí pre človeka a životné prostredie žiadne nebezpečenstvo. Ďalšie informácie o bezpečnom používaní vášho vozidla nájdete vo vašom návode na používanie.

Berte, prosím, do úvahy, že v štartovacom akumulátore, zliatinách, povrchových úpravách, konštrukčných dieloch zo skla, keramiky alebo elastoméru, ako aj v rôznych elektronických konštrukčných dieloch (najmä v spájke) sa nachádza aj olovo (č. CAS 7439-92-1).

| Skupina výrobkov      | Názov látky                                                 | Číslo CAS   |
|-----------------------|-------------------------------------------------------------|-------------|
| Akumulátor Vozidla    | Lead-monoxide                                               | 1317-36-8   |
|                       | Diboron-trioxide                                            | 1303-86-2   |
|                       | Lead(II,IV)-oxide                                           | 1314-41-6   |
| Anténa Snímania Tlaku |                                                             |             |
| V Pneumatikách        | Lead titanium zirconium oxide                               | 12626-81-2  |
| Blatník               | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| Čerpadlo Média        |                                                             |             |
| Chladiaceho           | Lead-monoxide                                               | 1317-36-8   |
|                       | Diboron-trioxide                                            | 1303-86-2   |
|                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Dióda                 | TBBA                                                        | 79-94-7     |
| Dvere                 | Triphenyl-phosphate                                         | 115-86-6    |
| Dvere Bočné           | Triphenyl-phosphate                                         | 115-86-6    |
| Hadica Brzdová        | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
|                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Hrdlo Skrutkované     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| Jednotka Ovládania    | Lead-monoxide                                               | 1317-36-8   |
| Jednotka Pripojovacia |                                                             |             |
| Multimediálna         | Lead-monoxide                                               | 1317-36-8   |
|                       | Diboron-trioxide                                            | 1303-86-2   |
| Kamera                | Octamethylcyclotetrasiloxane                                | 556-67-2    |
|                       | 2-Methylimidazole                                           | 693-98-1    |
|                       | Decamethylcyclopentasiloxane                                | 541-02-6    |
|                       | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                       | Lead-monoxide                                               | 1317-36-8   |
|                       | Diboron-trioxide                                            | 1303-86-2   |
|                       | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
|                       | Refractory ceramic fibres                                   | 142844-00-6 |
|                       | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
| Klapka                | C,C'-azodi(formamide)                                       | 123-77-3    |
| Klimatizácia          | Lead-monoxide                                               | 1317-36-8   |

|                                   |                                                                                                   |            |
|-----------------------------------|---------------------------------------------------------------------------------------------------|------------|
| Kompresor Na Chladivo             | 4,4'-Isopropylidenediphenol                                                                       | 80-05-7    |
|                                   | 2-Methylimidazole                                                                                 | 693-98-1   |
|                                   | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5 |
|                                   | Lead-monoxide                                                                                     | 1317-36-8  |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2  |
| Kontrolka                         | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4 |
|                                   | TBBA                                                                                              | 79-94-7    |
|                                   | Melamine                                                                                          | 108-78-1   |
| Kotúč Uzatvárací                  | Imidazolidine-2-thione                                                                            | 96-45-7    |
| Krúžok O                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1   |
| Kúrenie                           | Lead-titanium-trioxide                                                                            | 12060-00-3 |
|                                   | Lead-monoxide                                                                                     | 1317-36-8  |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2  |
| Menič Napätia                     | Melamine                                                                                          | 108-78-1   |
| Menič Pevnej Siete                | Lead-titanium-trioxide                                                                            | 12060-00-3 |
|                                   | Lead-monoxide                                                                                     | 1317-36-8  |
| Modul Akumulátora Vysokovoltového | Lead-monoxide                                                                                     | 1317-36-8  |
| Modulátor Nápravy                 | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1)                        | 29420-49-3 |
|                                   | Lead-monoxide                                                                                     | 1317-36-8  |
| Motorček Stieračov                | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                                                   | 25973-55-1 |
| Náprava                           | Boric acid                                                                                        | 10043-35-3 |
|                                   | Imidazolidine-2-thione                                                                            | 96-45-7    |
|                                   | Octamethylcyclotetrasiloxane                                                                      | 556-67-2   |
|                                   | 2-Methylimidazole                                                                                 | 693-98-1   |
|                                   | Decamethylcyclopentasiloxane                                                                      | 541-02-6   |
|                                   | Lead-monoxide                                                                                     | 1317-36-8  |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2  |
|                                   | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4 |
|                                   | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                  | 2451-62-9  |
|                                   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1   |
|                                   | Chromium-trioxide                                                                                 | 1333-82-0  |
|                                   | Hexahydromethylphthalic-anhydride                                                                 | 25550-51-0 |
|                                   | Paraffin oils, chloro                                                                             | 85422-92-0 |
|                                   | TBBA                                                                                              | 79-94-7    |
|                                   | Phenol, methylstyrenated                                                                          | 68512-30-1 |
|                                   | Triphenyl-phosphate                                                                               | 115-86-6   |
|                                   | O,O,O-Triphenyl phosphorothioate                                                                  | 597-82-0   |
| Náprava Hnacia                    | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9 |
|                                   | N,N-Dimethylacetamide                                                                             | 127-19-5   |
|                                   | Octamethylcyclotetrasiloxane                                                                      | 556-67-2   |
|                                   | 2-Methylimidazole                                                                                 | 693-98-1   |
|                                   | Decamethylcyclopentasiloxane                                                                      | 541-02-6   |
|                                   | Lead-monoxide                                                                                     | 1317-36-8  |
|                                   | Diboron-trioxide                                                                                  | 1303-86-2  |
|                                   | 4-Nonylphenol, branched                                                                           | 84852-15-3 |
|                                   | Nonylphenol                                                                                       | 25154-52-3 |
|                                   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1   |

|                                                  |                                                                                                                                              |             |
|--------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Náprava Hnacia                                   | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
|                                                  | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                  | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                                  | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Obrazovka                                        | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Ovládacie Pole                                   | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| Páka Ovládacia                                   | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Pedál Akceleračný                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| Prepínač Kolískový                               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| Prepínač Svetiel                                 | Lead-monoxide                                                                                                                                | 1317-36-8   |
| Prepínač Združený                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| Priechodka                                       | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| Prístroj Ovládací                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| Prístroj Riadiaci XMC                            | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                  | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride                                                                                           | 19438-60-9  |
| Prístroj Riadiaci, Airbag                        | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| Prístroj Riadiaci, Displej                       | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                                                                     | 71868-10-5  |
|                                                  | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                  | 1-Propanol, 2,3-dibromo-                                                                                                                     | 96-13-9     |
| Prístroj Riadiaci, Edrive, Kontrolér             | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
|                                                  | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone                                                                                           | 119313-12-1 |
| Prístroj Riadiaci, Jednotka Vrdu                 | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                                  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Prístroj Riadiaci, Jednotka Zásobovania Vzduchom | Lead titanium zirconium oxide                                                                                                                | 12626-81-2  |
|                                                  | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |

|                                                                  |                                                                 |            |
|------------------------------------------------------------------|-----------------------------------------------------------------|------------|
| <b>Jednotka Zásobovania</b>                                      | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2  |
| <b>Prístroj Riadiaci,<br/>Kamera Multifunkčná</b>                | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3 |
|                                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2  |
|                                                                  | <b>Pitch, coal tar, high-temp.</b>                              | 65996-93-2 |
| <b>Prístroj Riadiaci,<br/>Klimatizácia<br/>Automatická</b>       | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3 |
|                                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8  |
| <b>Prístroj Riadiaci,<br/>Kontrola Tlaku<br/>V Pneumatikách</b>  | <b>Lead-monoxide</b>                                            | 1317-36-8  |
| <b>Prístroj Riadiaci, Menič</b>                                  | <b>2-Methylimidazole</b>                                        | 693-98-1   |
|                                                                  | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5 |
|                                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2  |
|                                                                  | <b>TBBA</b>                                                     | 79-94-7    |
| <b>Prístroj Riadiaci, Menič<br/>Jednosmerný Prúd</b>             | <b>N,N-Dimethylacetamide</b>                                    | 127-19-5   |
|                                                                  | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5 |
|                                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>             | 119-47-1   |
|                                                                  | <b>Dodecamethylcyclohexasiloxane</b>                            | 540-97-6   |
|                                                                  | <b>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide</b>          | 75980-60-8 |
| <b>Prístroj Riadiaci, Modul<br/>Dverový, Spolujazdec</b>         | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2  |
| <b>Prístroj Riadiaci, Modul<br/>Dverový, Vodič</b>               | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2  |
| <b>Prístroj Riadiaci, Modul<br/>Riadenia Signálu,<br/>Kabína</b> | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3 |
|                                                                  | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>Diboron-trioxide</b>                                         | 1303-86-2  |
| <b>Prístroj Riadiaci,<br/>Náprava Prídavná<br/>Riadená</b>       | <b>Lead-monoxide</b>                                            | 1317-36-8  |
|                                                                  | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>             | 119-47-1   |
|                                                                  | <b>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                 | 80-43-3    |
| <b>Prístroj Riadiaci,<br/>Platforma Telematická</b>              | <b>4,4'-Isopropylidenediphenol</b>                              | 80-05-7    |
|                                                                  | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5 |
|                                                                  | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3 |

|                                                                  |                                                                                                                                                                        |                                                                              |
|------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>Platforma Telematická</b>                                     | Lead-monoxide<br>Diboron-trioxide                                                                                                                                      | 1317-36-8<br>1303-86-2                                                       |
| <b>Prístroj Riadiaci,<br/>Priechod Sieťový<br/>Centrálly</b>     | Lead-monoxide<br>Diboron-trioxide                                                                                                                                      | 1317-36-8<br>1303-86-2                                                       |
| <b>Prístroj Riadiaci,<br/>Prístroj Združený</b>                  | 4,4'-Isopropylidenediphenol<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                               | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7                                 |
| <b>Prístroj Riadiaci, Radar<br/>S Krátkym Dosahom</b>            | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Prístroj Riadiaci,<br/>Regulácia Výšky</b>                    | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Prístroj Riadiaci,<br/>Riadenie Nabíjania</b>                 | Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                                                              | 1317-36-8<br>1303-86-2<br>79-94-7                                            |
| <b>Prístroj Riadiaci,<br/>Riadenie Prevodovky</b>                | Lead-monoxide<br>Diboron-trioxide                                                                                                                                      | 1317-36-8<br>1303-86-2                                                       |
| <b>Prístroj Riadiaci,<br/>Snímač Svetelný<br/>Dažd'ový</b>       | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Prístroj Riadiaci,<br/>Snímač Vzdialenosti</b>                | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>TBBA                                                                                                    | 12060-00-3<br>1317-36-8<br>1303-86-2<br>79-94-7                              |
| <b>Prístroj Riadiaci,<br/>Systém Manažmentu<br/>Akumulátora</b>  | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Prístroj Riadiaci,<br/>Tachograf</b>                          | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide<br>Triphenyl-phosphate | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>75980-60-8<br>115-86-6 |
| <b>Prístroj Riadiaci, Zámok<br/>Zapaľovania<br/>Elektronický</b> | Lead-titanium-trioxide<br>Lead-monoxide                                                                                                                                | 12060-00-3<br>1317-36-8                                                      |
| <b>Pruh Plst'ový</b>                                             | Disodium-octaborate                                                                                                                                                    | 12008-41-2                                                                   |
| <b>Riadiaci Prístroj,<br/>Snímač Uhla Natočenia<br/>Kolies</b>   | Lead-monoxide<br>Diboron-trioxide                                                                                                                                      | 1317-36-8<br>1303-86-2                                                       |
| <b>Rozvádzač Elektrickej<br/>Energie</b>                         | Octamethylcyclotetrasiloxane                                                                                                                                           | 556-67-2                                                                     |

|                                       |                                                             |            |
|---------------------------------------|-------------------------------------------------------------|------------|
| <b>Energie</b>                        | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                                       | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Sedadlo Odpružené</b>              | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Sedadlo Vedľajšie Pri Vodičovi</b> | C,C'-azodi(formamide)                                       | 123-77-3   |
|                                       | Melamine                                                    | 108-78-1   |
|                                       | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Sedadlo Vodiča</b>                 | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                       | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Sieť Na Batožinu</b>               | N,N-Dimethylacetamide                                       | 127-19-5   |
| <b>Sklo Bočné</b>                     | Diboron-trioxide                                            | 1303-86-2  |
| <b>Skrutka So Hlavou Šest'hrannou</b> | Diboron-trioxide                                            | 1303-86-2  |
| <b>Skrutka Torx</b>                   | Diboron-trioxide                                            | 1303-86-2  |
| <b>Snímač Teploty</b>                 | TBBA                                                        | 79-94-7    |
| <b>Snímač Tlaku</b>                   | Lead titanium zirconium oxide                               | 12626-81-2 |
|                                       | Lead-monoxide                                               | 1317-36-8  |
|                                       | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                                       | 1,3-Propanesultone                                          | 1120-71-4  |
| <b>Snímač Účinku Brzdného</b>         | Lead-monoxide                                               | 1317-36-8  |
|                                       | Diboron-trioxide                                            | 1303-86-2  |
| <b>Snímač Zrýchlenia</b>              | Diboron-trioxide                                            | 1303-86-2  |
| <b>Spínač Tlačidlový</b>              | Lead-monoxide                                               | 1317-36-8  |
|                                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Súprava Kľúčov</b>                 | 1,2-Dimethoxyethane                                         | 110-71-4   |
| <b>Svetlo Vnútorné</b>                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Svetlomety</b>                     | Lead-monoxide                                               | 1317-36-8  |
| <b>Svietidlá Obrysové</b>             | TBBA                                                        | 79-94-7    |
|                                       | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Svietidlo Stropné</b>              | Triphenyl-phosphate                                         | 115-86-6   |
| <b>Svietidlo Zadné</b>                | Lead-monoxide                                               | 1317-36-8  |
|                                       | TBBA                                                        | 79-94-7    |
|                                       | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| <b>Tesnenie</b>                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Tesnenie Profilované</b>           | C,C'-azodi(formamide)                                       | 123-77-3   |
| <b>Tlačidlo</b>                       | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                                       | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                                       | Lead-monoxide                                               | 1317-36-8  |
|                                       | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Valec Pracovný</b>                 | Imidazolidine-2-thione                                      | 96-45-7    |
|                                       | Lead-monoxide                                               | 1317-36-8  |
| <b>Veko Zásuvky</b>                   | Bumetrizole                                                 | 3896-11-5  |
| <b>Ventil Magnetický</b>              | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| <b>Ventilátor</b>                     | TBBA                                                        | 79-94-7    |
|                                       | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| <b>Vesta Výstražná</b>                | Diboron-trioxide                                            | 1303-86-2  |
| <b>Vlnovec Pruženia</b>               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| <b>Volant</b>                         | Lead-monoxide                                               | 1317-36-8  |
| <b>Výparník</b>                       | Lead-monoxide                                               | 1317-36-8  |
|                                       | Diboron-trioxide                                            | 1303-86-2  |
| <b>Zámok Dverí</b>                    | Triphenyl-phosphate                                         | 115-86-6   |

|                            |                                          |           |
|----------------------------|------------------------------------------|-----------|
| <b>Zátka</b>               | Bumetrizole                              | 3896-11-5 |
| <b>Zátka Chladiča</b>      | Bis(alpha,alpha-dimethylbenzyl) peroxide | 80-43-3   |
| <b>Žiarovka</b>            | Diboron-trioxide                         | 1303-86-2 |
| <b>Zosilňovač Anténový</b> | Lead-monoxide                            | 1317-36-8 |
|                            | Diboron-trioxide                         | 1303-86-2 |
| <b>Zrkadlo</b>             | 2-Methylimidazole                        | 693-98-1  |
|                            | Lead-monoxide                            | 1317-36-8 |
|                            | Diboron-trioxide                         | 1303-86-2 |
| <b>Zrkadlo Vonkajšie</b>   | TBBA                                     | 79-94-7   |
|                            | Triphenyl-phosphate                      | 115-86-6  |
| <b>Zväzok Vedení</b>       |                                          |           |
| <b>Elektrických</b>        | Melamine                                 | 108-78-1  |
|                            | Bis(alpha,alpha-dimethylbenzyl) peroxide | 80-43-3   |

Spoštovana stranka!

Namen zakona o Uredbi (ES) št. 1907/2006 o kemikalijah, (REACH – registracija, evalvacija, avtorizacija in omejevanje kemikalij), ki je začel veljati 1. junija 2007, je varovanje zdravja ljudi in zaščita okolja pred možnimi tveganji zaradi kemikalij.

Podjetje Daimler Truck AG sledi ciljem uredbe o REACH. Člen 33 zakonodajnega akta predvideva, da vas je treba kot stranko obveščati o snoveh, ki vzbujajo veliko zaskrbljenost (SVHC) in jih vsebujejo naši izdelki. Cilj te določbe je zagotoviti varno ravnanje z opredeljenimi snovmi v celotni življenjski dobi izdelka.

Na podlagi pravnih zahtev in ob upoštevanju informacij, ki jih posreduje podjetje Daimler Truck AG, so bile opredeljene naslednje snovi, katerih koncentracija bi lahko bila večja od 0,1 masnega % v posameznem izdelku. Pri predvideni uporabi vozila ni nevarnosti za ljudi in okolje. Več informacij o uporabi svojega vozila lahko najdete v vaših navodilih za uporabo.

Upoštevajte, da je dodatno prisoten svinec (št. CAS 7439-92-1) v zagonskem akumulatorju, v zlitinah, prevlekah, steklenih in keramičnih komponentah ter komponentah iz elastomerov in v različnih elektronskih komponentah (zlasti spajkah).

| Skupina izdelkov                    | Ime snovi                                                   | CAS št.     |
|-------------------------------------|-------------------------------------------------------------|-------------|
| <b>Akumulator</b>                   |                                                             |             |
| <b>Električnega Omrežja</b>         | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
|                                     | Lead(II,IV)-oxide                                           | 1314-41-6   |
| <b>Antena Za Tlak V</b>             |                                                             |             |
| <b>Pnevmatiki</b>                   | Lead titanium zirconium oxide                               | 12626-81-2  |
| <b>Antenski Ojačevalnik</b>         | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
| <b>Blatnik</b>                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| <b>Bočno Steklo</b>                 | Diboron-trioxide                                            | 1303-86-2   |
| <b>Črpalka Za Hladilno Sredstvo</b> | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Delovni Valj</b>                 | Imidazolidine-2-thione                                      | 96-45-7     |
|                                     | Lead-monoxide                                               | 1317-36-8   |
| <b>Dioda</b>                        | TBBA                                                        | 79-94-7     |
| <b>Električni Kabelski Snop</b>     | Melamine                                                    | 108-78-1    |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Enota Za Upravljanje</b>         | Lead-monoxide                                               | 1317-36-8   |
| <b>Gibka Zavorna Cev</b>            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
|                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3     |
| <b>Gretje</b>                       | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                     | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
| <b>Kamera</b>                       | Octamethylcyclotetrasiloxane                                | 556-67-2    |
|                                     | 2-Methylimidazole                                           | 693-98-1    |
|                                     | Decamethylcyclopentasiloxane                                | 541-02-6    |
|                                     | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                     | Lead-monoxide                                               | 1317-36-8   |
|                                     | Diboron-trioxide                                            | 1303-86-2   |
|                                     | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
|                                     | Refractory ceramic fibres                                   | 142844-00-6 |
|                                     | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |

|                                                |                                                          |             |
|------------------------------------------------|----------------------------------------------------------|-------------|
| Klimatska Naprava                              | Lead-monoxide                                            | 1317-36-8   |
| Ključavnica                                    | Triphenyl-phosphate                                      | 115-86-6    |
| Klobučevinasti Trak                            | Disodium-octaborate                                      | 12008-41-2  |
| Komplet Ključev                                | 1,2-Dimethoxyethane                                      | 110-71-4    |
| Kompresor Hladilnega Sredstva                  | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | 2-Methylimidazole                                        | 693-98-1    |
|                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | Tris(nonylphenyl)phosphite                               | 26523-78-4  |
| Kontrolna Lučka                                | TBBA                                                     | 79-94-7     |
|                                                | Melamine                                                 | 108-78-1    |
| Krmilnik, Avtomatska Klimatska Naprava         | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| Krmilnik, Centralni Gateway                    | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| Krmilnik, Edrive, Common Powertrain Controller | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
|                                                | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone       | 119313-12-1 |
| Krmilnik, Elektronska Zagonska Ključavnica     | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
| Krmilnik, Enota Za Oskrbo Z Zrakom             | Lead titanium zirconium oxide                            | 12626-81-2  |
|                                                | Lead-titanium-trioxide                                   | 12060-00-3  |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
| Krmilnik, Kombinirani Inštrument               | 4,4'-Isopropylidenediphenol                              | 80-05-7     |
|                                                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |
|                                                | TBBA                                                     | 79-94-7     |
| Krmilnik, Kontrola Tlaka V Pnevmatikah         | Lead-monoxide                                            | 1317-36-8   |
| Krmilnik, Krmiljena Dodatna Prema              | Lead-monoxide                                            | 1317-36-8   |
|                                                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1    |
|                                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3     |
| Krmilnik, Krmiljenje Menjalnika                | Lead-monoxide                                            | 1317-36-8   |
|                                                | Diboron-trioxide                                         | 1303-86-2   |

|                                                    |                                                          |            |
|----------------------------------------------------|----------------------------------------------------------|------------|
| Krmilnik, Krmiljenje Polnjenja                     | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
|                                                    | TBBA                                                     | 79-94-7    |
| Krmilnik, Modul Za Zaj.Signalov in Krm., Fhs       | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
| Krmilnik, Pretvornik                               | 2-Methylimidazole                                        | 693-98-1   |
|                                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
|                                                    | TBBA                                                     | 79-94-7    |
| Krmilnik, Pretvornik Dc/Dc, Nizkovoltna Napetost 1 | N,N-Dimethylacetamide                                    | 127-19-5   |
|                                                    | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                                    | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
|                                                    | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
| Krmilnik, Prikazovalnik                            | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                    | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
|                                                    | 1-Propanol, 2,3-dibromo-                                 | 96-13-9    |
| Krmilnik, Radar                                    |                                                          |            |
| Kratkega Dosega                                    | Lead-monoxide                                            | 1317-36-8  |
| Krmilnik, Regulacija Nivoja Podvozja               | Lead-monoxide                                            | 1317-36-8  |
| Krmilnik, Senzor Kota Zavijanja                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
| Krmilnik, Senzor Razdalje                          | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
|                                                    | TBBA                                                     | 79-94-7    |
| Krmilnik, Senzor Za Dež In Osvetljenost            | Lead-monoxide                                            | 1317-36-8  |
| Krmilnik, Sistem Upravljanja Energije              |                                                          |            |
| Akumulatorja                                       | Lead-monoxide                                            | 1317-36-8  |
| Krmilnik, Tahograf                                 | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                    | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                    | Lead-monoxide                                            | 1317-36-8  |
|                                                    | Diboron-trioxide                                         | 1303-86-2  |
|                                                    | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                                                    | Triphenyl-phosphate                                      | 115-86-6   |

|                                            |                                                                            |            |
|--------------------------------------------|----------------------------------------------------------------------------|------------|
| <b>Krmilnik, Telematska Platforma</b>      | 4,4'-Isopropylidenediphenol                                                | 80-05-7    |
|                                            | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5 |
|                                            | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                            | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Krmilnik, Večfunkcijska Kamera</b>      | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                            | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
|                                            | Pitch, coal tar, high-temp.                                                | 65996-93-2 |
| <b>Krmilnik, Video Radar Decision Unit</b> | Lead-titanium-trioxide                                                     | 12060-00-3 |
|                                            | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Krmilnik, Vratni Modul, Sovoznik</b>    | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Krmilnik, Vratni Modul, Voznik</b>      | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Krmilnik, XMC</b>                       | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
|                                            | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride                         | 19438-60-9 |
| <b>Krmilnik, Zračna Blazina</b>            | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
|                                            | TBBA                                                                       | 79-94-7    |
| <b>Loputa</b>                              | C,C'-azodi(formamide)                                                      | 123-77-3   |
| <b>Magnetni Ventil</b>                     | Dodecamethylcyclotetrasiloxane                                             | 540-97-6   |
| <b>Markirna Luč</b>                        | TBBA                                                                       | 79-94-7    |
|                                            | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Modul Visokovoltnega Akumulatorja</b>   | Lead-monoxide                                                              | 1317-36-8  |
|                                            | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| <b>Modulator Preme</b>                     | Lead-monoxide                                                              | 1317-36-8  |
| <b>Motor Brisalnikov</b>                   | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                            | 25973-55-1 |
| <b>Mreža Za Prtljago</b>                   | N,N-Dimethylacetamide                                                      | 127-19-5   |
| <b>Multimedijska Priključna Enota</b>      | Lead-monoxide                                                              | 1317-36-8  |
|                                            | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Napetostni Pretvornik</b>               | Melamine                                                                   | 108-78-1   |
| <b>Notranja Luč</b>                        | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9  |
| <b>Obvolansko Stikalo</b>                  | Lead-monoxide                                                              | 1317-36-8  |
|                                            | TBBA                                                                       | 79-94-7    |
| <b>Odsevni Jopič</b>                       | Diboron-trioxide                                                           | 1303-86-2  |
| <b>Ogledalo</b>                            | 2-Methylimidazole                                                          | 693-98-1   |
|                                            | Lead-monoxide                                                              | 1317-36-8  |

|                                    |                                                                                                                                              |             |
|------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Ogledalo                           | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| Ogledalo, Zunaj                    | TBBA                                                                                                                                         | 79-94-7     |
|                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| O-Tesnilo                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| Pedal Za Plin                      | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
| Pogonska Prema                     | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                    | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                    | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                    | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                    | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                    | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                    | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                    | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                    | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
|                                    | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                    | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Pokrov Vtičnice                    | Bumetrizole                                                                                                                                  | 3896-11-5   |
| Pokrovček Hladilnika               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| Pomožni Sedež Ob Voznikovem Sedežu | C,C'-azodi(formamide)                                                                                                                        | 123-77-3    |
|                                    | Melamine                                                                                                                                     | 108-78-1    |
|                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| Prehodni Tulec                     | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
| Prema                              | Boric acid                                                                                                                                   | 10043-35-3  |
|                                    | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |
|                                    | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                    | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                    | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                    | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                    | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                    | Tris(nonylphenyl)phosphite                                                                                                                   | 26523-78-4  |
|                                    | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                                                             | 2451-62-9   |
|                                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                    | Chromium-trioxide                                                                                                                            | 1333-82-0   |
|                                    | Hexahydromethylphthalic-anhydride                                                                                                            | 25550-51-0  |
|                                    | Paraffin oils, chloro                                                                                                                        | 85422-92-0  |
|                                    | TBBA                                                                                                                                         | 79-94-7     |
|                                    | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                    | O,O,O-Triphenyl phosphorothioate                                                                                                             | 597-82-0    |
| Pretvornik Za Ethernet             | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                    | Lead-monoxide                                                                                                                                | 1317-36-8   |

|                             |                                                             |            |
|-----------------------------|-------------------------------------------------------------|------------|
| Prevesno Stikalo            | Lead-monoxide                                               | 1317-36-8  |
|                             | TBBA                                                        | 79-94-7    |
| Pritisni Gumb               | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                             | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                             | Lead-monoxide                                               | 1317-36-8  |
|                             | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| Profilno Tesnilo            | C,C'-azodi(formamide)                                       | 123-77-3   |
| Razdelilnik Energije        | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                             | Decamethylcyclopentasiloxane                                | 541-02-6   |
|                             | Dodecamethylcyclohexasiloxane                               | 540-97-6   |
| Senzor Stopnje<br>Zaviranja | Lead-monoxide                                               | 1317-36-8  |
|                             | Diboron-trioxide                                            | 1303-86-2  |
| Senzor Tlaka                | Lead titanium zirconium oxide                               | 12626-81-2 |
|                             | Lead-monoxide                                               | 1317-36-8  |
|                             | 1,2-Dimethoxyethane                                         | 110-71-4   |
|                             | 1,3-Propanesultone                                          | 1120-71-4  |
| Senzor Za Pospeševanje      | Diboron-trioxide                                            | 1303-86-2  |
| Šestrobi Vijak              | Diboron-trioxide                                            | 1303-86-2  |
| Stikalo S Tipko             | Lead-monoxide                                               | 1317-36-8  |
|                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Stikalo Za Luči             | Lead-monoxide                                               | 1317-36-8  |
| Stranska Vrata              | Triphenyl-phosphate                                         | 115-86-6   |
| Stropna Luč                 | Triphenyl-phosphate                                         | 115-86-6   |
| Temperaturni Senzor         | TBBA                                                        | 79-94-7    |
| Tesnilo                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Uparjalnik                  | Lead-monoxide                                               | 1317-36-8  |
|                             | Diboron-trioxide                                            | 1303-86-2  |
| Upravljalna Površina        | Lead-monoxide                                               | 1317-36-8  |
|                             | TBBA                                                        | 79-94-7    |
| Upravljalna Ročica          | Lead-monoxide                                               | 1317-36-8  |
|                             | Diboron-trioxide                                            | 1303-86-2  |
| Upravljalnik                | Lead-monoxide                                               | 1317-36-8  |
|                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Ventilator                  | TBBA                                                        | 79-94-7    |
|                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Vijačni Nastavek            | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Vijak torx                  | Diboron-trioxide                                            | 1303-86-2  |
| Volan                       | Lead-monoxide                                               | 1317-36-8  |
| Voznikov Sedež              | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                             | Triphenyl-phosphate                                         | 115-86-6   |
| Vrata                       | Triphenyl-phosphate                                         | 115-86-6   |
| Vzmeteni Sedež              | Triphenyl-phosphate                                         | 115-86-6   |
| Vzmetni Meh                 | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1   |
| Zadnja Luč                  | Lead-monoxide                                               | 1317-36-8  |
|                             | TBBA                                                        | 79-94-7    |
|                             | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Zapiralna Podložka          | Imidazolidine-2-thione                                      | 96-45-7    |
| Zaporni Čep                 | Bumetrizole                                                 | 3896-11-5  |
| Žarnica                     | Diboron-trioxide                                            | 1303-86-2  |
| Žaromet                     | Lead-monoxide                                               | 1317-36-8  |

|                        |                          |           |
|------------------------|--------------------------|-----------|
| <b>Zaslon</b><br><hr/> | <b>2-Methylimidazole</b> | 693-98-1  |
|                        | <b>Lead-monoxide</b>     | 1317-36-8 |
|                        | <b>Diboron-trioxide</b>  | 1303-86-2 |

Estimada cliente/Estimado cliente:

La ley sobre el Reglamento de la Unión Europea n.º 1907/2006, que entró en vigor el 1 de junio de 2007 (REACH - Registro, evaluación, autorización y restricción de las sustancias y preparados químicos), tiene como fin garantizar un nivel elevado de protección de la salud humana y el medio ambiente frente a posibles riesgos debidos a las sustancias y los preparados químicos.

Daimler Truck AG soporta y promueve los objetivos de REACH. El artículo 33 de la regulación trata de la obligación de informarle a usted como cliente sobre las sustancias altamente preocupantes (SVHC) contenidas en nuestros productos. El objetivo de esta prescripción es garantizar una manipulación segura de las sustancias definidas durante el ciclo de vida completo del producto.

De conformidad con las prescripciones legales, y teniendo en cuenta las informaciones de los proveedores de Daimler Truck AG, se han identificado las sustancias siguientes, que pueden formar parte de artículos individuales de este vehículo en una proporción mayor del 0,1 por ciento en peso. De la utilización del vehículo de acuerdo con el uso previsto no se deriva peligro alguno para el hombre o el medio ambiente. Encontrará información adicional acerca del uso seguro de su vehículo en su manual de instrucciones.

Debe tenerse en cuenta que la batería de arranque, algunas aleaciones, revestimientos, componentes de vidrio/cerámica/elastómeros y diversos componentes electrónicos (especialmente soldaduras) contienen plomo (nº CAS 7439-92-1) como sustancia adicional.

| Categoría de productos                 | Nombre de la sustancia                                      | N.º CAS    |
|----------------------------------------|-------------------------------------------------------------|------------|
| Aire Acondicionado                     | Lead-monoxide                                               | 1317-36-8  |
| Amplificador De Antena                 | Lead-monoxide                                               | 1317-36-8  |
|                                        | Diboron-trioxide                                            | 1303-86-2  |
| Antena De La Presión De Los Neumáticos | Lead titanium zirconium oxide                               | 12626-81-2 |
| Aparato De Operacion                   | Lead-monoxide                                               | 1317-36-8  |
|                                        | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9  |
| Asiento Auxiliar                       | C,C'-azodi(formamide)                                       | 123-77-3   |
|                                        | Melamine                                                    | 108-78-1   |
|                                        | Triphenyl-phosphate                                         | 115-86-6   |
| Asiento Del Conductor                  | 4,4'-Isopropylidenediphenol                                 | 80-05-7    |
|                                        | Triphenyl-phosphate                                         | 115-86-6   |
| Asiento Oscilante                      | Triphenyl-phosphate                                         | 115-86-6   |
| Batería De La Red De A Bordo           | Lead-monoxide                                               | 1317-36-8  |
|                                        | Diboron-trioxide                                            | 1303-86-2  |
|                                        | Lead(II,IV)-oxide                                           | 1314-41-6  |
| Bomba De Líquido Refrigerante          | Lead-monoxide                                               | 1317-36-8  |
|                                        | Diboron-trioxide                                            | 1303-86-2  |
|                                        | Bis(alpha,alpha-dimethylbenzyl) peroxide                    | 80-43-3    |
| Bombilla                               | Diboron-trioxide                                            | 1303-86-2  |
| Calefacción                            | Lead-titanium-trioxide                                      | 12060-00-3 |
|                                        | Lead-monoxide                                               | 1317-36-8  |
|                                        | Diboron-trioxide                                            | 1303-86-2  |
| Cámara                                 | Octamethylcyclotetrasiloxane                                | 556-67-2   |
|                                        | 2-Methylimidazole                                           | 693-98-1   |
|                                        | Decamethylcyclopentasiloxane                                | 541-02-6   |

|                                 |                                                                                                   |             |
|---------------------------------|---------------------------------------------------------------------------------------------------|-------------|
| Cámara                          | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5  |
|                                 | Lead-monoxide                                                                                     | 1317-36-8   |
|                                 | Diboron-trioxide                                                                                  | 1303-86-2   |
|                                 | Dodecamethylcyclotetrasiloxane                                                                    | 540-97-6    |
|                                 | Refractory ceramic fibres                                                                         | 142844-00-6 |
|                                 | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                                                   | 75980-60-8  |
| Cerradura De La Puerta          | Triphenyl-phosphate                                                                               | 115-86-6    |
| Chaleco Reflectante             | Diboron-trioxide                                                                                  | 1303-86-2   |
| Cilindro De Trabajo             | Imidazolidine-2-thione                                                                            | 96-45-7     |
|                                 | Lead-monoxide                                                                                     | 1317-36-8   |
| Compresor De Agente Frigorígeno | 4,4'-Isopropylidenediphenol                                                                       | 80-05-7     |
|                                 | 2-Methylimidazole                                                                                 | 693-98-1    |
|                                 | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                                          | 71868-10-5  |
|                                 | Lead-monoxide                                                                                     | 1317-36-8   |
|                                 | Diboron-trioxide                                                                                  | 1303-86-2   |
|                                 | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4  |
| Conmutador De Luces             | Lead-monoxide                                                                                     | 1317-36-8   |
| Convertidor De Tension          | Melamine                                                                                          | 108-78-1    |
| Convertidor Ethernet            | Lead-titanium-trioxide                                                                            | 12060-00-3  |
|                                 | Lead-monoxide                                                                                     | 1317-36-8   |
| Cubierta De La Caja De Enchufe  | Bumetrizole                                                                                       | 3896-11-5   |
| Diodo                           | TBBA                                                                                              | 79-94-7     |
| Disco De Cierre                 | Imidazolidine-2-thione                                                                            | 96-45-7     |
| Distribuidor De Energía         | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                                 | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                                 | Dodecamethylcyclotetrasiloxane                                                                    | 540-97-6    |
| Eje                             | Boric acid                                                                                        | 10043-35-3  |
|                                 | Imidazolidine-2-thione                                                                            | 96-45-7     |
|                                 | Octamethylcyclotetrasiloxane                                                                      | 556-67-2    |
|                                 | 2-Methylimidazole                                                                                 | 693-98-1    |
|                                 | Decamethylcyclopentasiloxane                                                                      | 541-02-6    |
|                                 | Lead-monoxide                                                                                     | 1317-36-8   |
|                                 | Diboron-trioxide                                                                                  | 1303-86-2   |
|                                 | Tris(nonylphenyl)phosphite                                                                        | 26523-78-4  |
|                                 | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione                                  | 2451-62-9   |
|                                 | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                      | 119-47-1    |
|                                 | Chromium-trioxide                                                                                 | 1333-82-0   |
|                                 | Hexahydromethylphthalic-anhydride                                                                 | 25550-51-0  |
|                                 | Paraffin oils, chloro                                                                             | 85422-92-0  |
|                                 | TBBA                                                                                              | 79-94-7     |
|                                 | Phenol, methylstyrenated                                                                          | 68512-30-1  |
|                                 | Triphenyl-phosphate                                                                               | 115-86-6    |
|                                 | O,O,O-Triphenyl phosphorothioate                                                                  | 597-82-0    |
| Eje Motriz                      | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene | 13560-89-9  |

|                                                  |                                                                                                                                              |             |
|--------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Eje Motriz</b>                                | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                                  | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                                  | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                  | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                                  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                                  | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                                  | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                                  | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
|                                                  | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
|                                                  | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
| <b>Enchufe Roscado</b>                           | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Espejo</b>                                    | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                                  | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Evaporador</b>                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Faro</b>                                      | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Fuelle De Suspensión</b>                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| <b>Guardabarros</b>                              | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Interruptor Basculante</b>                    | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| <b>Interruptor De Tecla</b>                      | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Interruptor En La Columna De La Dirección</b> | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
| <b>Juego De Cables Eléctricos</b>                | Melamine                                                                                                                                     | 108-78-1    |
|                                                  | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Juego De Llaves</b>                           | 1,2-Dimethoxyethane                                                                                                                          | 110-71-4    |
| <b>Junta</b>                                     | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Junta Tórica</b>                              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| <b>Lampara De Delimitacion</b>                   | TBBA                                                                                                                                         | 79-94-7     |
|                                                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Lampara Interior</b>                          | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Luz De Posición Trasera</b>                   | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                                  | TBBA                                                                                                                                         | 79-94-7     |
|                                                  | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                                                                                  | 3147-75-9   |
| <b>Luz De Techo</b>                              | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Modulador De Freno Del Eje</b>                | Lead-monoxide                                                                                                                                | 1317-36-8   |

|                                      |                                                                            |            |
|--------------------------------------|----------------------------------------------------------------------------|------------|
| Módulo De La Batería De Alto Voltaje | Lead-monoxide                                                              | 1317-36-8  |
|                                      | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3 |
| Motor Del Limpiaparabrisas           | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol                            | 25973-55-1 |
| Palanca De Mando                     | Lead-monoxide                                                              | 1317-36-8  |
|                                      | Diboron-trioxide                                                           | 1303-86-2  |
| Panel De Manejo                      | Lead-monoxide                                                              | 1317-36-8  |
|                                      | TBBA                                                                       | 79-94-7    |
| Pantalla                             | 2-Methylimidazole                                                          | 693-98-1   |
|                                      | Lead-monoxide                                                              | 1317-36-8  |
|                                      | Diboron-trioxide                                                           | 1303-86-2  |
| Pasacables De Goma                   | Imidazolidine-2-thione                                                     | 96-45-7    |
| Pedal Acelerador                     | Lead-monoxide                                                              | 1317-36-8  |
|                                      | TBBA                                                                       | 79-94-7    |
| Perfil Hermetizante                  | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Piloto De Control                    | TBBA                                                                       | 79-94-7    |
|                                      | Melamine                                                                   | 108-78-1   |
| Puerta                               | Triphenyl-phosphate                                                        | 115-86-6   |
| Puerta Lateral                       | Triphenyl-phosphate                                                        | 115-86-6   |
| Pulsador                             | Octamethylcyclotetrasiloxane                                               | 556-67-2   |
|                                      | Decamethylcyclopentasiloxane                                               | 541-02-6   |
|                                      | Lead-monoxide                                                              | 1317-36-8  |
|                                      | Dodecamethylcyclohexasiloxane                                              | 540-97-6   |
| Red Para Equipaje                    | N,N-Dimethylacetamide                                                      | 127-19-5   |
| Retrovisor Exterior                  | TBBA                                                                       | 79-94-7    |
|                                      | Triphenyl-phosphate                                                        | 115-86-6   |
| Sensor De Aceleración                | Diboron-trioxide                                                           | 1303-86-2  |
| Sensor De Presión                    | Lead titanium zirconium oxide                                              | 12626-81-2 |
|                                      | Lead-monoxide                                                              | 1317-36-8  |
|                                      | 1,2-Dimethoxyethane                                                        | 110-71-4   |
|                                      | 1,3-Propanesultone                                                         | 1120-71-4  |
| Sensor De Temperatura                | TBBA                                                                       | 79-94-7    |
| Tapa                                 | C,C'-azodi(formamide)                                                      | 123-77-3   |
| Tapa De Cierre Del Radiador          | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |
| Tapón De Cierre                      | Bumetrizole                                                                | 3896-11-5  |
| Tira De Filtro                       | Disodium-octaborate                                                        | 12008-41-2 |
| Torn.Hex.Int.Red.                    | Diboron-trioxide                                                           | 1303-86-2  |
| Tornillo Hexag.                      | Diboron-trioxide                                                           | 1303-86-2  |
| Transmisor De Valor De Freno         | Lead-monoxide                                                              | 1317-36-8  |
|                                      | Diboron-trioxide                                                           | 1303-86-2  |
| Tubo Flexible De Líquido De Frenos   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1   |
|                                      | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3    |

|                                                                   |                                                                 |             |
|-------------------------------------------------------------------|-----------------------------------------------------------------|-------------|
| <b>Uc Del Módulo Registro<br/>De Señales y Activación<br/>Fhs</b> | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                                   |                                                                 |             |
| <b>Uc Módulo De La Puerta<br/>Del Conductor</b>                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
| <b>Unidad Control Edrive<br/>Common Powertrain<br/>Controller</b> | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                                   | <b>TBBA</b>                                                     | 79-94-7     |
|                                                                   | <b>2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone</b>       | 119313-12-1 |
| <b>Unidad De Conexión<br/>Multimedia</b>                          | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
| <b>Unidad De Control<br/>Cerradura Electr.De<br/>Encendido</b>    | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <b>Unidad De Control<br/>Climatizador<br/>Automático Confort</b>  | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <b>Unidad De Control<br/>Control De Carga De La<br/>Batería</b>   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                                   | <b>TBBA</b>                                                     | 79-94-7     |
|                                                                   |                                                                 |             |
| <b>Unidad De Control<br/>Convertidor Cc/Cc Bajo<br/>Voltaje 1</b> | <b>N,N-Dimethylacetamide</b>                                    | 127-19-5    |
|                                                                   | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one</b> | 71868-10-5  |
|                                                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol</b>             | 119-47-1    |
|                                                                   | <b>Dodecamethylcyclohexasiloxane</b>                            | 540-97-6    |
|                                                                   | <b>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide</b>          | 75980-60-8  |
| <b>Unidad De Control De<br/>La Cámara Multifunción</b>            | <b>Lead-titanium-trioxide</b>                                   | 12060-00-3  |
|                                                                   | <b>Lead-monoxide</b>                                            | 1317-36-8   |
|                                                                   | <b>Diboron-trioxide</b>                                         | 1303-86-2   |
|                                                                   | <b>Pitch, coal tar, high-temp.</b>                              | 65996-93-2  |
| <b>Unidad De Control De<br/>La Presión De Los<br/>Neumáticos</b>  | <b>Lead-monoxide</b>                                            | 1317-36-8   |
| <b>Unidad De Control Del<br/>Airbag</b>                           | <b>Lead-monoxide</b>                                            | 1317-36-8   |

|                                                               |                                                                                                                                                                   |                                                               |
|---------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Airbag</b>                                                 | <b>Diboron-trioxide<br/>TBBA</b>                                                                                                                                  | 1303-86-2<br>79-94-7                                          |
| <b>Unidad De Control Del<br/>Sensor De Distancia</b>          | <b>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                                                                                     | 12060-00-3<br>1317-36-8<br>1303-86-2<br>79-94-7               |
| <b>Unidad De Control Del<br/>Variador</b>                     | <b>2-Methylimidazole<br/>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                             | 693-98-1<br>71868-10-5<br>1317-36-8<br>1303-86-2<br>79-94-7   |
| <b>Unidad De Control<br/>Display</b>                          | <b>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide<br/>1-Propanol, 2,3-dibromo-</b>    | 71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>96-13-9 |
| <b>Unidad De Control Eje<br/>Adicional Dirigido</b>           | <b>Lead-monoxide<br/>6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol<br/>Bis(alpha,alpha-dimethylbenzyl) peroxide</b>                                                | 1317-36-8<br>119-47-1<br>80-43-3                              |
| <b>Unidad De Control<br/>Gateway Central</b>                  | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Unidad De Control<br/>Gestión Del Cambio</b>               | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Unidad De Control<br/>Instrumento<br/>Combinado</b>        | <b>4,4'-Isopropylidenediphenol<br/>Lead-monoxide<br/>Diboron-trioxide<br/>TBBA</b>                                                                                | 80-05-7<br>1317-36-8<br>1303-86-2<br>79-94-7                  |
| <b>Unidad De Control<br/>Módulo De Puerta<br/>Acompañante</b> | <b>Lead-monoxide<br/>Diboron-trioxide</b>                                                                                                                         | 1317-36-8<br>1303-86-2                                        |
| <b>Unidad De Control<br/>Plataforma Telemática</b>            | <b>4,4'-Isopropylidenediphenol<br/>2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one<br/>Lead-titanium-trioxide<br/>Lead-monoxide<br/>Diboron-trioxide</b> | 80-05-7<br>71868-10-5<br>12060-00-3<br>1317-36-8<br>1303-86-2 |
| <b>Unidad De Control<br/>Radar De Corto Alcance</b>           | <b>Lead-monoxide</b>                                                                                                                                              | 1317-36-8                                                     |

|                                                         |                                                                                                                                                                        |                                                                              |
|---------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>Unidad De Control Regulación De Nivel</b>            | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Unidad De Control Sensor De Lluvia Y Luminosidad</b> | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Unidad De Control Sensor Del Ángulo De Viraje</b>    | Lead-monoxide<br>Diboron-trioxide                                                                                                                                      | 1317-36-8<br>1303-86-2                                                       |
| <b>Unidad De Control Sistema De Gestión De Batería</b>  | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Unidad De Control Tacógrafo</b>                      | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide<br>Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide<br>Triphenyl-phosphate | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2<br>75980-60-8<br>115-86-6 |
| <b>Unidad De Control Unidad De Tratamiento De Aire</b>  | Lead titanium zirconium oxide<br>Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                           | 12626-81-2<br>12060-00-3<br>1317-36-8<br>1303-86-2                           |
| <b>Unidad De Control Video Radar Decision Unit</b>      | Lead-titanium-trioxide<br>Lead-monoxide<br>Diboron-trioxide                                                                                                            | 12060-00-3<br>1317-36-8<br>1303-86-2                                         |
| <b>Unidad De Control XMC</b>                            | Lead-monoxide<br>Diboron-trioxide<br>4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride                                                                                | 1317-36-8<br>1303-86-2<br>19438-60-9                                         |
| <b>Unidad De Mando Válvula Electromagnética</b>         | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |
| <b>Ventanilla Ventilador</b>                            | Dodecamethylcyclohexasiloxane<br>Diboron-trioxide<br>TBBA<br>Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                  | 540-97-6<br>1303-86-2<br>79-94-7<br>80-43-3                                  |
| <b>Volante De Direccion</b>                             | Lead-monoxide                                                                                                                                                          | 1317-36-8                                                                    |

Kära kunder,

den 1 juni 2007 trädde lagstiftningen för EU:s kemikalieförordning (EG) nr. 1907/2006 (REACH – registrering, utvärdering, tillstånd och begränsningar av kemiska ämnen) i kraft, som syftar till att skydda människors hälsa och miljön från möjliga faror som uppstår vid användning av kemikalier.

Daimler Truck AG stödjer målen hos REACH. Artikel 33 i lagstiftningen föreskriver att du som kund ska informeras om särskilt farliga ämnen (SVHC) i våra produkter. Syftet med denna föreskrift är att säkerställa säker hantering av de definierade ämnena under produktens hela livscykel.

Utifrån de rättsliga föreskrifterna och information från Daimler Truck AG:s leverantörer, identifierades följande ämnen, som i enskilda produkter i detta fordon kan ha en viktprocent på mer än 0,1. Om fordonet används som avsett föreligger det ingen fara för människor eller miljön. Mer information om säker användning av ditt fordon hittar du i bruksanvisningen.

Observera att ämnet bly (CAS-nr 7439-92-1) dessutom finns i startbatteriet, i legeringar, ytbehandlingar, glas-/keramik-/elastkomponenter samt diverse elektroniska komponenter (framför allt lod).

| Produktgrupp            | Substance Name                                                   | CAS Nr.    |
|-------------------------|------------------------------------------------------------------|------------|
| Accelerationssensor     | Diboron-trioxide                                                 | 1303-86-2  |
| Antennförstärkare       | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Arbetscylinder          | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Lead-monoxide                                                    | 1317-36-8  |
| Axel                    | Boric acid                                                       | 10043-35-3 |
|                         | Imidazolidine-2-thione                                           | 96-45-7    |
|                         | Octamethylcyclotetrasiloxane                                     | 556-67-2   |
|                         | 2-Methylimidazole                                                | 693-98-1   |
|                         | Decamethylcyclopentasiloxane                                     | 541-02-6   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
|                         | Tris(nonylphenyl)phosphite                                       | 26523-78-4 |
|                         | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione | 2451-62-9  |
|                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Chromium-trioxide                                                | 1333-82-0  |
|                         | Hexahydromethylphthalic-anhydride                                | 25550-51-0 |
|                         | Paraffin oils, chloro                                            | 85422-92-0 |
|                         | TBBA                                                             | 79-94-7    |
|                         | Phenol, methylstyrenated                                         | 68512-30-1 |
|                         | Triphenyl-phosphate                                              | 115-86-6   |
|                         | O,O,O-Triphenyl phosphorothioate                                 | 597-82-0   |
| Axelmodulator           | Lead-monoxide                                                    | 1317-36-8  |
| Bagagenät               | N,N-Dimethylacetamide                                            | 127-19-5   |
| Baklykta                | Lead-monoxide                                                    | 1317-36-8  |
|                         | TBBA                                                             | 79-94-7    |
|                         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9  |
| Belysning i Förarhytten | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol      | 3147-75-9  |
| Bildskärm               | 2-Methylimidazole                                                | 693-98-1   |
|                         | Lead-monoxide                                                    | 1317-36-8  |
|                         | Diboron-trioxide                                                 | 1303-86-2  |
| Bromsslang              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                     | 119-47-1   |
|                         | Bis(alpha,alpha-dimethylbenzyl) peroxide                         | 80-43-3    |

|                                |                                                                                                                                              |             |
|--------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| <b>Bromsvärdessensor</b>       | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Däcktrycksantenn</b>        | Lead titanium zirconium oxide                                                                                                                | 12626-81-2  |
| <b>Diod</b>                    | TBBA                                                                                                                                         | 79-94-7     |
| <b>Dörr</b>                    | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Dörrlås</b>                 | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Drivaxel</b>                | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene                                            | 13560-89-9  |
|                                | N,N-Dimethylacetamide                                                                                                                        | 127-19-5    |
|                                | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                | 2-Methylimidazole                                                                                                                            | 693-98-1    |
|                                | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                | 4-Nonylphenol, branched                                                                                                                      | 84852-15-3  |
|                                | Nonylphenol                                                                                                                                  | 25154-52-3  |
|                                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
|                                | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
|                                | TBBA                                                                                                                                         | 79-94-7     |
|                                | Phosphorodithioic acid, mixed O,O-bis(2-ethylhexyl and iso-Bu and iso-Pr) S-[3a,4,5,6,7,7a-hexahydro-4,7-methano-1H-inden-5(or 6)-yl] esters | 255881-94-8 |
| <b>Elkabelsats</b>             | Phenol, methylstyrenated                                                                                                                     | 68512-30-1  |
|                                | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
|                                | Melamine                                                                                                                                     | 108-78-1    |
| <b>Eluttagsskydd</b>           | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
|                                | Bumetizole                                                                                                                                   | 3896-11-5   |
| <b>Energifördelare</b>         | Octamethylcyclotetrasiloxane                                                                                                                 | 556-67-2    |
|                                | Decamethylcyclopentasiloxane                                                                                                                 | 541-02-6    |
|                                | Dodecamethylcyclohexasiloxane                                                                                                                | 540-97-6    |
| <b>Ethernet-Omvandlare</b>     | Lead-titanium-trioxide                                                                                                                       | 12060-00-3  |
|                                | Lead-monoxide                                                                                                                                | 1317-36-8   |
| <b>Fällbart Extrasäte Fram</b> | C,C'-azodi(formamide)                                                                                                                        | 123-77-3    |
|                                | Melamine                                                                                                                                     | 108-78-1    |
|                                | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Filtremsa</b>               | Disodium-octaborate                                                                                                                          | 12008-41-2  |
| <b>Fjäderbälg</b>              | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                                                                                                 | 119-47-1    |
| <b>Fläkt</b>                   | TBBA                                                                                                                                         | 79-94-7     |
|                                | Bis(alpha,alpha-dimethylbenzyl) peroxide                                                                                                     | 80-43-3     |
| <b>Förångare</b>               | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
| <b>Förarsäte</b>               | 4,4'-Isopropylidenediphenol                                                                                                                  | 80-05-7     |
|                                | Triphenyl-phosphate                                                                                                                          | 115-86-6    |
| <b>Fordonsbatteri</b>          | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                | Diboron-trioxide                                                                                                                             | 1303-86-2   |
|                                | Lead(II,IV)-oxide                                                                                                                            | 1314-41-6   |
| <b>Gaspedal</b>                | Lead-monoxide                                                                                                                                | 1317-36-8   |
|                                | TBBA                                                                                                                                         | 79-94-7     |
| <b>Genomföringshylsa</b>       | Imidazolidine-2-thione                                                                                                                       | 96-45-7     |

|                      |                                                                            |             |
|----------------------|----------------------------------------------------------------------------|-------------|
| Glödlampa            | Diboron-trioxide                                                           | 1303-86-2   |
| Högvoltsbatterimodul | Lead-monoxide                                                              | 1317-36-8   |
| Inskruvningsstuts    | 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) | 29420-49-3  |
| Kamera               | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
|                      | Octamethylcyclotetrasiloxane                                               | 556-67-2    |
|                      | 2-Methylimidazole                                                          | 693-98-1    |
|                      | Decamethylcyclopentasiloxane                                               | 541-02-6    |
|                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                      | Lead-monoxide                                                              | 1317-36-8   |
|                      | Diboron-trioxide                                                           | 1303-86-2   |
|                      | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
|                      | Refractory ceramic fibres                                                  | 142844-00-6 |
|                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide                            | 75980-60-8  |
| Klimatanläggning     | Lead-monoxide                                                              | 1317-36-8   |
| Knappströmställare   | Lead-monoxide                                                              | 1317-36-8   |
|                      | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Kontrollampa         | TBBA                                                                       | 79-94-7     |
|                      | Melamine                                                                   | 108-78-1    |
| Kontrolldon          | Lead-monoxide                                                              | 1317-36-8   |
|                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
| Kontrollpanel        | Lead-monoxide                                                              | 1317-36-8   |
|                      | TBBA                                                                       | 79-94-7     |
| Kylarlock            | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Kylkompressor        | 4,4'-Isopropylidenediphenol                                                | 80-05-7     |
|                      | 2-Methylimidazole                                                          | 693-98-1    |
|                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one                   | 71868-10-5  |
|                      | Lead-monoxide                                                              | 1317-36-8   |
|                      | Diboron-trioxide                                                           | 1303-86-2   |
|                      | Tris(nonylphenyl)phosphite                                                 | 26523-78-4  |
| Kylvätskepump        | Lead-monoxide                                                              | 1317-36-8   |
|                      | Diboron-trioxide                                                           | 1303-86-2   |
|                      | Bis(alpha,alpha-dimethylbenzyl) peroxide                                   | 80-43-3     |
| Låsbricka            | Imidazolidine-2-thione                                                     | 96-45-7     |
| Ljusomkopplare       | Lead-monoxide                                                              | 1317-36-8   |
| Lucka                | C,C'-azodi(formamide)                                                      | 123-77-3    |
| Luftfjädrad Stol     | Triphenyl-phosphate                                                        | 115-86-6    |
| Magnetventil         | Dodecamethylcyclohexasiloxane                                              | 540-97-6    |
| Manöverspak          | Lead-monoxide                                                              | 1317-36-8   |
|                      | Diboron-trioxide                                                           | 1303-86-2   |
| Markeringslykta      | TBBA                                                                       | 79-94-7     |
|                      | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol                | 3147-75-9   |
| Nyckelsats           | 1,2-Dimethoxyethane                                                        | 110-71-4    |
| O-Ring               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                               | 119-47-1    |
| Panel För            |                                                                            |             |
| Multimediauttag      | Lead-monoxide                                                              | 1317-36-8   |
|                      | Diboron-trioxide                                                           | 1303-86-2   |
| Plugg                | Bumetrizole                                                                | 3896-11-5   |
| Profiltätning        | C,C'-azodi(formamide)                                                      | 123-77-3    |
| Ratt                 | Lead-monoxide                                                              | 1317-36-8   |
| Rattstångskontakt    | Lead-monoxide                                                              | 1317-36-8   |

|                                                      |                                                             |             |
|------------------------------------------------------|-------------------------------------------------------------|-------------|
| <b>Rattstängskontakt</b>                             | TBBA                                                        | 79-94-7     |
| <b>Sexkantskruv</b>                                  | Diboron-trioxide                                            | 1303-86-2   |
| <b>Sextandskruv</b>                                  | Diboron-trioxide                                            | 1303-86-2   |
| <b>Sidodörr</b>                                      | Triphenyl-phosphate                                         | 115-86-6    |
| <b>Sidoruta</b>                                      | Diboron-trioxide                                            | 1303-86-2   |
| <b>Spännings-omvandlare</b>                          | Melamine                                                    | 108-78-1    |
| <b>Spegel</b>                                        | 2-Methylimidazole                                           | 693-98-1    |
|                                                      | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
| <b>Spegel Utv</b>                                    | TBBA                                                        | 79-94-7     |
|                                                      | Triphenyl-phosphate                                         | 115-86-6    |
| <b>Stänkskärm</b>                                    | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol | 3147-75-9   |
| <b>Strålkastare</b>                                  | Lead-monoxide                                               | 1317-36-8   |
| <b>Styrenhet</b>                                     |                                                             |             |
| <b>Avståndssensor</b>                                | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                      | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
|                                                      | TBBA                                                        | 79-94-7     |
| <b>Styrenhet Batteri-styrningssystem</b>             | Lead-monoxide                                               | 1317-36-8   |
| <b>Styrenhet Central Gateway</b>                     | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
| <b>Styrenhet Däcktryckskontroll</b>                  | Lead-monoxide                                               | 1317-36-8   |
| <b>Styrenhet Dc/Dc-Omvandlare Lågvolt 1</b>          | N,N-Dimethylacetamide                                       | 127-19-5    |
|                                                      | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                                      | Lead-monoxide                                               | 1317-36-8   |
|                                                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol                | 119-47-1    |
|                                                      | Dodecamethylcyclohexasiloxane                               | 540-97-6    |
|                                                      | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide             | 75980-60-8  |
| <b>Styrenhet Display</b>                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one    | 71868-10-5  |
|                                                      | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                      | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
|                                                      | 1-Propanol, 2,3-dibromo-                                    | 96-13-9     |
| <b>Styrenhet Dörrmodul Förare</b>                    | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
| <b>Styrenhet Dörrmodul Passageraren Fram</b>         | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
| <b>Styrenhet Edrive Common Powertrain Controller</b> | Lead-titanium-trioxide                                      | 12060-00-3  |
|                                                      | Lead-monoxide                                               | 1317-36-8   |
|                                                      | Diboron-trioxide                                            | 1303-86-2   |
|                                                      | TBBA                                                        | 79-94-7     |
|                                                      | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone          | 119313-12-1 |

|                                                        |                                                          |            |
|--------------------------------------------------------|----------------------------------------------------------|------------|
| <b>Styrenhet Elektroniskt<br/>Tändningslås</b>         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
| <b>Styrenhet Färdskrivare</b>                          | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                        | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
|                                                        | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide          | 75980-60-8 |
|                                                        | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Styrenhet<br/>Klimatautomatik</b>                   | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
| <b>Styrenhet<br/>Kombiinstrument</b>                   | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
|                                                        | TBBA                                                     | 79-94-7    |
| <b>Styrenhet Krockkudde</b>                            | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
|                                                        | TBBA                                                     | 79-94-7    |
| <b>Styrenhet<br/>Laddstyrssystem</b>                   | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
|                                                        | TBBA                                                     | 79-94-7    |
| <b>Styrenhet Luft-<br/>behandlingsenhet</b>            | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                                        | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styrenhet Multi-<br/>funktionskamera</b>            | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
|                                                        | Pitch, coal tar, high-temp.                              | 65996-93-2 |
| <b>Styrenhet Närradar</b>                              | Lead-monoxide                                            | 1317-36-8  |
| <b>Styrenhet Nivåreglering</b>                         | Lead-monoxide                                            | 1317-36-8  |
| <b>Styrenhet Omriktare</b>                             | 2-Methylimidazole                                        | 693-98-1   |
|                                                        | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |
|                                                        | TBBA                                                     | 79-94-7    |
| <b>Styrenhet Regn-<br/>/Ljussensor</b>                 | Lead-monoxide                                            | 1317-36-8  |
| <b>Styrenhet Signalreg.-<br/>och Akt.Modul Förarh.</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                                        | Lead-monoxide                                            | 1317-36-8  |
|                                                        | Diboron-trioxide                                         | 1303-86-2  |

|                                            |                                                          |            |
|--------------------------------------------|----------------------------------------------------------|------------|
| <b>Styrenhet Styrd Extraaxel</b>           | Lead-monoxide                                            | 1317-36-8  |
|                                            | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol             | 119-47-1   |
|                                            | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Styrenhet Styrvinkelsensor</b>          | Lead-monoxide                                            | 1317-36-8  |
|                                            | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styrenhet Telematikplattform</b>        | 4,4'-Isopropylidenediphenol                              | 80-05-7    |
|                                            | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one | 71868-10-5 |
|                                            | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                            | Lead-monoxide                                            | 1317-36-8  |
|                                            | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styrenhet Växellådsstyrssystem</b>      | Lead-monoxide                                            | 1317-36-8  |
|                                            | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styrenhet Video Radar Decision Unit</b> | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                            | Lead-monoxide                                            | 1317-36-8  |
|                                            | Diboron-trioxide                                         | 1303-86-2  |
| <b>Styrenhet XMC</b>                       | Lead-monoxide                                            | 1317-36-8  |
|                                            | Diboron-trioxide                                         | 1303-86-2  |
|                                            | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride       | 19438-60-9 |
| <b>Taklampa</b>                            | Triphenyl-phosphate                                      | 115-86-6   |
| <b>Tätning</b>                             | Bis(alpha,alpha-dimethylbenzyl) peroxide                 | 80-43-3    |
| <b>Temperatursensor</b>                    | TBBA                                                     | 79-94-7    |
| <b>Torkarmotor</b>                         | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol          | 25973-55-1 |
| <b>Tryckbrytare</b>                        | Octamethylcyclotetrasiloxane                             | 556-67-2   |
|                                            | Decamethylcyclopentasiloxane                             | 541-02-6   |
|                                            | Lead-monoxide                                            | 1317-36-8  |
|                                            | Dodecamethylcyclohexasiloxane                            | 540-97-6   |
| <b>Trycksensor</b>                         | Lead titanium zirconium oxide                            | 12626-81-2 |
|                                            | Lead-monoxide                                            | 1317-36-8  |
|                                            | 1,2-Dimethoxyethane                                      | 110-71-4   |
|                                            | 1,3-Propanesultone                                       | 1120-71-4  |
| <b>Värmesystem</b>                         | Lead-titanium-trioxide                                   | 12060-00-3 |
|                                            | Lead-monoxide                                            | 1317-36-8  |
|                                            | Diboron-trioxide                                         | 1303-86-2  |
| <b>Varningsväst</b>                        | Diboron-trioxide                                         | 1303-86-2  |
| <b>Vippknapp</b>                           | Lead-monoxide                                            | 1317-36-8  |
|                                            | TBBA                                                     | 79-94-7    |